

Asbestos Hazard Emergency Response Act Three-Year Asbestos Re-Inspection and Management Plan Update

for
Facilities Administration Building

For Compliance with
Connecticut of Connecticut Department of Public Health
Asbestos-Containing Material in Schools Regulation
(Sections 19a - 333-1 through 19a - 333-13)
and
EPA Asbestos Hazard Emergency Response Act
(Title 40 CFR, Part 763, Subpart E)

New Milford Public Schools
New Milford, Connecticut

January 2017



Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040



May 4, 2017

Mr. Kevin Munrett
Facilities Manager
New Milford Public Schools
386 Danbury Road
New Milford, CT 06776

RE: Three-Year AHERA Asbestos Re-Inspection and Management Plan Update
Re-Inspection Date: January 23, 2017
Facilities Administration Building
386 Danbury Road, New Milford, CT
Fuss & O'Neill EnviroScience Project No. 20071230.A6E

Dear Mr. Munrett:

Enclosed is the three-year AHERA Asbestos Re-Inspection and Management Plan Update report prepared by Fuss & O'Neill EnviroScience, LLC for the Facilities Administration Building located at 386 Danbury Road in New Milford, Connecticut (the "Site"). The inspection was performed for New Milford Public Schools (the "Client"). This report is an important document that must be kept on file at the school as well as at a central location where the Management Plans are maintained.

If you should have any questions regarding this report, please do not hesitate to contact me. Thank you for this opportunity to have served your environmental needs.

Sincerely,

A handwritten signature in black ink, appearing to read 'JDS'. Below the signature, the name 'Jared D. Smith, CSP' is printed in a standard black font.

Jared D. Smith, CSP
Project Manager

JDS/kr

146 Hartford Road
Manchester, CT
06040
t 860.646.2469
800.286.2469
f 860.533.5143

www.fando.com

Enclosure

Connecticut
Massachusetts
Rhode Island
South Carolina

Table of Contents

Asbestos Hazard Emergency Response Act Three-Year Re-Inspection and Management Plan Update Facilities Administration Building

| | | |
|----------|---|-----------|
| 1 | Introduction | 1 |
| 1.1 | Background | 1 |
| 1.2 | Local Education Agency (LEA) Responsibilities | 1 |
| 1.3 | Accreditation | 2 |
| 2 | Building and Mechanical System Description | 3 |
| 3 | Three Year Re-Inspection..... | 3 |
| 3.1 | Re-Inspection Procedures..... | 3 |
| 4 | Re-Inspection Report..... | 4 |
| 4.1 | Review of Existing Records | 4 |
| 4.2 | Re-Inspection Summary..... | 4 |
| 4.3 | Newly Identified or Re-sampled ACBM Materials..... | 6 |
| 4.4 | Physical Assessment of ACBM | 7 |
| 5 | Management Plan Update | 8 |
| 5.1 | Recommended Response Actions..... | 8 |
| 5.2 | Periodic Surveillance | 9 |
| 5.3 | Preventive Measures..... | 9 |
| 5.4 | Abatement (Removal) Cost Estimates | 10 |
| 6 | EPA Accreditation Requirements | 10 |

Appendices

End of Report

| | |
|------------|--|
| APPENDIX A | EXISTING RECORDS CHECKLIST |
| APPENDIX B | RE-INSPECTION FORM 1A |
| APPENDIX C | RE-INSPECTION FORM 1B |
| APPENDIX D | RE-INSPECTION FORM 2 |
| APPENDIX E | SAMPLE 6-MONTH PERIODIC SURVEILLANCE FORM |
| APPENDIX F | PREVENTIVE MEASURES |
| APPENDIX G | ASBESTOS INSPECTOR AND MANAGEMENT PLANNER CONNECTICUT LICENSES AND EPA ACCREDITATIONS |

1 Introduction

1.1 Background

The Clean Air Act required the United States Environmental Protection Agency (EPA) to develop standards to address the potential health risks associated with adverse effects of asbestos exposure as an indoor contaminant. In October 1986, the EPA promulgated the Asbestos Hazard Emergency Response Act (AHERA) located at Title 40 CFR, Part 763, Subpart E.

The AHERA regulations required that local education agencies (LEAs) conduct inspections of each school building that they lease, own, or otherwise use as a school building to identify friable (easily crumbled or crushed to powder by hand pressure) and non-friable asbestos-containing building materials (ACBM) locations. The original inspections were required to have been completed prior to October 12, 1988.

AHERA also requires that any building leased or acquired on or after October 12, 1998 that is to be used as a school building shall be inspected for friable and non-friable ACBM prior to use as a school building. In the event of an emergency use of a building that has not been inspected for ACBM, the building shall be inspected within 30 days after commencement of such use.

The regulatory requirements remain in effect for private or public school systems, a church-affiliated school of any denomination, a school dedicated to the education of children with special needs, or a charter school. In the Connecticut of Connecticut, the Department of Public Health (CTDPH) is responsible for AHERA regulation enforcement.

1.2 Local Education Agency (LEA) Responsibilities

- A. The LEA is responsible for compliance with the AHERA regulation. The following responsibilities must be followed:
 1. The LEA must designate a person to ensure that all of the AHERA requirements are properly implemented. The Designated Person must receive adequate training to perform their duties.
 2. The LEA must ensure that management plans are maintained in a central location, as well as at each facility, and such plans and records are available for inspection or review at all times.
 3. The LEA must inform all workers, building occupants or their legal representative in writing at least once per school year about asbestos-related activities, and the availability of the AHERA management plans for the school buildings.
 4. The LEA must ensure proper accreditation for all persons who perform asbestos inspections, asbestos Re-Inspections, develop/update management plans, develop response

actions, and perform required response actions including operations and maintenance (O&M) activities that may disturb asbestos.

5. The LEA must provide training for all custodial and maintenance staff who regularly perform building maintenance where ACBM are present. The training must be provided upon initial hire, as well as annual updates.
6. The LEA must provide information (disclosure) to any workers who may perform work and may come into contact with asbestos in school buildings where ACBM or presumed ACBM are present.
7. The LEA must ensure that known ACBM or presumed ACBM are provided with warning labels in routine maintenance areas.
8. The LEA must ensure that periodic surveillance is performed at least once every six months, after management plan implementation, in all school buildings that it leases, owns, or otherwise uses that contains ACBM or presumed ACBM.
9. The LEA must ensure that once every three years, after a management plan is implemented, a Re-Inspection is performed at each school building that it leases owns or otherwise uses that contains ACBM or presumed ACBM.

Refer to above-mentioned regulation for full requirements and responsibilities.

1.3 Accreditation

A. Local Education Agency (LEA):

| | |
|----------|----------------------------|
| LEA: | New Milford Public Schools |
| Address: | 50 East Street |
| | New Milford, Connecticut |
| Phone: | (860) 355-8406 |
| Fax: | (860) 210-4132 |

B. Designated Person:

| | |
|--------------------|--------------------------|
| Designated Person: | Mr. Kevin Munrett |
| Address: | 386 Danbury Road |
| | New Milford, Connecticut |
| Phone: | (860) 354-6265 |
| Fax: | (860) 210-2233 |

C. Asbestos Consultant:

Firm: Fuss & O'Neill EnviroScience, LLC
Address: 146 Hartford Road
Manchester, Connecticut
Phone: (860) 646-2469
Fax: (860) 649-6883

D. Asbestos Inspector:

Inspector: John Robert Hobbins
CTDPH License #: 000700
Expiration Date: January 31, 2017

E. Asbestos Management Planner:

Planner: Jared Smith
CTDPH License #: 000309
Expiration: October 31, 2017

2 Building and Mechanical System Description

The Facility Administration Building is a two-story house with a basement reportedly constructed approximately sixty years ago and encompasses approximately 3,500 square feet. The structure is wood-framed with hardwood floors throughout the first and second floors. An attic is located above the second floor, with a chimney passing through the attic. The basement has concrete floors while the foundation is constructed of stone. The house is heated with an oil-fired forced air furnace. The window systems are wood framed. Walls throughout the building are plaster, with the exception of the basement walls.

3 Three Year Re-Inspection

3.1 Re-Inspection Procedures

This three-year asbestos re-inspection was conducted in accordance with EPA requirements of the AHERA regulation, Title 40 CFR, Part 763, Section 763.85 (b).

On January 23, 2016, Fuss & O'Neill EnviroScience, LLC (EnviroScience) representatives Mr. John Robert Hobbins performed the re-inspection.

A. During the re-inspection, EnviroScience conducted the following required tasks:

1. A visual re-inspection and reassessment of all known friable or assumed ACBM.

2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has become friable.
3. Identification and assessment of any newly-identified homogeneous area that contains friable ACBM since the last inspection or re-inspection.

4 Re-Inspection Report

4.1 Review of Existing Records

An important part of this AHERA re-inspection involved researching prior documentation that is required to be present at the school, as well as at the central recordkeeping location where management plans are stored.

Please see *Appendix A* for the checklist for existing records.

4.2 Re-Inspection Summary

The on-site portion of the re-inspection was documented on forms modeled after examples provided by the EPA and reviewed with the CTDPH. The first form, **Re-Inspection Form 1A**, identifies previous inspection data gathered during the initial AHERA inspection and subsequent re-inspection (see *Appendix B*). This form is useful to reference response actions (if any), which have been performed since the last inspection, as well as identifies the last known conditions of ACBM in the building. It additionally provides the inspector a “quick glance” reference when performing the re-inspection.

The second EPA form, **Re-Inspection Form 1B**, is used to list all known or assumed asbestos-containing materials that were previously unidentified (See *Appendix C*). It also lists the ACBM in areas newly-acquired by the school for student use either permanently or temporarily.

The third EPA form, **Re-Inspection Form 2**, was used to provide information and justification regarding re-assessment of the ACBM (see *Appendix D*). This form also provides response action recommendations, including a tentative schedule for completing response actions that recommend removal or repair.

No bulk samples were collected during this re-inspection.

Using EPA protocol and criteria, the following materials existing in Facilities Administration Building at the time of this three-year re-inspection have been determined and/or assumed to be **ACBM**. Please refer to the above-mentioned Re-Inspection Forms for specific locations of the materials.

Table 1
Asbestos-Containing Building Materials

| Material | Location | Reference | Asbestos Content |
|---|--|---|-------------------------|
| White Pipe Insulation | Basement | EnviroScience 2000 Asbestos Management Plan | 65% of Chrysotile |
| White Pipe Fitting Insulation | Basement | EnviroScience 2000 Asbestos Management Plan | 65% of Chrysotile |
| White 1' x 1' Ceiling Tiles | Second Floor Secretary's Office | EnviroScience 2000 Asbestos Management Plan | Assumed |
| 1' x 1' Ceiling Tiles Glue Daubs | Second Floor Secretary's Office | EnviroScience 2000 Asbestos Management Plan | Assumed |
| Silver Duct Insulation | Attic | EnviroScience 2017 AHERA Inspection | Assumed |
| Tan/Black Batt Wrapping Insulation | Attic | EnviroScience 2017 AHERA Inspection | Assumed |
| Black Sheet Paper underneath two Layers of Flooring | Kitchen | EnviroScience 2017 AHERA Inspection | Assumed |
| Yellow Ceramic Wall Tile | Bathrooms | EnviroScience 2017 AHERA Inspection | Assumed |
| Gray Ceramic Wall Tile Grout | Bathrooms | EnviroScience 2017 AHERA Inspection | Assumed |
| Gray Ceramic Wall Tile Adhesive | Bathrooms | EnviroScience 2017 AHERA Inspection | Assumed |
| Red Wall Paper | 1 st Floor Bathroom, Room 1 | EnviroScience 2017 AHERA Inspection | Assumed |
| White/Blue Wall Paper | Facilities Manager, Maintenance Assistant offices | EnviroScience 2017 AHERA Inspection | Assumed |
| Yellow Wall Paper | Storage | EnviroScience 2017 AHERA Inspection | Assumed |
| Gray Plaster Base Coat | Throughout Walls, Ceiling and Chimney at the Attic | EnviroScience 2017 AHERA Inspection | Assumed |
| White Plaster Skim Coat | Throughout Walls, Ceiling and Chimney at the Attic | EnviroScience 2017 AHERA Inspection | Assumed |
| White Textured Skim Coat | Room 2-3, Stairwells | EnviroScience 2017 AHERA Inspection | Assumed |
| White Gypsum Board Wall | Rear foyer, Bathrooms, Room 1, 2-2, 2-3, 2-4 | EnviroScience 2017 AHERA Inspection | Assumed |
| White Gypsum Board Joint Compound | Rear foyer, Bathrooms, Room 1, 2-2, 2-3, 2-4 | EnviroScience 2017 AHERA Inspection | Assumed |

| Material | Location | Reference | Asbestos Content |
|--|------------------------------|-------------------------------------|------------------|
| White Laminated Wall Panel | Kitchen | EnviroScience 2017 AHERA Inspection | Assumed |
| Wall Panel Glue associated with White Wall Panel | Kitchen | EnviroScience 2017 AHERA Inspection | Assumed |
| Black Laminated Counter Top | Kitchen | EnviroScience 2017 AHERA Inspection | Assumed |
| White 2" x 2" Ceiling Tiles | Maintenance Assistant office | EnviroScience 2017 AHERA Inspection | Assumed |

Using the EPA protocol, samples of the following suspect materials were collected and analyzed. The analytical results indicated that these materials are **non-ACBM**:

Table 2
Non-Asbestos-Containing Building Materials (Previous Re-Inspections)

| Material | Location | Reference |
|--|--|---|
| Chimney Flue Cement | Basement | EnviroScience Original Management Plan 2000 |
| Window Glazing Compounds | Basement | EnviroScience Original Management Plan 2000 |
| 12x12 Floor Tile | First Floor Kitchen | EnviroScience Original Management Plan 2000 |
| Middle Layer of Linoleum Sheet Flooring | First Floor Kitchen | EnviroScience Original Management Plan 2000 |
| Bottom Layer of Linoleum Sheet Flooring | First Floor Kitchen | EnviroScience Original Management Plan 2000 |
| Linoleum Sheet Flooring | First Floor Bathroom | EnviroScience Original Management Plan 2000 |
| Skim and Rough Coat Wall and Ceiling Plaster | Throughout First and Second Floors of Building | EnviroScience Original Management Plan 2000 |

Mr. Jared Smith reviewed the information obtained during this Re-Inspection. Mr. Jared Smith is an EPA-accredited and CTDPH licensed Asbestos Management Planner.

4.3 Newly Identified or Re-sampled ACBM Materials

The following newly identified suspect ACBM have been identified in the building:

- White Pipe Insulation
- White 1' x 1' Ceiling Tiles
- Silver Duct Insulation
- White Pipe Fitting Insulation
- 1' x 1' Ceiling Tiles Glue Daubs
- Tan/Black Batt Wrapping Insulation

- Black Sheet Paper underneath two Layers of Flooring
- Gray Grout associated with Yellow Ceramic Wall Tile
- Red Wall Paper
- Yellow Wall Paper
- White Plaster Skim Coat
- White Gypsum Board Wall
- White Laminated Wall Panel
- Black Laminated Counter Top
- Yellow Ceramic Wall Tile
- Adhesive associated with Yellow Ceramic Wall Tile
- White/Blue Wall Paper
- Gray Plaster Base Coat
- White Textured Skim Coat
- White Gypsum Board Joint Compound
- Laminated Wall Panel Glue
- White 2" x 2" Ceiling Tiles

These materials must be assumed to contain asbestos until laboratory analysis determine otherwise. These materials have been added to Table 1 as assumed ACBM.

AHERA regulations pertain to interior identified or assumed ACBM and limited exterior ACBM. AHERA regulations do include ACBM located on exterior porticos, covered walkways, and mechanical equipment used to condition interior building air.

Any suspect material encountered during renovation/demolition/maintenance activities that is not specifically identified in the Asbestos Management Plan (AMP) as a non-ACM should be assumed to contain asbestos unless sample results indicate otherwise.

Additional Information:

- ACBM floor tile and associated mastics may exist below non-moveable objects such as cabinets, platforms, sheetrock walls, lockers, etc.;
- Samples of exterior building materials not covered under AHERA, such as caulking and glazing compounds, roofing materials and materials behind exterior walls and panels should be collected and analyzed to determine asbestos content prior to performing activities that would disturb them;
- Asbestos-containing vapor barriers and waterproofing materials may exist beneath wood floors, behind walls, exterior below ground surface foundations, etc.; and
- Subsurface cementitious pipe (i.e., asbestos cement pipe).

4.4 Physical Assessment of ACBM

During inspection, suspect ACBM were separated into three EPA categories. These categories are thermal system insulation (TSI), surfacing ACBM, and miscellaneous ACBM. TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe and fitting insulations, boiler insulation, and duct insulation. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACBM not listed in TSI or surfacing, such as sheet flooring, vinyl asbestos flooring, ceiling tiles, and construction mastics/adhesives.

Finally, ACBM were quantified in linear and/or square feet, depending on the nature of the material.

The ACBM identified during the inspection and still remaining in the school were re-assessed using the CTDPH and AHERA guidelines for assessment of ACBM. The following assessment categories are listed:

- 1 Damaged or significantly damaged TSI ACBM
- 2 Damaged friable surfacing ACBM
- 3 Significantly damaged friable surfacing ACBM
- 4 Damaged or significantly damaged friable miscellaneous ACBM
- 5 ACBM with potential for damage
- 6 ACBM with potential for significant damage
- 7 Any remaining friable ACBM or friable suspected ACBM

Material locations, assessments, and recommended response actions are listed in the Re-Inspection forms.

5 Management Plan Update

5.1 Recommended Response Actions

Based on the inspection report, physical walk-through inspection, and existing ACBM conditions, the following response actions are recommended:

1. Removal - Not Applicable
2. Repair – Approximately 8 LF of white pipe insulation is damaged at the basement.
3. Enclosure - Not Applicable
4. Encapsulation - Not Applicable
5. Operations and Maintenance (O & M) - All remaining ACBM.

It should be noted that only ACBM with assessments of 1 or 2 are recommended for removal or repair. The remaining ACBM should be included in the O & M Program. The condition of these ACBM will be monitored until all of the ACBM have been completely removed from the building. A successful O & M Program includes the following elements:

- A. Cleaning: All areas of the school where friable ACBM or assumed friable ACBM are present should be cleaned at least once after completion of the initial inspection. Additional cleaning may be necessary if the Management Planner makes a written recommendation indicating the methods and frequency of such cleaning.
- B. O & M Activities: The LEA shall ensure that the procedures described below are followed to protect building occupants from O & M activities that may disturb known or assumed ACBM:
 1. Restrict entry into the area either by physically isolating or by scheduling.

2. Post asbestos warning signs to prevent entry by unauthorized persons.
 3. Deactivate or temporarily shut off or divert the air-handling system to the area.
 4. Use proper work practices and engineering controls, such as wet methods, protective clothing, High Efficiency Particulate Air (HEPA) vacuums, mini-enclosures/glove bags, etc. to inhibit fiber migration.
 5. Place asbestos debris and other contaminated materials into a sealed, leak-tight container for disposal.
- C. **Minor Fiber Release Episode:** The LEA shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., disturbance of less than or equal to 3 linear/square feet of friable ACBM):
1. Saturate the debris using wet method.
 2. Place the debris in a sealed, leak-tight container and clean the area.
 3. Repair the area of damaged ACBM with materials such as asbestos-free spackling, plaster or insulation or seal with an encapsulant.
- D. **Major Fiber Release Episode:** The LEA shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., disturbance of greater than 3 linear/square feet of friable ACBM):
1. Restrict entry into the area and post asbestos warning signs.
 2. Deactivate or temporarily shut off or divert the air handling system from the area to prevent fiber migration.
 3. The response action for any major fiber release episode must be prepared by EPA-accredited Asbestos Project Designers and conducted by EPA-accredited personnel.
 4. The LEA shall notify the CTDPH of any major fiber release episode within twenty-four hours of its occurrence and, if necessary, provide written notification as required by applicable federal and/or Connecticut regulations.

5.2 Periodic Surveillance

At least once every six months after an AMP is implemented, the LEA will conduct periodic surveillance in the school that contains ACBM or assumed ACBM. The person conducting periodic surveillance will visually inspect all areas in the school that where ACBM have been identified in the AMP, record the date of surveillance, their name, any changes in the ACBM condition and submit the record to the LEA Designated Person for inclusion in the AMP.

Please see *Appendix E* for the sample Periodic Surveillance Form that may be used for conducting periodic surveillance.

5.3 Preventive Measures

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that ACBM will become damaged, deteriorated, or delaminated.

Please see *Appendix F* for preventive measures designed for various types of ACBM that may exist in the school.

5.4 Abatement (Removal) Cost Estimates

Costs for abatement (removal) of damaged ACBM identified as recommended response actions are as follows:

Table 4
Abatement Cost Estimates

| Material | Location | Quantity | Estimated Contractor Cost |
|---|----------|----------------------------|---------------------------|
| White Pipe Insulation/White Pipe Fitting Insulation | Basement | 8 LF Damaged (30 LF Total) | ~\$5,000 |

6 EPA Accreditation Requirements

The EPA accreditations and the CTDPH Asbestos Inspector licenses for John Robert Hobbins and Jared Smith are provided in *Appendix G*.

Report prepared by Environmental Technician II Sandra Guzman

Reviewed by:



Jared D. Smith, CSP
Project Manager



Robert L. May, Jr.
President

Appendix A

Existing Records Checklist

Existing Records Checklist

Local Education Agency (LEA): New Milford Public Schools
50 East Street
New Milford, Connecticut, 06776

School Building: Facilities Administration Building

The following documentation is required to be present in both the LEA's office, as well as in a centralized location in the school administrative office. The information included in this checklist will be verified to be present and complete as part of three-year Re-Inspection.

| DOCUMENTATION | | LOCATION | |
|---------------|---|----------|------------|
| | | School | LEA Office |
| 1 | Original AHERA Operations and Maintenance Plan/Inspection Report | Yes | Yes |
| 2 | Three Year Re-Inspection (First and All Subsequent Inspections) | No | No |
| 3 | Parents and Teachers Notifications (Annually Since Last Re-Inspection) | No | No |
| 4 | Designated Person Identification and Proper Training (Person Must Be Named and Have Appropriate Training) | No | No |
| 5 | Designated Person Periodic Surveillance (Once Every Six Months) | No | No |
| 6 | Maintenance Staff Awareness Training Records | No | No |
| 7 | Outside Vendor Awareness Notification | No | No |
| 8 | Asbestos Warning Signs and Labels (Required Posting in Boiler Rooms and Mechanical Spaces Only) | No | No |
| 9 | Response Action Records (Includes Any Abatement Conducted Since Last 3-Year Re-Inspection) | No | No |

Comments: Items marked "No" indicate not present/available at the time of this inspection.

Inspector (LEA Office): Scott Mossey Date: January 9, 2017

Inspector (School): John Robert Hobbins Date: January 23, 2017

Appendix B

Re-Inspection Form 1A



Re-Inspection Form 1 (A) – List of Identified ACBM

Page 1 of 1

School: New Milford Public Schools
Address: 386 Danbury Road, New Milford, CT

Building: Facilities Administration
Date(s) of Original Inspection: 2000
Date(s) of Subsequent Re-Inspections: 2008, 2009, 2010, 2017

| Homogeneous Material | | | Material Category | Assessment Category (1-7) | Recorded Locations | Response Actions Taken/Renovations/Other Comments |
|----------------------|------------------|----------------------------------|-------------------|---------------------------|--------------------|---|
| Sample Number | Asbestos Content | Material Description | Friability | | | |
| DF-1013-01A-C | 65 % Chrysotile | White Pipe Insulation | TSI | F | 1 | Basement |
| DF-1013-01A-C | 65 % Chrysotile | White Pipe Fitting Insulation | TSI | F | 1 | Basement |
| Assumed | Unknown | White 1' x 1' Ceiling Tiles | Misc. | NF | 5 | Second Floor Secretary's Office |
| Assumed | Unknown | 1' x 1' Ceiling Tiles Glue Daubs | Misc. | NF | 5 | Second Floor Secretary's Office |

Information abstracted by: John Robert Hobbins Date: January 23, 2017

Material Category: TSI = Thermal System Insulation, Surf. = Surfacing, Misc. = Miscellaneous

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories:

1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM

Appendix C

Re-Inspection Form 1B



Re-Inspection Form 1 (B) – List of Previously-Unidentified Suspect ACBM

School: New Milford Public Schools
Address: 386 Danbury Road, New Milford, CT

Building: Facilities Administration
Date of Re-Inspection: January 23, 2017

Page 1 of 2

Date(s) of Original AHERA Inspection: 2000

| Sample Number | Homogeneous Material | Material Description | Asbestos Content (%) | Material Category | Estimated Quantity (SF/LF) | Friability | Assessment Category (1-7) | Recorded Locations of Material for Each Assessment Category |
|----------------------|---|-----------------------------|-----------------------------|--------------------------|-----------------------------------|-------------------|----------------------------------|--|
| N/A | Silver Duct Insulation | Assumed | TSI | 30 LF | F | 5 | | Attic |
| N/A | Tan/Black Batt Wrapping Insulation | Assumed | TSI | 30 LF | NF | 5 | | Attic |
| N/A | Black Sheet Paper underneath two Layers of Flooring | Assumed | Misc. | 390 SF | NF | 5 | | Kitchen |
| N/A | Yellow Ceramic Wall Tile | Assumed | Misc. | 400 SF | NF | 5 | | Bathroom |
| N/A | Gray Grout associated with Yellow Ceramic Wall Tile | Assumed | Misc. | 400 SF | NF | 5 | | Bathroom |
| N/A | Adhesive associated with Yellow Ceramic Wall Tile | Assumed | Misc. | 400 SF | NF | 5 | | Bathroom |
| N/A | Red Wall Paper | Assumed | Misc. | 560 SF | NF | 5 | | Bathroom, Room 1 |
| N/A | White/Blue Wall Paper | Assumed | Misc. | 700 SF | NF | 5 | | Facilities Manager, Maintenance Assistant offices |
| N/A | Yellow Wall Paper | Assumed | Misc. | 350 SF | NF | 5 | | Storage |
| N/A | Gray Plaster Base Coat | Assumed | S | 10,000 SF | F | 2 | | Throughout Walls, Ceiling and Chimney at the Attic |
| N/A | White Plaster Skim Coat | Assumed | S | 10,000 SF | F | 2 | | Throughout Walls, Ceiling and Chimney at the Attic |
| N/A | White Textured Skim Coat | Assumed | S | 1,800 SF | F | 5 | | Room 2-3, Stair Wells |
| N/A | White Gypsum Board Wall | Assumed | Misc. | 1,700 SF | NF | 5 | | Rear foyer, Bathrooms, Room 1, 2-2, 2-3, 2-4 |
| N/A | White Gypsum Board Joint Compound | Assumed | Misc. | 1,700 SF | NF | 5 | | Rear foyer, Bathrooms, Room 1, 2-2, 2-3, 2-4 |
| N/A | White Laminated Wall Panel | Assumed | Misc. | 700 SF | NF | 5 | | Kitchen |
| N/A | Wall Panel Glue associated with White Wall Panel | Assumed | Misc. | 700 SF | NF | 5 | | Kitchen |



Re-Inspection Form 1 (B) – List of Previously-Unidentified Suspect ACBM

School: New Milford Public Schools
Address: 386 Danbury Road, New Milford, CT

Building: Facilities Administration
Date of Re-Inspection: January 23, 2017

Page 2 of 2

Date(s) of Original AHERA Inspection: 2000

| Homogeneous Material | | Asbestos Content (%) | Material Category | Estimated Quantity (SF/LF) | Friability | Assessment Category (1-7) | Recorded Locations of Material for Each Assessment Category |
|----------------------|-----------------------------|----------------------|-------------------|----------------------------|------------|---------------------------|---|
| Sample Number | Material Description | | | | | | |
| N/A | Black Laminated Counter Top | Assumed | Misc. | 40 SF | NF | 5 | Kitchen |
| N/A | White 2" x 2" Ceiling Tiles | Assumed | Misc. | 144 SF | NF | 5 | Maintenance Assistant office |
| N/A | Gray Chimney Flue Cement | Assumed | Misc. | 2 SF | NF | 5 | Basement |

Inspected by: John Robert Hobbins Date: January 23, 2017

Material Category: TSI = Thermal System Insulation, S = Surfacing, M = Miscellaneous

LF = Linear Feet; SF = Square Feet

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories:

1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM

Appendix D

Re-Inspection Form 2



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 1 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White Pipe Insulation

Sample ID Number: DE-1013-01A-C

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|---|---|------------------------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Basement | F | 30 LF | 1 | Damaged or Significantly Damaged TSI ACBM | Repair of approximately 8 LF of white pipe insulation damaged at the basement. Maintain under the O&M Plan | Recommend Response for Summer 2017 |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: April 25, 2017 | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature: | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature: Accreditation #/State: <u>000309</u> Expiration Date: <u>01/31/2017</u> | |
| | | | | | I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 2 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White Pipe Fitting Insulation

Sample ID Number: DE-1013-01A-C

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|---|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Basement | F | 30 LF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature: | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature: | |
| Accreditation #/State: <u>000700</u> | | | | | Accreditation #/State: <u>000309</u> | |
| Expiration Date: <u>01/31/2017</u> | | | | | Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ | | | | | | |
| Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 2 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White 1'x 1' Ceiling Tiles

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|---|------------|--------------------|---------------------|--------------------------------|---|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Second Floor Secretary's Office | NF | 144 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature: | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature: | |
| Accreditation #/State: <u>000700</u> | | | | | Accreditation #/State: <u>000309</u> | |
| Expiration Date: <u>01/31/2017</u> | | | | | Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 4 of 22


School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: 1'x1' Ceiling Tiles Glue Daubs

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|---|---|---|--|--------------------------------------|--|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Second Floor Secretary's Office | NF | 144 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u>  | Management Planner Name: <u>Jared D. Smith</u>  | Inspector Signature: <u></u> | Management Planner Signature: <u></u> | Accreditation #/State: <u>000309</u> | Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 5 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Silver Duct Insulation

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|---|---|--------------------|---------------------|------------------------------------|--------------------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) |
| Attic | F | 30 LF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan |
| | | | | On Going | |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | |
| Date of Management Planner Review: <u>April 25, 2017</u> | | | | | |
| Inspector's Name: <u>John Robert Hobbins</u>  | Management Planner Name: <u>Jared D. Smith</u>  | | | | |
| Inspector Signature:  | Management Planner Signature:  | | | | |
| Accreditation #/State: <u>000700</u> | Accreditation #/State: <u>000309</u> | | | | |
| Expiration Date: <u>01/31/2017</u> | Expiration Date: <u>10/31/2017</u> | | | | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ | | | | | |
| Date: _____ | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 6 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Tan/Black Batt Wrapping Insulation

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|---|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Attic | NF | 30 LF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature:  Accreditation #/State: <u>000700</u> Expiration Date: <u>01/31/2017</u> | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature:  Accreditation #/State: <u>000309</u> Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 7 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Black Sheet Paper underneath two Layers of Flooring

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|---|---|--------------------|---------------------|------------------------------------|--------------------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) |
| Kitchen | NF | 390 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan |
| | | | | On Going | |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | |
| Date of Management Planner Review: <u>April 25, 2017</u> | | | | | |
| Inspector's Name: <u>John Robert Hobbins</u>  | Management Planner Name: <u>Jared D. Smith</u>  | | | | |
| Inspector Signature:  | Management Planner Signature:  | | | | |
| Accreditation #/State: <u>000700</u> | Accreditation #/State: <u>000309</u> | | | | |
| Expiration Date: <u>01/31/2017</u> | Expiration Date: <u>10/31/2017</u> | | | | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ | | | | | |
| Date: _____ | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 8 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Yellow Ceramic Wall Tile

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|---|---|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) |
| Bathrooms | NF | 400 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature: | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature: | |
| Accreditation #/State: <u>000700</u> | | | | Accreditation #/State: <u>000309</u> | |
| Expiration Date: <u>01/31/2017</u> | | | | Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 2 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Gray Grout associated with Yellow Ceramic Wall Tile

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | | |
|---|---|---|--|--|------------------------------------|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Bathrooms | NF | 400 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | Date of Management Planner Review: <u>April 25, 2017</u> | | |
| Inspector's Name: <u>John Robert Hobbins</u>  | Management Planner Name: <u>Jared D. Smith</u>  | Inspector Signature: <u></u> | Management Planner Signature: <u></u> | Accreditation #/State: <u>000309</u> | Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 10 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Adhesive associated with Yellow Ceramic Wall Tile

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | | |
|---|---|--------------------|---------------------|--|--------------------------------|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Bathrooms | NF | 400 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | Date of Management Planner Review: <u>April 25, 2017</u> | | |
| Inspector's Name: <u>John Robert Hobbins</u>  | Management Planner Name: <u>Jared D. Smith</u>  | | | | | |
| Inspector Signature:  | Management Planner Signature:  | | | | | |
| Accreditation #/State: <u>000700</u> | Accreditation #/State: <u>000309</u> | | | | | |
| Expiration Date: <u>01/31/2017</u> | Expiration Date: <u>10/31/2017</u> | | | | | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ | | | | | | |
| Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 11 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Red Wall Paper

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|---|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| 1st Floor Bathroom, Room 1 | NF | 560 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature:  Accreditation #/State: <u>000700</u> Expiration Date: <u>01/31/2017</u> | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature:  Accreditation #/State: <u>000309</u> Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 12 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White/Blue Wall Paper

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------------|---|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Facilities Manager, Maintenance Assistant offices | NF | 700 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature:  Accreditation #/State: <u>000700</u> Expiration Date: <u>01/31/2017</u> | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature:  Accreditation #/State: <u>000309</u> Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 13 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Yellow Wall Paper

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|---|---|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) |
| Storage | NF | 350 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature: | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature: | |
| Accreditation #/State: <u>000700</u> | | | | Accreditation #/State: <u>000309</u> | |
| Expiration Date: <u>01/31/2017</u> | | | | Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 14 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Gray Plaster Base Coat

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|---|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Throughout Walls, Ceiling and Chimney at the Attic | F | 10,000 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature:  Accreditation #/State: <u>000700</u> Expiration Date: <u>01/31/2017</u> | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature:  Accreditation #/State: <u>000309</u> Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 15 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White Plaster Skim Coat

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|---|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Throughout Walls, Ceiling and Chimney at the Attic | F | 10,000 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature:  Accreditation #/State: <u>000700</u> Expiration Date: <u>01/31/2017</u> | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature:  Accreditation #/State: <u>000309</u> Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 16 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White Textured Skim Coat

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | | |
|---|---|---|--|--|------------------------------------|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Room 2-3, Stairwells | F | 1,800 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | Date of Management Planner Review: <u>April 25, 2017</u> | | |
| Inspector's Name: <u>John Robert Hobbins</u>  | Management Planner Name: <u>Jared D. Smith</u>  | Inspector Signature: <u></u> | Management Planner Signature: <u></u> | Accreditation #/State: <u>000309</u> | Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 17 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White Gypsum Board Wall

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|---|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Rear foyer, Bathrooms, Room 1, 2-2, 2-3, 2-4 | NF | 1,700 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature:  Accreditation #/State: <u>000700</u> Expiration Date: <u>01/31/2017</u> | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature:  Accreditation #/State: <u>000309</u> Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 18 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White Gypsum Board Joint Compound

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|---|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Rear foyer, Bathrooms, Room 1, 2-2, 2-3, 2-4 | NF | 1,700 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan | On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature:  Accreditation #/State: <u>000700</u> Expiration Date: <u>01/31/2017</u> | | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature:  Accreditation #/State: <u>000309</u> Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 19 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White Laminated Wall Panel

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|---|---|--------------------|---------------------|------------------------------------|--------------------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) |
| Kitchen | NF | 700 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan |
| | | | | On Going | |
| Were additional samples of this ACBM collected? <u>No</u> | | | | | |
| Date of Management Planner Review: <u>April 25, 2017</u> | | | | | |
| Inspector's Name: <u>John Robert Hobbins</u>  | Management Planner Name: <u>Jared D. Smith</u>  | | | | |
| Inspector Signature:  | Management Planner Signature:  | | | | |
| Accreditation #/State: <u>000700</u> | Accreditation #/State: <u>000309</u> | | | | |
| Expiration Date: <u>01/31/2017</u> | Expiration Date: <u>10/31/2017</u> | | | | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ | | | | | |
| Date: _____ | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 20 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Wall Panel Glue associated with White Wall Panel

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|---|---|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) |
| Kitchen | NF | 700 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature: | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature: | |
| Accreditation #/State: <u>000700</u> | | | | Accreditation #/State: <u>000309</u> | |
| Expiration Date: <u>01/31/2017</u> | | | | Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 21 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: Black Laminated Counter Top

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|---|---|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) |
| Kitchen | NF | 40 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature:  Accreditation #/State: <u>000700</u> Expiration Date: <u>01/31/2017</u> | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature:  Accreditation #/State: <u>000309</u> Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | |



FUSS & O'NEILL
EnviroScience, LLC

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 22 of 22

School: New Milford Public Schools

Building: Facilities Administration

Date of Re-Inspection: January 23, 2017

Homogeneous Material: White 2" x 2" Ceiling Tile

Sample ID Number: Assumed

| ACBM RE-INSPECTION FINDINGS | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|---|---|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) |
| Maintenance Assistant Office | NF | 144 SF | 5 | ACBM with Potential for Damage | Maintain under the O&M Plan On Going |
| Were additional samples of this ACBM collected? <u>No</u> | | | | Date of Management Planner Review: <u>April 25, 2017</u> | |
| Inspector's Name: <u>John Robert Hobbins</u> Inspector Signature:  Accreditation #/State: <u>000700</u> Expiration Date: <u>01/31/2017</u> | | | | Management Planner Name: <u>Jared D. Smith</u> Management Planner Signature:  Accreditation #/State: <u>000309</u> Expiration Date: <u>10/31/2017</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: Date: _____ | | | | | |

Appendix E

Sample 6-Month Periodic Surveillance Form



Sample 6-Month Periodic Surveillance Form

Local Education Agency (LEA): New Milford Public Schools

Facility Address: Facilities Administration Building, 386 Danbury Road, New Milford CT

Date of Surveillance:

ACBM Damage Report

| Asbestos-Containing Building Material | Location | Previous Condition | Present Condition | Change in Condition (Yes/No) | Estimated Damaged Quantity | Comments |
|---|--|--------------------|-------------------|------------------------------|----------------------------|---|
| White Pipe Insulation | Basement | | | | | 8 LF of Pipe Insulation Damaged in Basement Maintain under O&M Plan |
| White Pipe Fitting Insulation | Basement | | | | | |
| White 1' x 1' Ceiling Tiles | Second Floor Secretary's Office | | | | | |
| 1' x 1' Ceiling Tiles Glue Daubs | Second Floor Secretary's Office | | | | | |
| Silver Duct Insulation | Attic | | | | | |
| Tan/Black Batt Wrapping Insulation | Attic | | | | | |
| Black Sheet Paper underneath two Layers of Flooring | Kitchen | | | | | |
| Yellow Ceramic Wall Tile | Bathrooms | | | | | |
| Gray Ceramic Wall Tile Grout | Bathrooms | | | | | |
| Gray Ceramic Wall Tile Adhesive | Bathrooms | | | | | |
| Red Wall Paper | 1 st Floor Bathroom, Room 1 | | | | | |
| White/Blue Wall Paper | Facilities Manager, Maintenance Assistant offices | | | | | |
| Yellow Wall Paper | Storage | | | | | |
| Gray Plaster Base Coat | Throughout Walls, Ceiling and Chimney at the Attic | | | | | |

| Asbestos-Containing Building Material | Location | Previous Condition | Present Condition | Change in Condition (Yes/No) | Estimated Damaged Quantity | Comments |
|--|--|---------------------------|--------------------------|-------------------------------------|-----------------------------------|-----------------|
| White Plaster Skim Coat | Throughout Walls, Ceiling and Chimney at the Attic | | | | | |
| White Textured Skim Coat | Room 2-3, Stairwells | | | | | |
| White Gypsum Board Wall | Rear foyer, Bathrooms, Room 1, 2-2, 2-3, 2-4 | | | | | |
| White Gypsum Board Joint Compound | Rear foyer, Bathrooms, Room 1, 2-2, 2-3, 2-4 | | | | | |
| White Laminated Wall Panel with White Wall Panel | Kitchen | | | | | |
| Black Laminated Counter Top | Kitchen | | | | | |
| White 2" x 2" Ceiling Tiles | Maintenance Assistant office | | | | | |

Conditions: D = Damaged; F = Fair; G = Good; IA = Inaccessible; N/A = Not Applicable; SD = Significant Damage; SF = Square Feet

Surveillance conducted by: _____

(print name) _____
(signature)

I, the LEA's Designated Person, have read and understood the findings noted above:

Date: _____

Appendix F

Preventive Measures

Preventive Measures for Various Asbestos-Containing Building Materials

A. Surfacing Materials

“Surfacing Materials” means materials in a school building that are applied by spray, trowel, or otherwise applied to surfaces. These include sprayed-applied fireproofing materials on structural members, ceiling and wall plasters, or other materials applied to surfaces for acoustical, fireproofing, or other purposes.

Surfacing Materials are generally considered friable and can release asbestos fibers if damaged by impact, air erosion, vibration, and/or water intrusion. When properly implemented, the following procedures will reduce the potential for fiber release:

1. Sprayed-Applied Fireproofing
 - a) Identify the materials and post warning signs on the laid-in or glued-in ceiling tile. If the decking is not covered, place the sign on the wall.
 - b) Maintain the materials in intact Connecticut and undamaged condition. During winter, pigeons, squirrels and other rodents tend to roost in boiler/machine rooms and dislodge sprayed-applied fireproofing on the decking. Prevent such possibilities.
 - c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, enclosure is a temporary solution. Encapsulation of damaged sprayed-on fireproofing material is not recommended.
 - d) Train the custodial people who are responsible for care and maintenance of surfacing materials. Please note that the repair/removal can only be performed by a licensed abatement contractor.
2. Ceiling and Wall Plasters
 - a) Identify the materials and post asbestos warning signs.
 - b) Maintain the materials in intact Connecticut and undamaged condition. Avoid storing/stacking on/near the materials to reduce contact damage.
 - c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, repair or enclosure is a temporary solution.
 - d) Train the custodial people who are responsible for care and maintenance of surfacing materials.

B. Thermal System Insulation (TSI)

“Thermal System Insulation (TSI)” means insulating materials applied to pipes, pipe fittings, boilers, breechings, tanks, ducts, or other components to prevent process heat loss or gain, water condensation, or for other purposes (e.g., fire door insulation core).

TSI are generally considered friable ACM. This means they can be easily damaged, increasing the potential for fiber release. When properly implemented, the following procedures will reduce the potential for fiber release:

1. **Boiler and Breeching Insulation**
 - a) Identify the locations and label the boiler. Warning signs should be posted outside the boiler room.
 - b) Reduce the likelihood of fiber release by ensuring that the insulation is not damaged. Avoid storing/stacking on/near the boiler to reduce contact damage.
 - c) Maintain the insulation in intact Connecticut and undamaged condition. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
 - d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.
2. **Pipe, Pipe Fitting, Tank, Duct & Breeching Insulations**
 - a) Identify the locations and label the materials. Warning signs should be posted outside of rooms that have TSI materials.
 - b) Reduce the likelihood of fiber release by ensuring that the materials are not damaged. Avoid storing/stacking near the materials to reduce contact damage.
 - c) Maintain all TSI materials in intact Connecticut and undamaged condition. Inspect the protective jackets for damage. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
 - d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

C. Miscellaneous Materials

“Miscellaneous Materials” are the other ACM in a school building that are not categorized as Surfacing Materials or TSI. These include floor tiles, floor tile and carpet mastics, gypsum wallboard and joint compound, ceiling tiles, glue daubs, asbestos cement panels, cove base and associated glue, window/door caulking and glazing compounds, etc. The following maintenance procedures are recommended for these materials:

1. Vinyl Asbestos Floor Tiles (VAT)

Vinyl Asbestos Floor Tiles (VAT) are considered non-friable, however routine maintenance procedures such as spray-buffing, burnishing, wet scrubbing, and stripping can generate asbestos fibers. Following procedures, when properly implemented, will reduce the potential of fiber release:

- a) Do not sand, grind, or abrade the tiles. Stripping of VAT should be done as infrequently as possible. When stripping becomes necessary, follow the appropriate work practices. Never perform dry stripping.
- b) During spray-buffing or burnishing the floor, operate the machine at the lowest workable speed and use the least abrasive pad. Use a wet mop for routine cleaning whenever possible.
- c) Routinely check whether chair and desk glides are in good condition and replace when necessary. Worn glides can gouge the floor and cause fiber release.
- d) Place carpets/floor mats in all entrances to reduce abrasion of floor tiles by sand and pebbles. During winter, have parking lots and walkways swept to the extent possible to avoid the tracking of salt and ice-melting compounds into the school by the students.
- e) Train the custodial people who are responsible for care and maintenance of VAT. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Wallboard and Joint Compound Assembly

- a) Since a number of different homogeneous assemblies may exist in a building, sheetrock/joint compound must be assumed to be ACBM unless sample results prove otherwise. If any specific areas are going to be disturbed, samples of the material in that area should be collected and analyzed.
- b) Reduce the likelihood of fiber release by avoiding cutting or drilling holes through the sheetrock panels.

3. Ceiling Tile and Glue Daubs

- a) Reduce the likelihood of fiber release by limiting access to the space above the ceiling tiles. Maintain the ceiling tiles in undamaged condition. Replace any damaged or water-stained tile.
- b) If the ceiling tiles are non-asbestos, collect samples and analyze the glue daubs to identify asbestos-content before disturbing the tiles.

4. Asbestos Cement Panels, Window/Door Caulking and Glazing Compounds

- a) Maintain asbestos cement panels and window/door caulking and glazing compounds in undamaged condition.

5. Carpet Glue, Blackboard/Tack Board Glue, Floor Tile Mastic, Cove Base, and Mastic

- a) Reduce the likelihood of fiber release by leaving materials in place.
- b) Maintain materials in good condition. Collect samples and analyze to identify asbestos-content before disturbing.

Appendix G

Asbestos Inspector and Management Planner Licenses and EPA Accreditations

1001102 01 AV 0.388 **AUTO 162 0564 06040 599246 C01-P011051



JOHN R. HOBBINS
C/O FUSS & O'NEILL ENVIROSCIENCE, LLC
146 HARTFORD ROAD
MANCHESTER CT 06040-5992



Dear JOHN R. HOBBINS,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health
P.O. Box 340308
M.S.#12MQA
Hartford, CT 06134-0308

Sincerely,

Raeus

**RAUL PINO, MD, MPH, ACTING COMMISSIONER
DEPARTMENT OF PUBLIC HEALTH**

| | | |
|------------------------------------|---------------------|-----------------------|
| EMPLOYER'S COPY | | |
| STATE OF CONNECTICUT | | |
| DEPARTMENT OF PUBLIC HEALTH | | |
| NAME | | |
| JOHN R. HOBBINS | | |
| VALIDATION NO. | CERTIFICATE NO. | CURRENT THROUGH |
| 03-373287 | 000700 | 01/31/17 |
| PROFESSION | | |
| ASBESTOS CONSULTANT-INSPECTOR | | |
| <u><i>John R. Hobbins</i></u> | | <u><i>Raymond</i></u> |
| SIGNATURE | ACTING COMMISSIONER | |

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED
BY THIS DEPARTMENT AS A
ASBESTOS CONSULTANT-INSPECTOR

JOHN R. HOBIBNS

CERTIFICATE NO
000700

CURRENT THROU
01/31/17

VALIDATION NO
03-373287

John R Hoffmire
SIGNATURE

Raymond
ACTING COMMISSIONER

INSTRUCTIONS:

1. Detach and sign each of the cards on this form.
 2. Display the large card in a prominent place in your office or place of business.
 3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet card, place it in a secure place.
 4. The employer's copy is for persons who must demonstrate current licensure/certification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.

| | | |
|--|---------------------|-----------------|
| WALLET CARD | | |
| STATE OF CONNECTICUT | | |
| DEPARTMENT OF PUBLIC HEALTH | | |
| NAME | | |
| JOHN R. HOBBINS | | |
| VALIDATION NO. | CERTIFICATE NO. | CURRENT THROUGH |
| 03-373287 | 000700 | 01/31/17 |
| PROFESSION | | |
| ASBESTOS CONSULTANT-INSPECTOR | | |
| <u><i>John R. Hobbin</i></u> <u><i>Raymond</i></u> | | |
| SIGNATURE | ACTING COMMISSIONER | |

ATC GROUP SERVICES LLC

104 East 25th Street, New York, NY 10010
(212) 353-8280

certifies that

John Robert Hobbins

XX-XX-XXXX

(Social Security Number)

*Has Successfully Completed the Accredited 4 Hour EPA-AHERA/ASHARA under 40 CFR 763 and the
New York State Department of Health Approved Course for*

Asbestos Inspector Refresher

on


September 12, 2016

**** Please note that the official record of successful completion is the DOH 2832 Certificate of Asbestos Safety Training.****

This course meets the requirements of TSCA Title II

Certificate#: NYS -RHIIR-20938
Course Location ATC, NYC

Exam date: 09-12-16 Expiration Date: 09-12-17



Signed:

Steve Winograd, Director of Training

1000185 01 AV 0.3/3 **AUTO** 103 1 1464 064/3 155815 C01 P003871



JARED D SMITH
15 RIDGEBURY RD
EAST HADDAM CT 06423-1558



Dear JARED D SMITH,



Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health (860) 509-7603
P.O. Box 340308 opcl.dph@ct.gov
M.S.#12MQA www.ct.gov/dph/license
Hartford, CT 06134-0308

Sincerely,

Zayd
PAUL RINGARD, MD, COM

**RAUL PINO, MD, MPH, COMMISSIONER
DEPARTMENT OF PUBLIC HEALTH**

| | | |
|---|-----------------|---|
| EMPLOYER'S COPY | | |
| STATE OF CONNECTICUT | | |
| DEPARTMENT OF PUBLIC HEALTH | | |
| NAME | | |
| JARED D SMITH | | |
| VALIDATION NO. | CERTIFICATE NO. | CURRENT THROUGH |
| 03-547810 | 000309 | 10/31/17 |
| PROFESSION | | |
| ASBESTOS CONSULTANT-INSP/MGMT PLANNER | | |
|  | |  |
| SIGNATURE | COMMISSIONER | |

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED
BY THIS DEPARTMENT AS A
ASBESTOS CONSULTANT-INSP/MGMT PLANNER

JARED D SMITH

CERTIFICATE NO.
000309

CURRENT THROUGH
10/31/17

VALIDATION NO.
03-547810

SIGNATURE

COMMISSIONER

SIGNATURE

WALLET CARD
STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH

NAME

VALIDATION
03-54781

CERTIFICATE NO.
000309

CURRENT THROUGH
10/31/17

PROFESSION

Digitized by srujanika@gmail.com

10

B. C.

— — —

SIGNATURE

Certificate of Training

Awarded to

JARED D. SMITH

*For successful completion of an 8 Hour, 1 Day
Asbestos Inspector & Management Planner
Annual Refresher Training
September 9, 2016*

This training was approved and given in accordance with
Regulations for Connecticut State Agencies
RCSA 20-440 -1-9 and RCSA 20-441 and meets the
requirements of the EPA Revised MAP under TSCA Title II of 4/4/94

Presented by

Mystic Air Quality Consultants, Inc.

1204 North Road, Groton, CT 06340 (800) 247-7746

Certificate Number: IMPR25287
Exam Grade: 100
Exam Date: 09/09/2016
Expiration Date: 09/09/2017

Christopher J. Eident
Christopher J. Eident, CIH, CSP, RS

George Williamson, Training Director

Richard Haffey, Training Director

