



August 31, 2005

Mr. John Calhoun
Facilities Manager
Environmental Services
New Milford Public Schools
386 Danbury Road
New Milford, CT 06776

**RE: Three Year AHERA Asbestos Re-inspection
and Management Plan Update
John Pettibone Elementary School
New Milford, CT
EnviroScience Project No. 04-542.10**

Dear Mr. Calhoun:

Enclosed is the report of the three-year AHERA asbestos re-inspection and Management Plan update conducted by EnviroScience Consultants, Inc. (EnviroScience) at John Pettibone Elementary School, in New Milford, Connecticut. This report is an important document that must be kept on file at the school as well as at a central location where the Management Plans are preserved. Please review re-inspection form 2 in Appendix D and sign and date each form at the bottom.

If you have any questions regarding this report, please do not hesitate to contact me at (203) 333-8872 extension 3102. Thank you for this opportunity to have served your environmental needs.

Sincerely,

A handwritten signature in cursive script that reads "Matthew Myers".

Matthew Myers
Manager, Hazardous Materials

MAM:ti

Enclosure

Y:\WORD\Projects\04\04-542.10 3yr-AHERA Pettibone.doc



ASBESTOS HAZARD EMERGENCY RESPONSE ACT
THREE-YEAR ASBESTOS REINSPECTION AND
MANAGEMENT PLAN UPDATE
FOR
JOHN PETTIBONE ELEMENTARY SCHOOL

PERFORMED BY

ENVIROSCIENCE CONSULTANTS, INC.
795 NORTH MOUNTAIN ROAD
NEWINGTON, CONNECTICUT 06111

For Compliance with
State of Connecticut, Department of Public Health
Regulation Regarding Asbestos-Containing Material in Schools
(19a - 333-1 through 19a - 333-13)

And
EPA Asbestos Hazard Emergency Response Act
(40 CFR Part 763)

TABLE OF CONTENTS

SECTION	PAGE
1.0 INTRODUCTION.....	1
2.0 BUILDING & MECHANICAL SYSTEM DESCRIPTION	1
3.0 REINSPECTION REPORT	2
3.1 Review of Records.....	2
3.2 Re-inspection Summary.....	2
3.3 Newly Identified or Re-sampled ACBM	4
3.4 Physical Assessment of ACBM	4
4.0 MANAGEMENT PLAN UPDATE.....	5
4.1 Recommended Response Actions.....	5
4.2 Periodic Surveillance	7
4.3 Preventive Measures	7
5.0 EPA CERTIFICATION REQUIREMENTS	7

APPENDICES

APPENDIX A:	CHECKLIST FOR EXISTING RECORDS
APPENDIX B:	REINSPECTION FORM 1A
APPENDIX C:	REINSPECTION FORM 1B
APPENDIX D:	REINSPECTION FORM 2
APPENDIX E:	PERIODIC SURVEILLANCE FORM
APPENDIX F:	PREVENTIVE MEASURES
APPENDIX G:	AHERA ACCREDITATIONS
APPENDIX H:	BUILDING DIAGRAM

1.0 INTRODUCTION

This three-year asbestos re-inspection of John Pettibone Elementary School, New Milford, Connecticut was conducted in accordance with the requirements of the following regulations:

- (i) State of Connecticut Department of Public Health (CTDPH) Asbestos-Containing Materials in Schools regulation (19a-331-1 through 19a-333-13, Section 3 (b)).
- (ii) United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) regulation (40 CFR Part 763, Section 763.85 (b)).

Mr. Dominick Fiore of EnviroScience Consultants, Inc. (EnviroScience) performed the re-inspection on January 18 and 20, 2005. Mr. Fiore is an accredited Asbestos Inspector in the State of Connecticut (License No. 000299). During the re-inspection, the following required tasks were performed:

1. A visual re-inspection and reassessment of all friable known or assumed asbestos-containing building materials (ACBM).
2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has made it friable.
3. Identification and assessment of any homogeneous areas that contains newly friable ACBM.
4. The six-month periodic surveillance was also conducted to assess the condition of the known and assumed asbestos containing materials.

2.0 BUILDING AND MECHANICAL SYSTEM DESCRIPTION

The John Pettibone Elementary School was built in 1955, with new additions constructed in 1958 and 1964. There are four wings to the building, all located on the ground floor.

The building is constructed on a slab foundation with brick outer walls and a corrugated steel frame. The inner walls are constructed of cinderblocks. A suspended ceiling exists in most of the building, resulting in a ceiling space with water pipes, air ducts and roof drains located near the true ceiling deck.

Ventilation is provided by an air handling system which draws air into return ducts and supplies air by means of air handling units located on the roof, forcing air into each room by means of supply ducts.

All areas of the school are serviced by a central boiler room. Heat is provided by two oil burning boilers, which convey heat through the pipe tunnels. The pipe tunnels begin at the boiler room and are located below grade throughout the perimeter of the building, branching up to baseboard radiators, which are located in each of the rooms.

3.0 RE-INSPECTION REPORT

3.1 Review of Records (Checklist)

An important part of this AHERA Re-inspection involved checking documentation that were required to be present at the school being inspected as well as at the central location where all management plans are preserved.

In reviewing the 1990 3-year AHERA original inspection the following materials were sampled and determined to be non asbestos containing materials: Plaster, 1'x1' ceiling tiles, and 2'x4' lay in ceiling tiles.

The wall plaster samples were taken in the 1955 section and labeled as 3-6-90PB 87-89.
The 1'x1' ceiling tile samples were taken in the 1958 section and labeled as 3-6-90PB45-47.
The 2'x4' ceiling tiles were taken in the 1955 section and labeled 3-6-90PB-39-41.
The 2'x4' ceiling tile were taken in the 1958 section and labeled 3-6-90PB-42-44.
The 2'x4' ceiling tile were taken in the 1962 section and labeled 3-6-90PB-50-52.

Please see Appendix A for details of our findings.

3.2 Re-inspection Summary

The on-site portion of the re-inspection was documented on forms modeled after examples provided by USEPA and reviewed by the State of Connecticut Department of Public Health.

The first form, **Re-inspection Form 1A**, abstracts inspection data gathered during the initial AHERA inspection (see Appendix B). This form is useful to reference response actions (if any) which have been performed since the last inspection. It additionally provides the inspector a "quick glance" reference when performing the re-inspection.

The second EPA form, **Re-inspection Form 1B**, is used to list all known or assumed asbestos-containing materials that were previously unidentified (see Appendix C). It also lists the ACBM in areas newly acquired by the school for student use, either permanently or temporarily.

The third EPA form, **Reinspection Form 2**, was used to provide information and justification regarding reassessment of the ACBM (see Appendix D). This form also provides response action recommendation including a tentative schedule for completing response actions that recommended removal or repair.

Using the USEPA protocol and criteria, the following materials existing in John Pettibone Elementary School at the time of this three year re-inspection have been determined or are assumed to be ACBM.

HOMOGENEOUS MATERIAL	REFERENCE	LOCATION(S)
Possible vapor barrier and mastic	EnviroScience 1999 AHERA Inspection	Gym, under wood floor
Ceramic tile adhesive/grout		All bathrooms, wherever ceramic tile is found
Pipe and pipe fitting insulation		Throughout School- within walls/pipe chases, especially bathrooms
9"x9" Floor tile(s) and associated mastic(s)		Main office, vault room and storage closets by principal's office, custodian's closet by Room 3, book storage room across from Main Office, storage room by room 29 and custodial closets by rooms 26 and 27
1'x1' ceiling tiles and associated glue daubs		Vice principal's and guidance offices, Foyer at building entrance and hallway between cafeteria and gym, 1962 Building entrance foyer ceiling, Rooms 21-30
Air cell pipe insulation		1955 tunnel – 50' from access door located in boiler room (blue access door)
Asphaltic paper vapor barrier		1955 tunnels, applied to concrete ceiling
Ceiling glue daubs		Closet storage area across hall from room 26
Black window sills		Rooms 10-16 (A and B), 18 and 20A
Mudded pipe fittings		1964 Wing, storage room near room 20
Flexible duct connector		1964 Wing, storage room near room 20
Plaster ceilings and walls and any other type of walls systems		Throughout building
Possible asbestos-containing cement board under the exterior windows		Throughout building

The information obtained during this re-inspection was transmitted to Mr. Matthew Myers, an accredited Management Planner, so that response actions relative to the condition of the ACBM could be designed. Mr. Myers is a licensed Asbestos Management Planner in the State of Connecticut (License No. 000041).

3.3 Newly Identified or Re-sampled ACBM

During the course of this re-inspection, several materials previously unidentified were discovered, which are suspected of being ACBM. Please refer to Re-inspection Form 1(B) for specific assessments. No bulk samples were taken of these materials during the re-inspection:

HOMOGENEOUS MATERIAL	REFERENCE	LOCATION(S)
Pipe Insulation/fittings above lay in ceiling tile	EnviroScience 2005 AHERA Inspection	Main office hallway outside principal's office and in copier room, Hallway outside Rooms 31, 33, bathrooms by Room 10
Mudded fitting associated with fiberglass pipe insulation		All Bathrooms, within walls & pipe chases
9"x9" floor tile and mastic under carpet		Throughout school (including under carpeted areas)
Sink undercoating		All classrooms (1-9, 21-30)
Blackboard and Tackboard adhesives		Throughout school

Note: The mudded fittings observed during the inspection did not have any jackets over them, but were intact and above drop-ceilings. No action is necessary at this point.

AHERA only regulates interior ACBM. Therefore, exterior ACBM were not sampled. However, the following suspect ACBM were noted exterior to the building: caulking compounds transite board and roofing materials.

Any suspect material encountered during potential renovation/demolition that is not specifically identified in this report as a non-ACM should be assumed to contain asbestos unless sample results prove otherwise.

3.4 Physical Assessment of ACBMs

During inspection, suspect ACBM were separated into three USEPA categories. These categories are thermal system insulation (TSI), surfacing ACBM, and miscellaneous ACBM. TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe insulation, boiler insulation, duct insulation, and mudded insulation on pipe fittings. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACBM not listed in TSI or surfacing, such as linoleum, vinyl asbestos flooring, and ceiling tiles. Finally, all ACBM is quantified in linear and/or square footage, depending on the nature of the material.

All ACBM identified during the inspection and still remaining in the school were reassessed using the State of Connecticut Department of Public Health and AHERA guidelines for assessment of ACBM. The assessment categories are listed as follows:

- 1 = Damaged or significantly damaged TSI ACBM
- 2 = Damaged friable surfacing ACBM
- 3 = Significantly damaged friable surfacing ACBM
- 4 = Damaged or significantly damaged friable miscellaneous ACBM
- 5 = ACBM with potential for damage
- 6 = ACBM with potential for significant damage
- 7 = Any remaining friable ACBM or friable suspected ACBM

Material locations, assessments, and recommended response actions are listed in the re-inspection forms.

4.0 MANAGEMENT PLAN UPDATE

Based on the inspection report, physical walk-through inspection and existing condition of the ACBM, following response actions are recommended:

4.1 Recommended Response Actions

- 1. Removal
Not applicable
- 2. Repair
Not applicable
- 3. Enclosure
Not applicable
- 4. Encapsulation
Not applicable
- 5. Operations and Maintenance (O & M)

It should be noted that only locations with assessments of 1 or 2 are recommended for removal or repair. All remaining ACBM in the school shall be placed in an Operations and Maintenance (O & M) Program. The condition of such materials will be monitored until all the ACBM have been removed from the building. A successful O & M Program include the following elements:

- a) Cleaning: All areas of the school where friable ACBM or friable suspected ACBM assumed to be ACBM are present shall be cleaned at least once after the completion of the initial inspection. Additional cleaning may be necessary if the Management Planner make a written recommendation indicating methods and frequency of such cleaning.
- b) O & M Activities: The LEA shall ensure that the procedures described below are followed to protect building occupants for any O & M activities that may disturb known or assumed ACBM:
 - (1) Restrict entry into the area either by physically isolating or by scheduling.
 - (2) Post warning signs to prevent entry by unauthorized persons.
 - (3) Shut off or temporarily modify the air-handling system.
 - (4) Use proper work practices and engineering controls such as wet methods, protective clothing, HEPA-vacuums, mini enclosures/ glove bags etc. to inhibit spread of fibers.
 - (5) Place all asbestos debris and other contaminated materials in a sealed, leak-tight container for eventual disposal.
- c) Minor Fiber Release Episodes: The LEA shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., disturbance of 3 linear/ square feet or less of friable ACBM):
 - (1) Saturate the debris using wet method.
 - (2) Place the debris in a sealed leak-tight container and clean the area.
 - (3) Repair the area of damaged ACBM with materials such as asbestos-free spackling, plaster or insulation or seal with an encapsulant.
- d) Major Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., disturbance of more than 3 linear/square feet of friable ACBM):
 - (1) Restrict entry into the area and post warning signs.
 - (2) Shut off or temporarily modify the air handling system to prevent spread of fibers to other areas of the school.
 - (3) **The response for any major fiber release episode must be designed by persons accredited to design response actions and conducted by persons accredited to conduct response actions.**
 - (4) The LEA shall notify the CTDPH of any major fiber release episode within twenty-four hours of its occurrence and, if necessary, provide written notification as required by applicable federal and/or state regulations.

4.2 Periodic Surveillance

At least once every six (6) months after a management plan is in place, the LEA shall conduct periodic surveillance in the school that contains ACBM or assumed to contain ACBM. The person conducting periodic surveillance shall visually inspect all areas in the school that have been identified in the management plan as having ACBM, record the date of surveillance, his/her name, and any changes in the condition of the materials and submit the record to the LEA Designated Person for inclusion in the management plan.

Please see Appendix E for Periodic Surveillance Form that may be used for conducting periodic surveillance.

4.3 Preventive Measures

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that the ACBM will become damaged, deteriorated or delaminated.

Please see Appendix F for preventive measures designed for various types of ACBM that may exist in the school.

5.0 EPA CERTIFICATION REQUIREMENTS

The certificates and the licenses for the individuals (Dominick Fiore and Matthew Myers) involved in performing the re-inspection and updating the management plan are provided in Appendix G.

Y:\WORD\Projects\04\04-542.10 3yr-AHERA Pettibone.doc

CHECKLIST FOR EXISTING RECORDS

Local Education Agency (LEA): Lillis Administration Building
50 East Street, New Milford, Connecticut

School Building: John Pettibone Elementary School

The following documentation is required to be present in both the LEA's Office as well as in a centralized location in the administrative office of the school. The information included in this checklist shall be verified to be present and complete as part of three year re-inspection.

DOCUMENTATION		LOCATION	
		School	LEA Office
1.	Original AHERA Inspection/Management Plan	Yes	Yes
2.	Three year Re-inspection (First)	Yes	Yes
3.	Three year Re-inspection (Second)	No	No
4.	Notifications to Parents/Guardians and Teachers (yearly since last re-inspection)	No	No
5.	Designated Person Identified and Proper Training (person must be named and have appropriate training)	No	No
6.	Designated Person Periodic Surveillance (every six months since last re-inspection)	No	No
7.	Record of Awareness Training for Maintenance Staff	No	No
8.	Outside Vendor Awareness Notification	No	No
9.	Warning Signs and Labels (required posting in Boiler room and mechanical spaces only)	No	No
10.	Record of Response Actions (includes any abatement done since last re-inspection)	No	No

Comments: _____

Inspector: Dominick Fiore

Date: 01/20/05

School New Milford Building John Petti bone

Homogeneous sampling areas		Material Category	Friability	Condition category (1-7)	Recorded locations	Response actions taken/renovations/other comments
Sample number	Material description					
None collected	vapor barrier	TSI Surf. Misc. (NF)	(NF)	5	Gymnasium under wood floor	
	ceramic tile adhesive / Prout	TSI Surf. Misc. (NF)	(NF)	5	All bathrooms, wherever ceramic tile is found	
	Pipe Insulation pipe fitting	TSI Surf. Misc. (NF)	(NF)	5	Throughout school with walls/pipe chases, especially bathrooms	
	9x9 Floor Tile and master	TSI Surf. Misc. (NF)	(NF)	5	Main office, vault Rm. and storage closets by Principals office, custodian closet by	
		TSI Surf. Misc. (NF)	(NF)	5	Room 3, book storage Room across Main office storage Rm by Rm 2 & custodial closets by Rm 1, 2, 6 & 7	
		TSI Surf. Misc. (NF)	(NF)	5		

Information abstracted by Dominick Fiore Date Jan 18/20, 2005

Friability: F = friable, NF = nonfriable

AHERA assessment category: 1 = Damaged or significantly damaged TSI ACBM, 2 = Damaged friable surfacing ACBM, 3 = Significantly damaged friable surfacing ACBM, 4 = Damaged or significantly damaged friable miscellaneous ACBM, 5 = ACBM with potential for damage, 6 = ACBM with potential for significant damage, 7 = Any remaining friable ACBM or friable suspected ACBM

Reinspection Form I (A) - List of ACM Asbestos-Containing Materials

School New Milford Building John Pettibone Date(s) of Original AHERA Inspection 1990

Homogeneous sampling areas		Material Category	Friability	Condition category (1-7)	Recorded locations	Response actions taken/renovations/other comments
Sample number	Material description					
None collected	H1 ceiling tiles associated with five labs	TSI Surf. <u>MISC.</u>	F <u>NF</u>	5	Vice Principals office & guidance offices, foyer 2 nd building entrance	
		TSI Surf. <u>MISC.</u>	F <u>NF</u>	5	and hallway between Cafeteria & gym (1962 building entrance Foyer ceiling)	
		TSI Surf. <u>MISC.</u>	F <u>NF</u>	5	Rooms 21, 22-30	
	Air-cell pipe insulation	TSI Surf. <u>MISC.</u>	F <u>NF</u>	5	1955 Tunnel-50' from blue access door located in boiler room	
	Asphaltic paper vapor barrier	TSI Surf. <u>MISC.</u>	F <u>NF</u>	5	1955 Tunnels, applied to concrete ceilings	
	ceiling glue daubs	TSI Surf. <u>MISC.</u>	F <u>NF</u>	5	closet storage area across hall from Rm 26	

Information abstracted by Dominick Fiore Date Jan 18/20, 2005

Friability: F = friable, NF = nonfriable

AHERA assessment category: 1 = Damaged or significantly damaged TSI ACBM, 2 = Damaged friable surfacing ACBM, 3 = Significantly damaged friable surfacing ACBM, 4 = Damaged or significantly damaged friable miscellaneous ACBM, 5 = ACBM with potential for damage, 6 = ACBM with potential for significant damage, 7 = Any remaining friable ACBM or friable suspected ACBM

Reinspection Form I (A) - List of ACM Asbestos-Containing Mater

School New Milford

Building John Kettibone

Date(s) of Original AIIRA Inspection 1990

Homogeneous sampling areas		Material Category	Friability	Condition category (1-7)	Recorded locations	Response actions taken/renovations/other comments
Sample number	Material description					
None collected	Black window sill spout	TSI Surf. Misc. (circled)	F (circled) NF	5	Rm 19-16 (A&B), 18 & 20A	
	Mudded pipe fittings	TSI Surf. Misc.	F NF	5	1964 wing, storage Rm near Rm 20	
	Flexible duct connector	TSI Surf. Misc. (circled)	F (circled) NF	5	↓	
	Plaster ceiling walls & other wall systems	TSI Surf. Misc. (circled)	F (circled) NF	5	Throughout the building	
	Transite panels under exterior windows	TSI Surf. Misc. (circled)	F (circled) NF	5	↓	
		TSI Surf. Misc.	F NF			

Information abstracted by Dominick Fiore

Date Jan 18/29/2005

Friability: F = friable, NF = nonfriable

AIIRA assessment category: 1 = Damaged or significantly damaged TSI ACBM, 2 = Damaged friable surfacing ACBM, 3 = Significantly damaged friable surfacing ACBM, 4 = Damaged or significantly damaged friable miscellaneous ACBM, 5 = ACBM with potential for damage, 6 = ACBM with potential for significant damage, 7 = Any remaining friable ACBM or friable suspected ACBM

Reinspection Form 1 (B) - New Suspect Asbestos-Containing materials previously unidentified

School New Milford

Building John Pettibone

Date(s) of RE-Inspection

Jan 18/20, 2005

Homogeneous sampling areas		Material Category	Quantity (SF/LF)	Friability	Assessment category (1-7)	Recorded locations of material for each assessment category	Asbestos Content (%)
Sample number	Material description						
None collected	Pipe insulation/Fittings above lay m ceiling tile	TSI Surf. Misc.	125 LF	F NF	5	Main office hallway by Principals office, copier rm, hallway outside Rm 31633, Teleby 10	assumed
	Mixed Fiberglass Insulation	TSI Surf. Misc.	150 SF	F NF	5	Throughout school with walls/pipe chases etc (62 classrooms)	
	9" x 9" Floor tile and mastic	TSI Surf. Misc.	35,000 SF	F NF	5	Throughout school/corridors areas	
	Sink undercoating	TSI Surf. Misc.	18 Sinks	F NF	5	Classrooms 1-9 21-30	
	Blackboard & Tackboard adhesive	TSI Surf. Misc.	15000 SF	F NF	5	Throughout school	
		TSI Surf. Misc.		F NF			

Inspected by Dominick Fiore

Date Jan 18/20, 2005

Friability: F = friable, NF = nonfriable

AHERA assessment category: 1 = Damaged or significantly damaged TSI ACBM, 2 = Damaged friable surfacing ACBM, 3 = Significantly damaged friable surfacing ACBM, 4 = Damaged or significantly damaged friable miscellaneous ACBM, 5 = ACBM with potential for damage, 6 = ACBM with potential for significant damage, 7 = Any remaining friable ACBM or friable suspected ACBM

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford
 Building John Pettibone
 Homogeneous Sampling Area: Material Description Misc Possible Vapor Barrier
 ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS			
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule	
						Begin	Complete
Gymnasium under wood Floor	3000 SF	F NF	5	Miscellaneous material with potential for gouging	OPM	Continuing	
		F NF					
		F NF					

Were additional samples of this ACBM collected? Yes No

Date of Management Planner review: 1/28/05

Management Planner name: Matthew Myers
 Management Planner signature: [Signature]
 Accreditation #/State: 000094/CT
 Expiration date: 04-30-05

Inspectors name: Dominick Fiore
 Inspector signature: Dominick Fiore
 Accreditation #/State: 000299/CT
 Expiration date: 04-30-05

I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford Building John Pettibone Date(s) of Reinspection Jan 18/20, 2005

Homogeneous Sampling Area: Material Description Misc Ceramic tile adhesive ID Number 87002

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
All bathrooms, wherever ceramic tile is found	4,000 SE	F NF	5	Miscellaneous material with a potential for damage	OTM	Continuing
		F NF				
		F NF				
Were additional samples of this ACBM collected? Yes <input type="radio"/> No <input checked="" type="radio"/>				Date of Management Planner review: <u>1/28/05</u>		
Inspectors name <u>Dominick Fiore</u>				Management Planner name <u>Matthew Yeas</u>		
Inspector signature <u>Dominick Fiore</u>				Management Planner signature <u>Matthew Yeas</u>		
Accreditation #/State <u>000299/CT</u>				Accreditation #/State <u>00094/CT</u>		
Expiration date <u>04-30-05</u>				Expiration date <u>04-30-05</u>		
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

Page 1 of 1

School New Milford Building John Pettibone

Date(s) of Reinspection Jan 18/20/2005

Homogeneous Sampling Area: Material Description TSI Pipe Insulation
SP in Hvy

ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
Throughout school, especially within walls and pipechases (bathrooms)	600LF (estimate)	(F) NF	5	Thermal system insulation with a potential for water & concrete damage	OM	Continues
Main office hallway by principal's office	95 LF	(F) NF				
copier Rm, toilet by 10						
Hallway outside Rm 31833	30 LF	(F) NF				
1955 Tunnel - 50' from boiler Rm blue access door.						

Were additional samples of this ACBM collected? Yes No

Date of Management Planner review: 1/28/05

Inspectors name Dominick Fiore
 Inspector signature Dominick Fiore
 Accreditation #/State 000299/CT
 Expiration date 04-30-05

Management Planner name Matthew Myers
 Management Planner signature Matthew Myers
 Accreditation #/State 000041/CT
 Expiration date 04-30-05

I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford Building John Pettibone Date(s) of Reinspection Jan 18/20 2005

Homogeneous Sampling Area: Material Description Misc 9" x 9" Floor Tile & Ma-Stic/including under carpet ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
Main office wait Rm and storage closets by Principal's office custodian closet by Rm 3 book storage Rm across main office, storage Rm by Rm 29d	35,000 SF (total)	F NF	5	Miscellaneous material with a potential for contact damage by water	Q7M	continuing
Custodial closets by Rm 5 26 & 27		F NF				
Throop photo school under carpeted areas		F NF				

Were additional samples of this ACBM collected? Yes No

Date of Management Planner review: 1/28/05

Management Planner name Matthew Myers

Management Planner signature Matthew Myers

Accreditation #/State 000041/CT

Expiration date 04-30-05

Inspectors name Dominick Fiore

Inspector signature Dominick Fiore

Accreditation #/State 000299/CT

Expiration date 04-30-05

I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford

Building John Pettibone

Date(s) of Reinspection Jan 18/20, 2005

Misc

Homogeneous Sampling Area: Material Description 1x1 ceiling tiles & associated glue tabs

ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS			
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Begin	Complete
Vice Principals office & guidance offices, foyer entrance between gymnasium & cafe.	15,000 SF (600)	F (NF)	S	Miscellaneous material w/ a potential for contact sample	ODM	Continued	
Rms 21-30, 33		F (NF)	↓				
1962 Foyers, closet storage area across hall from Rm 26		F (NF)	↓				
Were additional samples of this ACBM collected? Yes <input type="radio"/> No <input checked="" type="radio"/>				Date of Management Planner review: <u>1/18/05</u>			
Inspectors name <u>Dominick Fiore</u>				Management Planner name <u>Matthew Myers</u>			
Inspector signature <u>Dominick Fiore</u>				Management Planner signature <u>Matthew Myers</u>			
Accreditation #/State <u>000299/CT</u>				Accreditation #/State <u>000041/CT</u>			
Expiration date <u>04-30-05</u>				Expiration date <u>04-30-05</u>			
I, the LEA's Designated Person, have read and understood the recommendations made above:						Date: _____	

Reinspection Form 2, Reinspection of ACBM: Findings and Management Planner Recommendations

Page 1 of 1

School New Milford

Building John Pettibone

Date(s) of Reinspection Jan 18/20, 2005

Homogeneous Sampling Area: Material Description Misc Asphaltic vapor barrier

ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
1755 Pipe tunnels applied to concrete ceilings	5000 SF	F NF	5	Miscellaneous materials with potential for contact sample	OPM	Continuing
		F NF				
		F NF				
Were additional samples of this ACBM collected? Yes <input type="radio"/> No <input checked="" type="radio"/>						Date of Management Planner review: <u>1/28/05</u>
Inspectors name <u>Dominick Fiore</u>						Management Planner name <u>Matthew Myers</u>
Inspector signature <u>Dominick Fiore</u>						Management Planner signature <u>Matthew Myers</u>
Accreditation #/State <u>000299/CT</u>						Accreditation #/State <u>000041/CT</u>
Expiration date <u>04-30-05</u>						Expiration date <u>04-30-05</u>
I, the LEA's Designated Person, have read and understood the recommendations made above:						Date: _____

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

Page 1 of 1
 Date(s) of Reinspection Jan 18/20, 2005

School New Milford

Building John Pettibone

Misc: Black window sills and front of master

Homogeneous Sampling Area: Material Description front of master ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
Rms 10-16A/B 18620A	500 SF	F NF	5	Miscellaneous material with a potential for contact damage	OTM	Continuing
		F NF				
		F NF				

Were additional samples of this ACBM collected? Yes No

Date of Management Planner review: 1/28/05

Management Planner name Matthew Myers

Management Planner signature Matthew Myers

Accreditation #/State 000041/CT

Expiration date 04-30-05

Inspectors name Dominick Fiore

Inspector signature Dominick Fiore

Accreditation #/State 000299/CT

Expiration date 04-30-05

I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford

Building John Pettibone

Date(s) of Reinspection Jan 18/20, 2025

Homogeneous Sampling Area: Material Description TSI Mulsed Pipe Fittings

ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
1964 wing, storage Rm near Rm 20	5	F NF	5	Thermal system insulation with a potential for water and contact damage	OPM	continuing
Throughout school with walls/pipe chases also in bathrooms	750	F NF	↓	↓		
Were additional samples of this ACBM collected? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>						
Inspectors name <u>Dominick Fiore</u>				Date of Management Planner review: <u>1/28/25</u>		
Inspector signature <u>Dominick Fiore</u>				Management Planner name <u>Matthew Myers</u>		
Accreditation #/State <u>000297/CT</u>				Management Planner signature <u>[Signature]</u>		
Expiration date <u>04-30-25</u>				Accreditation #/State <u>000041/CT</u>		
				Expiration date <u>04-30-05</u>		

I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford Building John Pettibone Page 1 of 1
 Date(s) of Reinspection Jan 18/20 2005

Homogeneous Sampling Area: Material Description Misc: Flexible duct connectors ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
1964 Wing, Storage Rm near Rm 20	20 SF	F NF	5	Miscellaneous material with a potential for contact damage	OPM	Conting
		F NF				
		F NF				

Were additional samples of this ACBM collected? Yes No

Date of Management Planner review: 1/28/05

Management Planner name Matthew Myers

Management Planner signature [Signature]

Accreditation #/State 000041/CT

Expiration date 04-30-05

Inspectors name Dominick Fiore

Inspector signature Dominick Fiore

Accreditation #/State 000299/CT

Expiration date 04-30-05

I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford

Date(s) of Reinspection Jan 18/20, 2005

Building John Pettibone

Homogeneous Sampling Area: Material Description Surf: Plaster ceilings/walls and all other wall systems

ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
Through out the bldg (1762 & 1758 sections)	10,000 SF	F NF	5	Surface material with potential for contact water damage	ORM	continuing
		F NF				
		F NF				

Were additional samples of this ACBM collected? Yes No

Inspectors name Dominick Fiore

Inspector signature Dominick Fiore

Accreditation #/State 000299/CT

Expiration date 04-30-05

Date of Management Planner review: 1/28/05

Management Planner name Matthew Myers

Management Planner signature Matthew Myers

Accreditation #/State 000041/CT

Expiration date 04-30-05

I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____

Reinspection Form 2, Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford Page 1 of 1

Building John Pettibone Date(s) of Reinspections Jan 18/20, 2005

Homogeneous Sampling Area: Material Description Misc Transite Panels under exterior windows ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
		F NF				Begin Complete
Throughout bldg	1999 SF	F NF	5	Miscellaneous material with potential for damage	ORM	continuing
		F NF				
		F NF				

Were additional samples of this ACBM collected? Yes No

Date of Management Planner review: 1/28/05
 Management Planner name: Matthew Ayers
 Management Planner signature: [Signature]
 Accreditation #/State: 000041/CT
 Expiration date: 04-30-05

Inspectors name: Dominick Fiore
 Inspector signature: [Signature]
 Accreditation #/State: 1000297/CT
 Expiration date: 04-30-05

I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____

Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford Page 1 of 1
 Date(s) of Reinspection Jan 18, 22, 2005
 Building John Petalbone
 Homogeneous Sampling Area: Material Description Misc Sink under cavity ID Number _____

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
RMS 1-7 & 21-30	18 SINKS	F NF	5	Miscellaneous material with 2 potential for contact sample	OTM	Continuing
Were additional samples of this ACBM collected? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>						
Inspectors name <u>Dominick Fiore</u> Inspector signature <u>Dominick Fiore</u> Accreditation #/State <u>000297 / CT</u> Expiration date <u>04-30-05</u>						
Date of Management Planner review: <u>1/28/05</u> Management Planner name <u>Matthew Myers</u> Management Planner signature <u>Matthew Myers</u> Accreditation #/State <u>000044 / CT</u> Expiration date <u>04-30-05</u>						

I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____

Reinspection Form 2, Reinspection of ACBM: Findings and Management Planner Recommendations

School New Milford

Building John Pettibone

Date(s) of Reinspection Jan 18, 20, 2005

Homogeneous Sampling Area: Material Description Misc. Blackboard/Talkboard adhesive

ADHESIVE

REINSPECTION FINDINGS FOR ACBM				MANAGEMENT PLANNER RECOMMENDATIONS		
Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7)	Assessment	Preventive measures	Schedule
						Begin Complete
Throughout School	15,000 SF	F NF	5	Miscellaneous materials with 2 paint in for sample	09m	Century
		F NF				
		F NF				
Were additional samples of this ACBM collected? Yes <input type="radio"/> No <input checked="" type="radio"/>						
Inspectors name <u>Dominick Fiore</u>						
Inspector signature <u>Dominick Fiore</u>						
Accreditation #/State <u>000299 / CT</u>						
Expiration date <u>04-30-05</u>						
Date of Management Planner review: <u>1/28/05</u>						
Management Planner name <u>Matthew Myers</u>						
Management Planner signature <u>Matthew Myers</u>						
Accreditation #/State <u>000341 / CT</u>						
Expiration date <u>04-30-05</u>						
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, Page 1 of 3

Facility Address: John Pettibone Elementary School
New Milford, CT

Date of Surveillance: _____

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Vapor barrier under wood floor	Gymnasium					
Ceramic tile adhesive/grout	All bathrooms					
Pipe & pipe fitting insulation	Throughout school, especially within walls and pipe chases, main office hallway by principal's office, copier room, hallway outside rooms 31 and 33, bathrooms by room 10, pipe tunnel 1955 section under concrete floor 50 feet from blue access door					
9"x9" floor tile and mastic including under carpet	Main office, vault room and storage closets by principal's office, custodian's closet by Rooms 3, 26 & 29, book storage room across main office. All carpeted areas of the school					
12"x12" ceiling tiles and glue daubs	Vice principal's office and guidance offices, foyer entrance between gymnasium and cafeteria, rooms 21-30, 1962 foyers, closet storage room across the hall from room 26.					

Conditions: G = Good, D = Damaged, SD = Significant damage

Surveillance conducted by: _____ (Print)

 (Signature)

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools Page 2 of 3

Facility Address: John Pettibone Elementary School
New Milford, CT

Date of Surveillance: _____

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Black window sills including grout and mastic	Rooms 10-16 A & B, rooms 18 & 20A					
Asphaltic vapor barrier	1955 tunnels applied to concrete ceiling					
Pipe fitting insulation	1964 wing storage room near room 20, throughout school within walls/ pipe chases					
Flexible duct connectors	1964 wing storage room near room 20					
Plaster ceilings/ walls and all other wall systems	Throughout the building (1962 & 1968 sections)					

Conditions: G = Good, D= Damaged, SD = Significant damage

Surveillance conducted by: _____ (Print)

 (Signature)

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, Page 3 of 3

Facility Address: John Pettibone Elementary School
New Milford, CT

Date of Surveillance: _____

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Transite panels under window systems	Throughout building					
Sink undercoating	Rooms 1-9 and 21-30					
Blackboard/ tackboard adhesive	Throughout building					

Surveillance conducted by: _____
 (Print)

 (Signature)

PREVENTIVE MEASURES FOR VARIOUS ASBESTOS-CONTAINING MATERIALS

A. SURFACING MATERIALS

“Surfacing Materials” means materials in a school building that are sprayed-on, troweled-on, or otherwise applied to surfaces. These include sprayed-on fireproofing materials on structural members, ceiling and wall plasters, or other materials applied to surfaces for acoustical, fireproofing, or other purposes.

Surfacing Materials are generally considered friable and can release asbestos fibers if damaged by impact, air erosion, vibration, and/or water intrusion. The following procedures, when properly implemented, will reduce the potential for fiber release:

1. Sprayed-on fire-proofing

- a) Identify the materials and post warning signs on the laid-in or glued-in ceiling tile. If the decking is not covered, place the sign on the wall.
- b) Maintain the materials in intact state and undamaged condition. During winter, pigeons, squirrels and other rodents tend to roost in boiler/machine rooms and dislodge sprayed-on fireproofing on the decking. Prevent such possibilities.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, enclosure is a temporary solution. Encapsulation of damaged sprayed-on fireproofing material is not recommended.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Ceiling and wall plaster

- a) Identify the materials and post warning signs.
- b) Maintain the materials in intact state and undamaged condition. Avoid storing/stacking on/near the materials to reduce contact damage.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, repair or enclosure is a temporary solution.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials.

B. THERMAL SYSTEM INSULATION (TSI)

“Thermal System Insulation (TSI)” means insulating materials applied to pipes, pipe fittings, boilers, breechings, tanks, ducts, or other components to prevent process heat loss or gain, water condensation, or for other purposes (e.g., fire door insulation core).

TSI are generally considered friable asbestos-containing materials. This means they can be easily damaged, increasing the potential for fiber release. The following procedures, when properly implemented, will reduce the potential for fiber release:

1. Boiler and breeching insulation

- a) Identify the locations and label the boiler. Warning signs should be posted outside the boiler room.
- b) Reduce the likelihood of fiber release by ensuring that the insulation is not damaged. Avoid storing/stacking on/near the boiler to reduce contact damage.
- c) Maintain the insulation in intact state and undamaged condition. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Pipe, pipe-fittings, tank and duct insulation

- a) Identify the locations and label the materials. Warning signs should be posted outside of rooms that have TSI materials.
- b) Reduce the likelihood of fiber release by ensuring that the materials are not damaged. Avoid storing/stacking near the materials to reduce contact damage.
- c) Maintain all TSI materials in intact state and undamaged condition. Inspect the protective jackets for damage. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

3. Fire door

- a) Identify the locations and label the materials.
- b) Since there may be a number of different types of fire doors throughout a building, fire door cores must be considered to have asbestos-containing interior insulation unless sample result prove otherwise. Prior to performing any maintenance on any door (lock change, drilling, etc.), the door should be surveyed by qualified personnel to rule out the existence of an asbestos core.
- c) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

C. MISCELLANEOUS MATERIALS

“Miscellaneous Materials” are all other asbestos-containing materials in a school building that do not fall under the categories of Surfacing Materials or TSI. These include floor tiles, floor tile and carpet mastic, gypsum wallboard and joint compound, ceiling tiles, glue daubs, transite panels, laboratory counter tops, wall base and associated glue, window caulking and glazing compounds etc. The following maintenance procedures are recommended for these materials:

1. Vinyl Asbestos Floor Tiles (VAT)

Vinyl Asbestos Floor Tiles (VAT) are considered non-friable, however routine maintenance procedures such as spray-buffing, burnishing, wet scrubbing, and stripping can generate asbestos fibers. Following procedures, when properly implemented, will reduce the potential of fiber release:

- a) Do not sand, grind or abrade the tiles. Stripping of VAT should be done as infrequently as possible. When stripping becomes necessary, follow the appropriate work practices. Never perform dry stripping.
- b) During spray-buffing or burnishing the floor, operate the machine at the lowest workable speed and use the least abrasive pad. Use a wet mop for routine cleaning whenever possible.
- c) Routinely check whether chair and desk glides are in good condition and replace when necessary. Worn glides can gouge the floor and cause fiber release.
- d) Place carpets/floor mats in all entrances to reduce abrasion of floor tiles by sand and pebbles. During winter, have parking lots and walkways swept to the extent possible to avoid the tracking of salt and ice-melting compounds into the school by the students.
- e) Train the custodial people who are responsible for care and maintenance of VAT. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Gypsum wallboard and joint compound assembly

- a) Since there may exist a number of different homogeneous assemblies in a building, all sheetrock/joint compound must be assumed to be ACBM unless sample result prove otherwise. If any specific areas are going to be disturbed, the material in that area should be sampled.
- b) Reduce the likelihood of fiber release by avoiding cutting or drilling holes through the sheetrock panels.

3. Ceiling Tile and Glue Daubs

- a) Reduce the likelihood of fiber release by limiting access to the area above the ceiling tiles. Maintain the ceiling tiles in undamaged condition. Replace any damaged or water-stained tile.
- b) If the ceiling tiles are negative for asbestos, sample and analyze the glue daubs to ascertain whether these are asbestos-containing before the tiles are replaced.

4. Transite Panels, Laboratory Counter Tops, Window Caulking and Glazing Compounds

- a) Reduce the likelihood of fiber release.
- b) Maintain transite panels, lab tabletops and window caulking and glazing compounds in undamaged condition.

5. Carpet Glue, Blackboard/ Tack Board Glue, Sink Undercoating, Floor Tile Mastic, Baseboard and Mastic

- a) Reduce the likelihood of fiber release by leaving base cove and carpets in place.
- b) Maintain carpets and base cove in good condition. Sample and analyze the glue and the mastic to ascertain whether these are asbestos-containing if the renovation activities are going to impact the carpet and the baseboard.

There are general work practices which apply to all schools in the school system.

1. Vinyl Asbestos Floor Tile (VAT). In many cases, the surface of the tile may appear abraded. Often, custodial employees will use abrasives to clean floor surfaces prior to the application of floor wax. This practice should be strongly discouraged, as it wears away the top surface, exposing the underlying matrix which may contain asbestos. Where a dull white finish is observed through the top surface of the tile, it indicates that damage to the tile has occurred.
2. Hammering or drilling through floor tile to fasten carpeting or other materials should be prohibited.
3. Chairs and desks should be equipped with rubber feet or gliders to reduce damage to the floor tile surfaces.
4. Efforts should be made to minimize storage of maintenance supplies in the portions of the boiler rooms nearby boilers, breeching, headers, or other areas which might be damaged. This applies specifically to items such as ladders, chairs, desks, and other large items which might damage the surface.
5. The storage of desks, chairs, and other school supplies in pipe tunnels or chases where there is ACM should be discouraged. In addition to limiting access, movement of these items may cause damage to the surface.
6. Where ladders are required in areas where thermal system ACBM has been documented, hinge-type ladders should be used if possible. Custodial employees are discouraged from leaning extension ladders against boilers, breeching, or headers.

Boiler Rooms often have asbestos containing materials such as pipe insulation, pipe fitting insulation, tank insulation, boiler insulation, firebrick, gaskets, spray applied fireproofing and wall and ceiling plaster. Damage to these materials can be caused by contact forces (ladders and equipment hitting the materials), water (leaks in boilers, pipes and tanks) and vibration forces. All personnel (custodians, maintenance, and outside contractors) entering boiler rooms must be made aware of the asbestos containing materials and exercise caution as to not damage or disturb these materials. The boilers are typically serviced by an outside boiler contractor. The routine maintenance activities must not disturb the asbestos containing materials. The designated person should be notified if planned work or routine maintenance may disturb the asbestos containing materials. The appropriate response action (removal, etc.) will be selected by a licensed management planner and project designer and performed by properly trained personnel prior to routine non-asbestos maintenance work beginning.

Tunnels and crawl spaces often have asbestos containing pipe and/or pipe fitting insulation throughout. Sometimes asbestos containing tank insulation, duct insulation and transite are also found in these areas. The area should be restricted to persons with sixteen-hour training and respiratory protection at a minimum if the insulation is in damaged condition. All damaged areas should be repaired and a clearance air test passed prior to occupancy by custodial staff or outside Contractors. Persons entering a tunnel and/or crawl space must be made aware of the types of asbestos containing materials in these areas and exercise extreme caution as to not damage these materials.

Asbestos containing spray applied fireproofing can often be found on metal I-beams above ceilings and behind walls in many schools. This material is a very friable and usually is also found on adjacent ceiling decks, piping and mechanical systems, etc. (over-spray) because of the method of original installation. The fireproofing is often not hidden behind walls or ceilings in mechanical and boiler rooms. Sometimes this material becomes dislodged (age, delamination, air plenum wind forces and gravity) and lands on drop, sheetrock or plaster ceilings. Caution should be exercised if someone has to do work above the ceilings or when replacing a specific section of a ceiling. Schools with common return air plenums have additional concerns of delaminating fireproofing and subsequent asbestos fiber release into the return air. The designated person and a licensed asbestos management planner and project designer should be notified if work involves disturbance of the ceiling or areas above the ceiling. The project designer should develop standard operating procedures and a project design is its found that exposure is possible through activities such as popping ceiling tiles, routine repair or maintenance activities above the lower ceilings or work involving the disturbance of the material directly (example – installing ducts, pipes, ceilings, computer lines, etc – scraping areas to hang product).

Asbestos containing ceiling tiles can be found in school buildings. These tiles are often covering older ceiling materials such as plaster or sheetrock and are **typically 2x4', 2x2' and 1x1'** in size. They are either supported by a metal grid system (drop ceiling), concealed spline, or glued in place. Special considerations must be given for glue adhered ceilings. The ceiling tile, glue daub and ceiling above (plaster, etc.) must all be considered as asbestos containing even if

one is found not to contain asbestos. The ceiling tile is adhered to the glue daub that is adhered to the ceiling above and they usually can not be separated. A licensed asbestos abatement contractor should remove ceiling tiles that are within reach of building occupants and have a history of damage. Ceiling tiles that are “popped” on occasion to access areas above (for routine maintenance activities and due to small amounts of water damage) should be replaced with non-asbestos tiles or the potential for exposure should be examined through air testing in conjunction with a test containment. A licensed project designer should design a method for routine activities (portable pop-up containment, water, hepa-vac, respiratory protection, sixteen hour training, etc.). Asbestos containing ceiling tiles should be removed if work activity involves “popping” more than a few tiles. Running new computer lines, telecommunication systems, security systems, piping for sprinklers, large roof leaks, etc. all typically required moving many ceiling tiles throughout the school, therefore a licensed abatement contractor should remove the tiles prior to work by other contractors. Custodians, maintenance staff and outside contractors should be made aware of the locations of the asbestos containing ceiling tiles and in house work practices pertaining to them.

Asbestos containing pipe and/or pipe fitting insulation, duct insulation (commonly within reach in incinerator rooms, mechanical and air handling rooms and above ceilings in kitchens) **roof drain insulation and vibration isolation cloth** (on sections of metal ducts) are often located in chases, behind walls and above ceilings. Sometimes these materials are within reach of all building occupants (located below the ceilings in classrooms, corridors, stages, stairwells, etc.). Custodians, maintenance staff and contractors should be made aware of the presence of these materials. Persons working in these areas must exercise caution and not damage these materials. These asbestos containing materials should be removed or enclosed if they are within reach of most building occupants and damage has occurred in the past.

Asbestos containing hard and soft acoustical wall and ceiling plaster can exist throughout a building (corridors, classrooms, etc.) or only in limited areas such as a boiler room, auditorium, pool, etc. Asbestos containing hard plaster typically does not pose a threat to human health and safety unless deliberately disturbed. Activities such as drilling holes to run or hang wires and pipes, demolition of interior walls during renovation, removing glue daubs from plaster and water leaks can damage the material and result in a release of airborne asbestos fibers. Asbestos containing soft plaster can be damaged from the activities described above as well as contact damage from simply toughing the material. Asbestos containing fibers from soft plaster are dislodged from the light contact forces such as poking the materials with ones hand, pencils, pens, etc. Soft plaster should be removed immediately if it's located within reach of students (low ceiling in an auditorium, etc.). Outside contractors, custodial and maintenance staff must be made aware of the location of asbestos containing plaster and informed to avoid work practices that may disturb this material. The designed person and a licensed management planner and project designer should select the response action required if planner work activities anticipate disturbance of the asbestos containing plaster.

Asbestos containing 9x9” and 12x12” floor tiles and underlying mastic are common throughout school buildings. It shall be assumed that all areas with carpeting have floor tile and mastic located below carpet unless the floor tiles and mastic were abated prior to the installation of the carpet. Custodians, maintenance staff and contractors other than licensed asbestos abatement contractors shall not be permitted to remove carpeting unless the floor tiles are not disturbed in the process (stay intact adhered to the sub-flooring). Areas with “newer” non-asbestos containing floor tiles shall be assumed to have a lower layer of asbestos containing floor tile and/or flooring mastic adhered to the underneath unless both the older tile and underlying mastic were abated prior to the installation of the newer tile and mastic. The “newer” tile must be considered an asbestos containing material if asbestos containing floor tile and/or mastic is adhered to the bottom of it. Floor tiles are typically not damaged unless they are losing adhesion to the substrate due to adhesion failure, age and water damage or through improper maintenance or work activities. The designated person shall be contacted if adhesion failure, are and/or water damage has occurred or if renovation work will disturb the material (drilling for pipe insulation, etc.). A licensed management planner will select the proper response action and a project designer will create a design if abatement is required. Maintenance activities should be standardized and training required in order to minimize possible fiber release during routine floor maintenance. OSHA requires the following:

- a) Sanding of floors is prohibited
- ii) Stripping of finishes shall be conducted using low abrasion pads at speed lower than 300 rpm and wet methods.
- iii) Burnishing or dry buffing may be performed only on flooring which had sufficient finish so that the pad cannot contact the flooring material.

Some additional work practices are listed below:

- i) Stripping of floor coverings should be done as infrequently as possible (ex-annually)
- ii) Follow manufactures instructions and never perform dry stripping. Always use the least abrasive pad when stripping.
- iii) Sealing floors should be done through applying sever thin coats of high percentage solids finish.
- iv) Use the lowest rates of speed and least abrasive pads when spray-buffing or dry-burnishing floors
- v) Install floor matting at entrances (16-24 feet).

Asbestos containing materials in fire doors is typically inaccessible. These materials are often found in boiler and mechanical room doors as well as auditorium, library, café, kitchen and exterior doors. Sometimes these materials are also located in common doors used for classrooms, corridors, etc. Samples taken from any one door may not be representative of other doors in the facility. Prior to performing any maintenance or replacement of any door (lock changes, planning, sanding, drilling, removal, etc.) the designated person should be notified and the specific door should be sampled by a licensed asbestos inspector. A licensed project designer

will design the work procedures to be used for a specific work activity if the door materials are found to contain asbestos.

Asbestos containing electrical insulation is common in auditorium/stage light trays and as “pigtailed” on spotlights. This material is often white and contains a high percentage of asbestos. Many schools also have these light trays and pigtailed in storage or lying around the stage area. This material should be removed if no longer in use. The lighting insulation still in use should be removed and replaced if contact damage is likely. Black insulated wire and gray or black electrical box lining (paper like) sometimes contain asbestos. Custodians, maintenance staff, outside contractors, and parties (students, etc.) responsible for operating lighting with this insulation should be made aware of this material and practice work procedures that will not disturb it.

Many different mastics, glues and adhesives can contain asbestos. Common forms of these materials are carpet glue, flooring mastics (under tile, sheet flooring, linoleum and wood floors (gym)), ceramic tile adhesive, baseboard adhesive, ceiling and wall tile glue, daubs, chalkboard and bulletin board adhesives, etc. These materials are sometimes adhered to non-asbestos containing materials. These non-asbestos containing materials must be considered as asbestos containing because the mastic, glue or adhesive usually can not be separated from them. The custodians, maintenance staff and outside contractors must be made aware of any asbestos containing mastics, glues and adhesives prior to conducting activities that may disturb them. A licensed asbestos inspector must sample materials previously not analyzed for asbestos content prior to work activities that will disturb them. Only a licensed asbestos abatement contractor can remove asbestos containing materials (greater than 3 feet) and asbestos or non-asbestos containing materials bonded to them.

Sheetrock, taping/joint compound, wallboard, vinyl or sheet flooring and countertops, laboratory countertops and laboratory hoods can contain asbestos. **Transite board** is another common building product that contains asbestos. This material is typically found behind radiators, on exterior soffits, in laboratory products (tables, piping, hoods and exhaust ductwork) and on walls or ceilings. These materials are typically not a threat to human health and safety unless deliberately disturbed. Puncturing walls and ceilings, sawing countertops and laboratory hoods, etc. can release asbestos fibers into the air. Custodians, maintenance staff, and outside contractors must be made aware of these possible asbestos containing products and avoid work that will disturb them.

Exterior materials may also contain asbestos. **Roofing and flashing materials, door and window caulking and glazing, soffits, entrance eaves and overhangs, covered walkways, etc.** may have asbestos containing materials. These materials must be sampled prior to their disturbance in order to determine the appropriate removal techniques and disposal requirements. Covered walkways and overhangs must be assumed to contain asbestos unless bulk sample results prove otherwise.

Some building materials may be found to contain less than one percent asbestos and therefore are not regulated by the federal or state asbestos regulations. However, demolition or renovation activities that disturb these materials can create possible OSHA violations if the PEL (permissible exposure limit) or (exposure limit) is exceeded. Plaster and ceiling tiles (containing less than one percent asbestos) undergoing demolition can exceed OSHA's standards as well as the State of Connecticut Re-occupancy Criteria. These building materials should be removed either as an asbestos containing material or under a semi-controlled environment (ex. – use a significant amount of water during demolition of the ceiling or wall in conjunction with air testing) to control possible airborne exposures to asbestos.

Newer building materials may also contain greater than one percent asbestos. Building additions, portable classrooms and building products installed during renovations after 1980 have occasionally been found to contain asbestos. Floor tiles and mastics, adhesives and glues, wall and ceiling materials, roofing materials, etc. should be sampled prior to performing activities that will disturb them. Sampling can be avoided if the building architect signs a statement that the building materials do not contain asbestos or MSD sheets prove the corresponding materials are not asbestos containing.

Y:\WORD\Projects\04\04-542.10 3yr-AHERA Pettibone.doc

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT
THE INDIVIDUAL NAMED BELOW IS LICENSED
BY THIS DEPARTMENT AS A

ASBESTOS CONSULTANT - INSPECTOR

DOMINICK FIORE

LICENSE NO.
000299
CURRENT THROUGH
04/30/06
VALIDATION NO.
03-144247

Dominick Fiore
SIGNATURE

J Robert Galvin M.D., M.P.H.
COMMISSIONER

EnviroScience Consultants, Inc.

795 North Mountain Road, Newington, CT 06111 – (860) 953-2700

This is to certify that

Dominick Fiore

3 Ivy Lane, Shelton, CT 06484
SS# 042-74-1243

has successfully completed the
4 Hr. Asbestos Inspector Refresher
Asbestos Accreditation under TSCA Title II
40 CFR Part 763

Frank Mills
Principal Instructor

September 21, 2004
Date of Course

September 21, 2004: A-
Examination Date & Grade

Wesley

Training Manager

AI-R-9/04-9

Certificate Number

September 21, 2005
Expiration Date



Certificate of Training

Awarded to

Dominick Fiore
042-74-1243 (DOB 4/27/67)

For successful completion of a 24 Hour, 3 Day
Asbestos Building Inspector
Initial Training Course
October 20 - 22, 1997

Required by OSHA and the EPA Revised MAP
for accreditation under the TSCA Title II
as self-certified by Trainer 4/4/94

Presented by

Mystic Air Quality Consultants, Inc.
1204 North Road, Groton, Connecticut

Expiration Date: 10/22/98


Exam Grade: 97%

Exam Date: 10/22/97

Certificate Number: 353 AIC

Christopher J. Eident, CIH, CSP, RS

George Williamson, Training Director



Concentra Medical Centers (CT)

32 Strawberry Hill Ct STAMFORD, CT 06902
Phone: (203) 325-7889 Fax: (203) 325-7977

PLHCP¹ WRITTEN STATEMENT for RESPIRATORS (EMPLOYEE)

Service Date: 03/22/2005

Employee SSN: 042-74-1243

Employee Name:

Fiore, Dominick

Address:

3 ivy Lane

SHELTON CT 06484

Employer: Enviro science

You were evaluated in this office of your medical status related to your physical capability to wear a respirator. (Check one that applies)

- There were no abnormal findings that would hamper your ability to perform your job duties while wearing a respirator.
- The abnormal findings listed below were not related to wearing a respirator but should be reported to your personal physician for further evaluation.

Based upon the results of this evaluation it is my opinion that you: (Check ALL that apply)


- ARE qualified to wear a respirator.
- Have the following restrictions concerning respirator usage: _____
- ARE NOT qualified to wear a respirator.
- Require further testing by your private physician who must submit a written report of his/her findings to Concentra Medical Centers (CT) so that a final decision on your ability to wear a respirator can be made.
- Must wear Special prescription eye-wear needed to accommodate respirator.
- Must use an Eye glass conversion kit.
- May need to shave Facial hair to assure tight seal on certain face masks.
- Need to stop smoking.

(Check ALL that apply)

- The above individual HAS been examined for respirator fitness in accordance with 29 CFR 1910.134. This limited evaluation is specific to respirator use only. Employees should be instructed to report any difficulties in using respirators or change of any physical status to their supervisor or physician. This evaluation included the Respiratory Questionnaire outlined in 29 CFR 1910.134.
- The above individual HAS NOT been examined by me for respirator fitness. The employee's medical evaluation consisted of a review of OSHA's Medical Evaluation Questionnaire in Appendix C Part A Section 2. In accordance with 29 CFR 1910.134, this limited evaluation is specific to respirator use only. Employees should be instructed to report any difficulties in using respirators or change of any physical status to their supervisor or physician. This evaluation included the Respiratory Questionnaire outlined in 29 CFR 1910.134.
- In accordance with specific OSHA requirements, I have informed the above named individual of the results of this evaluation and of any medical conditions resulting from exposures that may require further explanation or treatment. Where applicable, the above named individual has been informed of the increased risk of lung cancer attributable to the combined effect of smoking and asbestos, lead and/or other chemical exposure(s).

Respirators must be properly selected based on the containment and concentration levels to which the worker will be exposed. Failure to follow the use and fitting instruction and warnings for proper use contained on the respirator packaging and/or failure to wear the respirator during all times of exposure can reduce the respirator's effectiveness and result in sickness or death. Wearer must be trained in the proper care of any respirator. Refer to product literature and packaging for specific information regarding fit, use and/or limitations.

PLHCP Signature



LARRY MOY, MD
PLHCP Name (printed)

¹Physician or other Licensed Healthcare Professional

Dominick Fiore

Employee's Signature

3-22-06

Expiration Date

To be maintained in the employee's file with a copy to the employee

Please Give to Mike Guerra

EnviroScience Consultants, Inc.
795 North Mountain Road
Newington, CT 06111
Phone: (860) 953-2700 Fax: (860) 953-3203

QUALITATIVE FIT TEST RECORD

EMPLOYEE INFORMATION

Name: Dominick Fiore Date of Birth: 04-27-67

Date of Last Pulmonary Function Test: 03-29-04 Passed Failed

RESPIRATOR(S) FIT TESTED

Manufacturer: Noreh Wilson
Type: 1/2 Face 1/2 Face
Model: 7700-806 6000 Series
Size: Large Medium
Approval Number: 46-3692

TEST AGENT AND RESULTS OF TEST

Irritant Smoke Isoamyl Acetate Saccharin Aerosol
 Passed Failed Comments: _____

TEST ADMINISTRATOR

Name: PAT SHACKANY Date: 10-12-04
Signature: [Signature] Next Test Due Date: 10-12-05

HOME

WELCOME

AGENCY
LISTALPHA
LISTFAQ
ANSWERS

▶ BUSINESS CENTER

▶ VERIFY LICENSE

▶ QUICK CONTACTS

▶ PHYSICIAN PROFILE

Health Care or Environmental Health Professional's License Status

This site is part of **CT-clic.com**, the **Connecticut Licensing Info Center**, that links to all YOUR State licensing and registration needs.

Note: Requests for copies of documents related to past disciplinary action must be submitted in writing. Such documents are currently not available in an electronic format. Therefore, include your name, mailing address and telephone number on any request.

License Type: Asbestos Consultant - Insp/Mgmt Planner
License Number: 000041
Name: MYERS, MATTHEW A
Expiration Date: 4/30/2006
Granted Date: 12/23/1994
License Name: MATTHEW A. MYERS
License Status: Current
Disciplinary Action: None

Questions ??

E-mail webmaster.dph@po.state.ct.us or call (860) 509-7603
 Return to [DPH Licensure/Renewal Page](#)

For Business Registry Questions? Contact **Smart State** or call 1-800-392-2122.

State of Connecticut [Disclaimer](#) and [Privacy Policy](#). Copyright © 2000 State of Connecticut. [Universal Website Accessibility Policy](#) applies. For comments about this site contact the [webmaster](#)

EnviroScience Consultants, Inc.

795 North Mountain Road, Newington, CT 06111 – (860) 953-2700


This is to certify that

Matthew Myers

10 Lewis Street, Milford, CT 06460
SS# 371-80-3305

has successfully completed the

8 Hr. Asbestos Inspector/Management Planner Refresher
Asbestos Accreditation under TSCA Title II
40 CFR Part 763



Frank Mills, Principal Instructor

September 21 & 22, 2004

Date of Course

September 22, 2004: A

Examination Date & Grade



Neal Freuden, Training Manager

AMP-R-9/04-2

Certificate Number

September 22, 2005

Expiration Date

Certificate of Training

Awarded to

Dominick Fiore

042-74-1243 (DOB 4/27/67)

For successful completion of a 24 Hour, 3 Day

Asbestos Building Inspector

Initial Training Course

October 20 - 22, 1997

Required by OSHA and the EPA Revised MAP

for accreditation under the TSCA Title 11

as self-certified by Trainer 4/4/94

Presented by

Mystic Air Quality Consultants, Inc.

1204 North Road, Groton, Connecticut

Certificate Number: 353 AIC

Exam Grade: 97%

Exam Date: 10/22/97

Expiration Date: 10/22/98



Christopher J. Eident, CIH, CSP, RS



George Williamson, Training Director

Stamford Corporate Health Services
Tully Health Center
32 Strawberry Hill Court
Stamford, CT 06902
(203) 325-7389

MEDICAL LETTER OF PROOF

In accordance with the requirements of section (m) (4) (1) of the OSHA Standard, CFR 1910.120;

This is to certify that on this date 04/09/04 and in accordance with the OSHA Standard 29 CFR 1910.120, based on physical examination and spirometry testing:

NAME: Matthew Myers SOCIAL SECURITY NUMBER 371-80-3305
And based upon the findings I have determined that this individual:

() MAY use a respiratory device while performing his/her required employment functions and the results of this examination have not detected any medical condition which would place the named individual at an increased risk of material health impairment from exposure to Hazardous Materials or from use of a respirator.


() MAY NOT use a respiratory device while performing his/her required employment functions and the results of this examination have detected a medical condition which would place the named individual at an increased risk of material health impairment from exposure to Hazardous Materials or of any condition which may be affected by the use of a respirator.

In accordance with OSHA requirements, I have informed the named individual of the results of his/her medical examination and of any condition, which may be affected by the use of a respirator.

ADDITIONAL
COMMENTS: _____

Check as applicable:

The above named individual has been counseled about the increased health risks of cigarette smoking combined with Hazardous Materials exposure and has been advised to discontinue smoking and to avoid cigarette smoking in the future.

Signed: 
(Physician)

Date: 04/09/04

EnviroScience Consultants, Inc.
795 North Mountain Road
Newington, CT 06111
Phone: (860) 953-2700 Fax: (860) 953-3203

QUALITATIVE FIT TEST RECORD

EMPLOYEE INFORMATION

Name: MYERS, MATT Date of Birth: 4/7/1970

Date of Last Pulmonary Function Test: 4/04 Passed Failed

RESPIRATOR(S) FIT TESTED

Manufacturer: WILSON

Type: 1/2 FACE

Model: 6000

Size: LARGE

Approval Number: _____

TEST AGENT AND RESULTS OF TEST

Irritant Smoke Isoamyl Acetate Saccharin Aerosol

Passed Failed Comments: _____

TEST ADMINISTRATOR


Name: GARRA, MICHAEL

Date: 11/17/2004


Signature: [Signature]

Next Test Due Date: 11/17/2005

FIRE DRILLS - Close all doors and windows, lock cabinets (meds). Lock hallway door; Take all students with you out the door by the restrooms and wait on the grass. 17C



AL
Marty
Bobby



AL
Marty
Bobby