

# **Asbestos Hazard Emergency Response Act Three-Year Asbestos Re-Inspection and Management Plan Update**

for  
Northville Elementary School

For Compliance with  
State of Connecticut Department of Public Health  
Asbestos-Containing Material in Schools Regulation  
(Sections 19a - 333-1 through 19a - 333-13)  
and  
EPA Asbestos Hazard Emergency Response Act  
(Title 40 CFR, Part 763, Subpart E)

**New Milford Public Schools**  
New Milford, Connecticut

March 2020



**FUSS & O'NEILL**

56 Quarry Road  
Trumbull, CT 06611



FUSS & O'NEILL

April 23, 2020

Mr. Kevin Munrett  
Facilities Manager  
New Milford Public Schools  
386 Danbury Road  
New Milford, CT 06776

**RE: Three-Year AHERA Asbestos Re-Inspection and Management Plan Update**  
**Re-Inspection Date: March 26, 2020**  
**Northville Elementary School**  
**22 Hipp Road, New Milford, CT**  
Fuss & O'Neill Project No. 20071230.C40

Dear Mr. Munrett:

Enclosed is the three-year AHERA Asbestos Re-Inspection and Management Plan Update report prepared by Fuss & O'Neill, Inc. for Northville Elementary School located at 22 Hipp Road in New Milford, Connecticut (the "Site"). The inspection was performed for New Milford Public Schools (the "Client"). This report is an important document that must be kept on file at the school as well as at a central location where the Management Plans are maintained.

If you should have any questions regarding this report, please do not hesitate to contact me. Thank you for this opportunity to have served your environmental needs.

Sincerely,

Eduardo Miguel Marques  
Senior Environmental Analyst

EMM/nw

Enclosure

56 Quarry Road  
Trumbull, CT  
06611

t 203.374.3748  
800.286.2469  
f 203.374.4391

[www.fando.com](http://www.fando.com)

California  
Connecticut  
Maine  
Massachusetts  
New Hampshire  
Rhode Island  
Vermont

# Table of Contents

## Asbestos Hazard Emergency Response Act Three-Year Re-Inspection and Management Plan Update Northville Elementary School New Milford Public Schools

---

<b>1</b>	<b>Introduction .....</b>	<b>1</b>
1.1	Background .....	1
1.2	Local Education Agency (LEA) Responsibilities .....	1
1.3	Accreditation .....	2
<b>2</b>	<b>Building and Mechanical System Description .....</b>	<b>3</b>
<b>3</b>	<b>Three Year Re-Inspection.....</b>	<b>3</b>
3.1	Re-Inspection Procedures .....	3
<b>4</b>	<b>Re-Inspection Report.....</b>	<b>4</b>
4.1	Review of Existing Records .....	4
4.2	Re-Inspection Summary.....	4
4.3	Newly Identified or Re-sampled ACBM Materials .....	7
4.4	Physical Assessment of ACBM .....	8
<b>5</b>	<b>Management Plan Update .....</b>	<b>9</b>
5.1	Recommended Response Actions.....	9
5.2	Periodic Surveillance .....	10
5.3	Preventive Measures.....	10
5.4	Abatement (Removal) Cost Estimates .....	10
<b>6</b>	<b>EPA Accreditation Requirements .....</b>	<b>11</b>

### Appendices

End of Report

APPENDIX A	EXISTING RECORDS CHECKLIST
APPENDIX B	RE-INSPECTION FORM 1A
APPENDIX C	RE-INSPECTION FORM 1B
APPENDIX D	RE-INSPECTION FORM 2
APPENDIX E	SAMPLE 6-MONTH PERIODIC SURVEILLANCE FORM
APPENDIX F	PREVENTIVE MEASURES
APPENDIX G	ASBESTOS INSPECTOR AND MANAGEMENT PLANNER STATE LICENSES AND EPA ACCREDITATIONS

# 1 Introduction

---

## 1.1 Background

The Clean Air Act required the United States Environmental Protection Agency (EPA) to develop standards to address the potential health risks associated with adverse effects of asbestos exposure as an indoor contaminant. In October 1986, the EPA promulgated the Asbestos Hazard Emergency Response Act (AHERA) located at Title 40 CFR, Part 763, Subpart E.

The AHERA regulations required that local education agencies (LEAs) conduct inspections of each school building that they lease, own, or otherwise use as a school building to identify friable (easily crumbled or crushed to powder by hand pressure) and non-friable asbestos-containing building materials (ACBM) locations. The original inspections were required to have been completed prior to October 12, 1988.

AHERA also requires that any building leased or acquired on or after October 12, 1988 that is to be used as a school building shall be inspected for friable and non-friable ACBM prior to use as a school building. In the event of an emergency use of a building that has not been inspected for ACBM, the building shall be inspected within 30 days after commencement of such use.

The regulatory requirements remain in effect for private or public school systems, a church-affiliated school of any denomination, a school dedicated to the education of children with special needs, or a charter school. In the State of Connecticut, the Department of Public Health (CTDPH) is responsible for AHERA regulation enforcement.

---

## 1.2 Local Education Agency (LEA) Responsibilities

- A. The LEA is responsible for compliance with the AHERA regulation. The following responsibilities must be followed:
1. The LEA must designate a person to ensure that all of the AHERA requirements are properly implemented. The Designated Person must receive adequate training to perform their duties.
  2. The LEA must ensure that management plans are maintained in a central location, as well as at each facility, and such plans and records are available for inspection or review at all times.
  3. The LEA must inform all workers, building occupants or their legal representative in writing at least once per school year about asbestos-related activities, and the availability of the AHERA management plans for the school buildings.

4. The LEA must ensure proper accreditation for all persons who perform asbestos inspections, asbestos re-inspections, develop/update management plans, develop response actions, and perform required response actions including operations and maintenance (O&M) activities that may disturb asbestos.
5. The LEA must provide training for all custodial and maintenance staff who regularly perform building maintenance where ACBM are present. The training must be provided upon initial hire, as well as annual updates.
6. The LEA must provide information (disclosure) to any workers who may perform work and may come into contact with asbestos in school buildings where ACBM or presumed ACBM are present.
7. The LEA must ensure that known ACBM or presumed ACBM are provided with warning labels in routine maintenance areas.
8. The LEA must ensure that periodic surveillance is performed at least once every six months, after management plan implementation, in all school buildings that it leases, owns, or otherwise uses that contains ACBM or presumed ACBM.
9. The LEA must ensure that once every three years, after a management plan is implemented, a Re-Inspection is performed at each school building that it leases owns or otherwise uses that contains ACBM or presumed ACBM.

Refer to above-mentioned regulation for full requirements and responsibilities.

---

### 1.3 Accreditation

A. Local Education Agency (LEA):

LEA: New Milford Public Schools  
Address: 50 East Street  
New Milford, Connecticut  
Phone: (860) 355-8406  
Fax: (860) 210-4132

B. Designated Person:

Designated Person: Mr. Kevin Munrett  
Address: 386 Danbury Road  
New Milford, Connecticut  
Phone: (860) 354-6265  
Fax: (860) 210-2233

C. Asbestos Consultant:

Firm: Fuss & O'Neill, Inc.  
Address: 56 Quarry Road  
Trumbull, Connecticut  
Phone: (203) 374-3748  
Fax: (203) 374-4391

D. Asbestos Inspector:

Inspector: Benjamin Silverman  
CTDPH License #: 000349  
Expiration Date: 08/31/2020

E. Asbestos Management Planner:

Planner: Eduardo Miguel Marques  
CTDPH License #: 000201  
Expiration: 02/28/2021

## 2 Building and Mechanical System Description

Northville Elementary School is a one-story building reportedly constructed in 1982. The building is constructed on a concrete slab foundation with brick outer walls and a corrugated steel frame. The inner walls are primarily constructed of concrete block. Suspended ceilings exist in most areas of the building, creating a plenum space with water pipes and HVAC ducts.

Ventilation is provided by an air handling system, which draws air into return ducts and supplies air by means of air handling units located above the ceiling, forcing air into each room by means of supply ducts.

All areas of the school are serviced by a central boiler room. Heat is provided by one oil burning boiler, which conveys heat via hot water pipes that traverse the building through the ceiling plenum to radiators in the rooms.

## 3 Three Year Re-Inspection

### 3.1 Re-Inspection Procedures

This three-year asbestos re-inspection was conducted in accordance with EPA requirements of the AHERA regulation, Title 40 CFR, Part 763, Section 763.85 (b).

On March 26, 2020, Fuss & O'Neill, Inc. (Fuss & O'Neill) representative Mr. Ben Silverman performed the re-inspection.

- A. During the re-inspection, Fuss & O'Neill conducted the following required tasks:
1. A visual re-inspection and reassessment of all known friable or assumed ACBM.
  2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has become friable.
  3. Identification and assessment of any newly-identified homogeneous area that contains friable ACBM since the last inspection or re-inspection.

## 4 Re-Inspection Report

---

### 4.1 Review of Existing Records

An important part of this AHERA re-inspection involved researching prior documentation that is required to be present at the school, as well as at the central recordkeeping location where management plans are stored.

Please see *Appendix A* for the checklist for existing records.

### 4.2 Re-Inspection Summary

---

The on-site portion of the re-inspection was documented on forms modeled after examples provided by the EPA and reviewed with the CTDPH. The first form, **Re-Inspection Form 1A**, identifies previous inspection data gathered during the initial AHERA inspection and subsequent re-inspection (see *Appendix B*). This form is useful to reference response actions (if any), which have been performed since the last inspection, as well as identifies the last known conditions of ACBM in the building. It additionally provides the inspector a “quick glance” reference when performing the re-inspection.

The second EPA form, **Re-Inspection Form 1B**, is used to list all known or assumed asbestos-containing materials that were previously unidentified (See *Appendix C*). It also lists the ACBM in areas newly-acquired by the school for student use either permanently or temporarily.

The third EPA form, **Re-Inspection Form 2**, was used to provide information and justification regarding re-assessment of the ACBM (see *Appendix D*). This form also provides response action recommendations, including a tentative schedule for completing response actions that recommend removal or repair.

No bulk samples were collected during this re-inspection.

Using EPA protocol and criteria, the following materials existing in Northville Elementary School at the time of this three-year re-inspection have been determined and/or assumed to be **ACBM**. Please refer to the above-mentioned Re-Inspection Forms for specific locations of the materials.

**Table 1  
Asbestos-Containing Building Materials**

<b>Material</b>	<b>Location</b>	<b>Reference</b>	<b>Asbestos Content</b>
Pipe Insulation and Associated Pipe Fitting Insulation	Within Walls and Pipe Chases, Boiler Room	EnviroScience 1999 AHERA Inspection	Assumed
Red Fire Caulking Compounds	In Boiler Room on Boiler	EnviroScience 2017 AHERA Inspection	Assumed
White Textured Ceiling Paint	Front Entrance Corridor and Exterior Door Overhangs 1, 5, 6, 7, 15, 16, and 17	EnviroScience 2008 AHERA Inspection	Assumed
Brown Interior Window Caulking	Throughout Exterior Window Systems	EnviroScience 2017 AHERA Inspection	Assumed
Brown Caulk on Brick	Vestibule between Rooms 11 – 12 and 13 – 15	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Gray Interior Window Glazing Compound (Painted Brown)	Interior Window and Door Systems at Library Suite, Display Cases in Hallway	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Black 4" Angle Cove Base and Associated Adhesive	Gymnasium	EnviroScience 1999 and 2017 AHERA Inspection	Assumed
Brown/Orange 4" Cove Base and Associated Adhesive	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	EnviroScience 1999 and 2017 AHERA Inspection	Assumed
Fire Door Insulation	Throughout Building, Potentially in Fire Door Cores	EnviroScience 1999 AHERA Inspection	Assumed
Gypsum Board and Associated Joint/Taping Compound	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, Boiler Room, and Cafeteria	EnviroScience 1999 AHERA Inspection	Assumed
Blackboards and Associated Adhesive	Throughout Building – Corridors, Classrooms, Offices, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Kitchen, And Cafeteria	EnviroScience 1999 AHERA Inspection	Assumed



<b>Material</b>	<b>Location</b>	<b>Reference</b>	<b>Asbestos Content</b>
Tack Boards and Associated Adhesive	Throughout Building – Corridors, Classrooms, Offices, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Kitchen, and Cafeteria	EnviroScience 1999 AHERA Inspection	Assumed
Adhesive Associated With Mirrors	Bathrooms	EnviroScience 1999 AHERA Inspection	Assumed
1" Multi-Tan Ceramic Floor Tile and Associated Gray Grout and Adhesive	Staff Bathrooms by Break Room and Main Office, Boy's and Girl's Bathrooms by Gym, Girl's Bathroom by Room 27, Nurse's Bathroom, Women's Bathroom by Cafeteria, Bathrooms in Classrooms 1-17 and 19	Fuss & O'Neill 2020 AHERA Inspection	Assumed
1" Multi-Blue Ceramic Floor Tile and Associated Gray Grout and Adhesive	Boy's Bathroom by Room 28 and Men's Bathroom by Cafeteria	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Blue 12" x 12" Floor Tile and Associated Adhesive	I.P.P. Room by Room 27	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Yellow Glue Associated with 12" x 12" Floor Tile	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	EnviroScience 1999 and 2017 AHERA Inspection	Assumed
Black Mastic Associated with 12" x 12" Floor Tile	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	EnviroScience 1999 and 2017 AHERA Inspection	Assumed
Orange 4" x 4" Quarry Tile and Associated Grout and Adhesive	Kitchen	EnviroScience 1999 and 2017 AHERA Inspection	Assumed
Stage Light Electrical Wiring	Cafeteria	EnviroScience 1999 and 2017 AHERA Inspection	Assumed
Black Sink Undercoating	Throughout Classrooms, Teacher's Room, and Nurse's Room	EnviroScience 1999 and 2017 AHERA Inspection	Assumed

<b>Material</b>	<b>Location</b>	<b>Reference</b>	<b>Asbestos Content</b>
Gray Sink Undercoating	Main Office Copy/Staff Room	Fuss and O'Neill 2019 AHERA Surveillance	Assumed
White Sink Undercoating	Nurse's Room	Fuss and O'Neill 2019 AHERA Surveillance	Assumed
Vapor Barrier/Tar Under Wood Flooring	Gymnasium, Stage in Cafeteria	EnviroScience 2005 AHERA Inspection	Assumed

Using the EPA protocol, samples of the following suspect materials were collected and analyzed. The analytical results indicated that these materials are **non-ACBM**:

**Table 2**  
**Non-Asbestos-Containing Building Materials**

<b>Material</b>	<b>Location</b>	<b>Reference</b>
Boiler Stack Insulation	Throughout Building	Consulting Services 1986
2' x 2' Ceiling Tiles	Throughout Building	Consulting Services 1986
2' x 4' Ceiling Tiles	Throughout Building	Consulting Services 1986
White with Brown and White Streak, Dark-Tan, Light-Tan, Blue, Brown, Pink, Brown with Dark-Brown Speck, Orange, and Red 12" x 12" Floor Tiles	Throughout Building	Consulting Services 1986
Stage Curtains	Throughout Building	Consulting Services 1986
Carpet Glue	Library, Classrooms, Offices, Conference Rooms	Fuss & O'Neill Bulk Sampling 2018

Mr. Eduardo Miguel Marques reviewed the information obtained during this Re-Inspection. Mr. Marques is an EPA-accredited and CTDPH-licensed Asbestos Management Planner.

### **4.3 Newly Identified or Re-sampled ACBM Materials**

The following newly identified suspect ACBM have been identified in the building:

- Brown Caulk on Brick;
- Gray Interior Window Glazing Compound (Painted Brown);
- 1" Multi-Tan Ceramic Floor Tile and Associated Gray Grout and Adhesive;
- 1" Multi-Blue Ceramic Floor Tile and Associated Gray Grout and Adhesive; and
- Blue 12" x 12" Floor Tile and Associated Adhesive.

These materials must be assumed to contain asbestos until laboratory analysis determine otherwise. These materials have been added to *Table 1* as assumed ACBM.

AHERA regulations pertain to interior identified or assumed ACBM and limited exterior ACBM. AHERA regulations do include ACBM located on exterior porticos, covered walkways, and mechanical equipment used to condition interior building air.

Any suspect material encountered during renovation/demolition/maintenance activities that is not specifically identified in the Asbestos Management Plan (AMP) as a non-ACM should be assumed to contain asbestos unless sample results indicate otherwise.

**Additional Information:**

- ACBM floor tile and associated mastics may exist below non-moveable objects such as cabinets, platforms, sheetrock walls, lockers, etc.;
- Samples of exterior building materials not covered under AHERA, such as caulking and glazing compounds, roofing materials and materials behind exterior walls and panels should be collected and analyzed to determine asbestos content prior to performing activities that would disturb them;
- Asbestos-containing vapor barriers and waterproofing materials may exist beneath wood floors, behind walls, exterior below ground surface foundations, etc.; and
- Subsurface cementitious pipe (i.e., asbestos cement pipe).

---

## 4.4 Physical Assessment of ACBM

During inspection, suspect ACBM were separated into three EPA categories. These categories are thermal system insulation (TSI), surfacing ACBM, and miscellaneous ACBM. TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe and fitting insulations, boiler insulation, and duct insulation. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACBM not listed in TSI or surfacing, such as sheet flooring, vinyl asbestos flooring, ceiling tiles, and construction mastics/adhesives.

Finally, ACBM were quantified in linear and/or square feet, depending on the nature of the material.

The ACBM identified during the inspection and still remaining in the school were re-assessed using the CTDPH and AHERA guidelines for assessment of ACBM. The following assessment categories are listed:

1. Damaged or significantly damaged TSI ACBM
2. Damaged friable surfacing ACBM
3. Significantly damaged friable surfacing ACBM
4. Damaged or significantly damaged friable miscellaneous ACBM
5. ACBM with potential for damage
6. ACBM with potential for significant damage

7. Any remaining friable ACBM or friable suspected ACBM

Material locations, assessments, and recommended response actions are listed in the Re-Inspection forms.

## 5 Management Plan Update

### 5.1 Recommended Response Actions

Based on the inspection report, physical walk-through inspection, and existing ACBM conditions, the following response actions are recommended:

1. Removal – Not Applicable
2. Repair – Not Applicable
3. Enclosure – Not Applicable
4. Encapsulation – Not Applicable
5. Operations and Maintenance (O & M) – All remaining ACBM.

It should be noted that only ACBM with assessments of 1 or 2 are recommended for removal or repair. The remaining ACBM should be included in the O & M Program. The condition of these ACBM will be monitored until all of the ACBM have been completely removed from the building. A successful O & M Program includes the following elements:

- A. Cleaning: All areas of the school where friable ACBM or assumed friable ACBM are present should be cleaned at least once after completion of the initial inspection. Additional cleaning may be necessary if the Management Planner makes a written recommendation indicating the methods and frequency of such cleaning.
- B. O & M Activities: The LEA shall ensure that the procedures described below are followed to protect building occupants from O & M activities that may disturb known or assumed ACBM:
  1. Restrict entry into the area either by physically isolating or by scheduling.
  2. Post asbestos warning signs to prevent entry by unauthorized persons.
  3. Deactivate or temporarily shut off or divert the air-handling system to the area.
  4. Use proper work practices and engineering controls, such as wet methods, protective clothing, High Efficiency Particulate Air (HEPA) vacuums, mini-enclosures/glove bags, etc. to inhibit fiber migration.
  5. Place asbestos debris and other contaminated materials into a sealed, leak-tight container for disposal.
- C. Minor Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., disturbance of less than or equal to 3 linear/square feet of friable ACBM):
  1. Saturate the debris using wet method.
  2. Place the debris in a sealed, leak-tight container and clean the area.

3. Repair the area of damaged ACBM with materials such as asbestos-free spackling, plaster or insulation or seal with an encapsulant.
- D. Major Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., disturbance of greater than 3 linear/square feet of friable ACBM):
1. Restrict entry into the area and post asbestos warning signs.
  2. Deactivate or temporarily shut off or divert the air handling system from the area to prevent fiber migration.
  3. The response action for any major fiber release episode must be prepared by EPA-accredited Asbestos Project Designers and conducted by EPA-accredited personnel.
  4. The LEA shall notify the CTDPH of any major fiber release episode within twenty-four hours of its occurrence and, if necessary, provide written notification as required by applicable federal and/or state regulations.

---

## 5.2 Periodic Surveillance

At least once every six months after an AMP is implemented, the LEA will conduct periodic surveillance in the school that contains ACBM or assumed ACBM. The person conducting periodic surveillance will visually inspect all areas in the school that where ACBM have been identified in the AMP, record the date of surveillance, their name, any changes in the ACBM condition and submit the record to the LEA Designated Person for inclusion in the AMP.

Please see *Appendix E* for the sample Periodic Surveillance Form that may be used for conducting periodic surveillance.

---

## 5.3 Preventive Measures

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that ACBM will become damaged, deteriorated, or delaminated.

Please see *Appendix F* for preventive measures designed for various types of ACBM that may exist in the school.

---

## 5.4 Abatement (Removal) Cost Estimates


Materials requiring abatement were not identified during this three year re-inspection therefore costs have not been provided.

## 6 EPA Accreditation Requirements


The EPA accreditations and the CTDPH Asbestos Inspector licenses for Mr. Ben Silverman and Mr. Eduardo Miguel Marques are provided in *Appendix G*.

Report prepared by Senior Environmental Technician Ben Silverman.

Reviewed by:



Eduardo Miguel Marques  
Senior Environmental Analyst



Jared D. Smith, CSP  
Senior Project Manager

## **Appendix A**

---

### Existing Records Checklist

## Existing Records Checklist

Local Education Agency (LEA): New Milford Public Schools  
50 East Street  
New Milford, Connecticut, 06776

School Building: Northville Elementary School

The following documentation is required to be present in both the LEA's office, as well as in a centralized location in the school administrative office. The information included in this checklist will be verified to be present and complete as part of three-year Re-Inspection.

DOCUMENTATION		LOCATION	
		School	LEA Office
1	Original AHERA Operations and Maintenance Plan/Inspection Report	*	Yes
2	Three Year Re-Inspection (First and All Subsequent Inspections)	*	Yes
3	Parents and Teachers Notifications (Annually Since Last Re-Inspection)	*	Yes
4	Designated Person Identification and Proper Training (Person Must Be Named and Have Appropriate Training)	*	Yes
5	Designated Person Periodic Surveillance (Once Every Six Months)	*	Yes
6	Maintenance Staff Awareness Training Records	*	Yes
7	Outside Vendor Awareness Notification	*	Yes
8	Asbestos Warning Signs and Labels (Required Posting in Boiler Rooms and Mechanical Spaces Only)	No	N/A
9	Response Action Records (Includes Any Abatement Conducted Since Last 3-Year Re-Inspection)	*	Yes

Comments: \* The Asbestos Management Plan (AMP) and support documentation is available electronically on the New Milford Public Schools website facilities page. Please refer to the Facilities page on the New Milford Public School website ([newmilfordps.org](http://newmilfordps.org)) for further information.

Inspector (LEA Office): Ben Silverman

Date: 3/26/2020

Inspector (School): Ben Silverman

Date: 3/26/2020



## **Appendix B**

---

### Re-Inspection Form 1A

School: New Milford Public Schools  
 Address: 22 Hipp Road, New Milford, CT

 Building: Northville Elementary School  
 Date(s) of Subsequent Re-Inspections: 1999, 2008, 2017, 2020

 Date(s) of Original Inspection: 1986

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
Assumed	Assumed ACM	Pipe Insulation and Associated Pipe Fitting Insulation	TSI	F	7	Within Walls and Pipe Chases, Boiler Room	
Assumed	Assumed ACM	Red Fire Caulking Compounds	Misc.	NF	5	In Boiler Room on Boiler	
Assumed	Assumed ACM	White Textured Ceiling Paint	Surf.	NF	5	Front Entrance Corridor and Exterior Door Overhangs 1, 5, 6, 7, 15, 16, and 17	
Assumed	Assumed ACM	Brown Interior Window Caulking	Misc.	NF	5	Throughout Exterior Window Systems	
Assumed	Assumed ACM	Black 4" Angle Cove Base and Associated Adhesive	Misc.	NF	5	Gymnasium	
Assumed	Assumed ACM	Brown/Orange 4" Cove Base and Associated Adhesive	Misc.	NF	5	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	
Assumed	Assumed ACM	Fire Door Insulation	Misc.	F	N/A	Throughout Building, Potentially in Fire Door Cores	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.

School: New Milford Public Schools  
 Address: 22 Hipp Road, New Milford, CT

 Building: Northville Elementary School  
 Date(s) of Subsequent Re-Inspections: 1999, 2008, 2017, 2020

 Date(s) of Original Inspection: 1986

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
Assumed	Assumed ACM	Gypsum Board and Associated Joint/Taping Compound	Misc.	NF	5	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, Boiler Room, and Cafeteria	
Assumed	Assumed ACM	Blackboards and Associated Adhesive	Misc.	NF	5	Throughout Building – Corridors, Classrooms, Offices, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Kitchen, And Cafeteria	
Assumed	Assumed ACM	Tack Boards and Associated Adhesive	Misc.	NF	5	Throughout Building – Corridors, Classrooms, Offices, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Kitchen, and Cafeteria	
Assumed	Assumed ACM	Adhesive Associated With Mirrors	Misc.	NF	5	Bathrooms	
Assumed	Assumed ACM	Yellow Glue Associated with 12" x 12" Floor Tile	Misc.	NF	5	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	

School: New Milford Public Schools  
 Address: 22 Hipp Road, New Milford, CT

 Building: Northville Elementary School  
 Date(s) of Subsequent Re-Inspections: 1999, 2008, 2017, 2020

 Date(s) of Original Inspection: 1986

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
Assumed	Assumed ACM	Black Mastic Associated with 12" x 12" Floor Tile	Misc.	NF	5	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	
Assumed	Assumed ACM	Orange 4" x 4" Quarry Tile and Associated Grout and Adhesive	Misc.	NF	5	Kitchen	
Assumed	Assumed ACM	Stage Light Electrical Wiring	Misc.	NF	5	Cafeteria	
Assumed	Assumed ACM	Black Sink Undercoating	Misc.	NF	N/A	Throughout Classrooms, Teacher's Room, and Nurse's Room	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.
Assumed	Assumed ACM	Gray Sink Undercoating	Misc.	NF	N/A	Main Office Copy/Staff Room	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.
Assumed	Assumed ACM	White Sink Undercoating	Misc.	NF	N/A	Nurse's Room	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.

School: New Milford Public Schools  
 Address: 22 Hipp Road, New Milford, CT

 Building: Northville Elementary School  
 Date(s) of Subsequent Re-Inspections: 1999, 2008, 2017, 2020

 Date(s) of Original Inspection: 1986

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
Assumed	Assumed ACM	Vapor Barrier/Tar Under Wood Flooring	Misc.	NF	5	Gymnasium, Stage in Cafeteria	
Assumed	Assumed ACM	Interior Boiler Components	TSI	F	5	Boiler room	
Assumed	Assumed ACM	Cementitious Panels	Misc.	NF	5	Throughout window systems (below windows)	Material determined to be metal. Material removed from inventory.

 Information abstracted by: Ben Silverman Date: 3/26/2020

Material Category: TSI = Thermal System Insulation, Surf. = Surfacing, Misc. = Miscellaneous

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories:

1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM

## **Appendix C**

---

### Re-Inspection Form 1B

School: New Milford Public Schools  
 Address: 22 Hipp Road, New Milford, CT

 Building: Northville Elementary School  
 Date(s) of Subsequent Re-Inspections: 1999, 2008, 2017, 2020

 Date(s) of Original Inspection: 1986

Homogeneous Material		Asbestos Content (%)	Material Category	Estimated Quantity (SF/LF)	Friability	Assessment Category (1-7)	Recorded Locations of Material for Each Assessment Category
Sample Number	Material Description						
Assumed	Brown Caulk on Brick	Assumed ACM	Misc.	32 LF	NF	5	Vestibule between Rooms 11– 12 and 13 – 15
Assumed	Gray Interior Window Glazing Compound (Painted Brown)	Assumed ACM	Misc.	900 LF	NF	5	Interior Window and Door Systems at Library Suite, Display Cases in Hallway
Assumed	1” Multi-Tan Ceramic Floor Tile and Associated Gray Grout and Adhesive	Assumed ACM	Misc.	1,936 SF	NF	5	Staff Bathrooms by Break Room and Main Office, Boy’s and Girl’s Bathrooms by Gym, Girl’s Bathroom by Room 27, Nurse’s Bathroom, Women’s Bathroom by Cafeteria, Bathrooms in Classrooms 1-17 and 19
Assumed	1” Multi-Blue Ceramic Floor Tile and Associated Gray Grout and Adhesive	Assumed ACM	Misc.	452 SF	NF	5	Boy’s Bathroom by Room 28 and Men’s Bathroom by Cafeteria
Assumed	Blue 12” x 12” Floor Tile and Associated Adhesive	Assumed ACM	Misc.	160 SF	NF	5	I.P.P. Room by Room 27

 Inspected by: Ben Silverman Date: 3/26/2020

Material Category: TSI = Thermal System Insulation, S = Surfacing, M = Miscellaneous

LF = Linear Feet; SF = Square Feet

Friability: F = Friable, NF = Non-Friable

School: New Milford Public SchoolsBuilding: Northville Elementary SchoolDate(s) of Original Inspection: 1986Address: 22 Hipp Road, New Milford, CTDate(s) of Subsequent Re-Inspections: 1999, 2008, 2017, 2020

## AHERA Assessment Categories:

1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM



## **Appendix D**

---

### Re-Inspection Form 2





School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Pipe Insulation and Associated Pipe Fitting Insulation

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Within Walls and Pipe Chases, Boiler Room	F	2,500 LF	7	Any remaining friable ACBM or friable suspected ACBM	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						





School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Red Fire Caulking Compounds

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
In Boiler Room on Boiler	NF	5 LF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: White Textured Ceiling Paint

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Front Entrance Corridor and Exterior Door Overhangs 1, 5, 6, 7, 15, 16, and 17	NF	800 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Brown Interior Window Caulking

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Exterior Window Systems	NF	65 window systems	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Brown Caulk on Brick

 Sample ID Number: Assumed



ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Vestibule between Rooms 11 – 12 and 13 – 15	NF	32 LF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Gray Interior Window Glazing Compound (Painted Brown) Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Interior Window and Door Systems at Library Suite, Display Cases in Hallway	NF	900 LF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Black 4" Angle Cove Base and Associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Gymnasium	NF	500 LF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Brown/Orange 4" Cove Base and Associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	NF	8,000 LF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Fire Door Insulation

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building, Potentially in Fire Door Cores	F	1,200 SF	N/A	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Gypsum Board and Associated Joint/Taping Compound

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, Boiler Room, and Cafeteria	NF	10,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Blackboards and Associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building – Corridors, Classrooms, Offices, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Kitchen, And Cafeteria	NF	7,500 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						





School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Tack Boards and Associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building – Corridors, Classrooms, Offices, Toilet Rooms, Library, Main Office, Principal’s Office, Teacher’s Room, Kitchen, and Cafeteria	NF	2,500 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector’s Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA’s Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Adhesive Associated With Mirrors

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Bathrooms	NF	1,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: 1" Multi-Tan Ceramic Floor Tile and Associated Gray Grout and Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Staff Bathrooms by Break Room and Main Office, Boy's and Girl's Bathrooms by Gym, Girl's Bathroom by Room 27, Nurse's Bathroom, Women's Bathroom by Cafeteria, Bathrooms in Classrooms 1-17 and 19	NF	1,936 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: 1" Multi-Blue Ceramic Floor Tile and Associated Gray Grout and Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boy's Bathroom by Room 28 and Men's Bathroom by Cafeteria	NF	452 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						







School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Blue 12" x 12" Floor Tile and Associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
I.P.P. Room by Room 27	NF	160 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Yellow Glue Associated with 12" x 12" Floor Tile

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	NF	40,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Black Mastic Associated with 12" x 12" Floor Tile

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal’s Office, Teacher’s Room, Storage Rooms, Kitchen, and Cafeteria	NF	40,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector’s Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA’s Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Northville Elementary School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Orange 4" x 4" Quarry Tile and Associated Grout and Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Kitchen	NF	700 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						





School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Stage Light Electrical Wiring

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Cafeteria	NF	Material Not Quantified	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____						
Date: _____						





School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Black Sink Undercoating

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Classrooms, Teacher's Room, and Nurse's Room	NF	175 SF	N/A	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____						
Date: _____						





School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Gray Sink Undercoating

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Main Office Copy/Staff Room	NF	5 SF	N/A	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: White Sink Undercoating

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Nurse's Room	NF	5 SF	N/A	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						







School: New Milford Public Schools

Building: Northville Elementary School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Vapor Barrier/Tar Under Wood Flooring

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Gymnasium, Stage in Cafeteria	NF	6,800 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

## **Appendix E**

---

### Sample 6-Month Periodic Surveillance Form

## 6- Month Periodic Surveillance Form

Local Education Agency (LEA): New Milford Public Schools

Facility Address: Northville Elementary School, 22 Hipp Road, New Milford, CT

Date of Surveillance: \_\_\_\_\_

### ACBM Damage Report

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
Pipe Insulation and Associated Pipe Fitting Insulation	Within Walls and Pipe Chases, Boiler Room	IA/G				
Red Fire Caulking Compounds	In Boiler Room on Boiler	G				
White Textured Ceiling Paint	Front Entrance Corridor and Exterior Door Overhangs 1, 5, 6, 7, 15, 16, and 17	G				
Brown Interior Window Caulking	Throughout Exterior Window Systems	G				
Brown Caulk on Brick	Vestibule between Rooms 11 – 12 and 13 – 15	G				
Gray Interior Window Glazing Compound (Painted Brown)	Interior Window and Door Systems at Library Suite, Display Cases in Hallway	G				
Black 4" Angle Cove Base and Associated Adhesive	Gymnasium	G				
Brown/Orange 4" Cove Base and Associated Adhesive	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	G				2 LF of cove base missing in Room 3 Coat Rack Area.

<b>Asbestos-Containing Building Material</b>	<b>Location</b>	<b>Previous Condition</b>	<b>Present Condition</b>	<b>Change in Condition (Yes/No)</b>	<b>Estimated Damaged Quantity</b>	<b>Comments</b>
Fire Door Insulation	Throughout Building, Potentially in Fire Door Cores	G				Exposed at Custodian's Office door. Cover.  Not Required by AHERA; for informational purposes only Material must be Managed and Disposed of as ACM Prior Disturbance
Gypsum Board and Associated Joint/Taping Compound	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, Boiler Room, and Cafeteria	G				
Blackboards and Associated Adhesive	Throughout Building – Corridors, Classrooms, Offices, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Kitchen, And Cafeteria	G				
Tack Boards and Associated Adhesive	Throughout Building – Corridors, Classrooms, Offices, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Kitchen, and Cafeteria	G				
Adhesive Associated With Mirrors	Bathrooms	IA	IA			

<b>Asbestos-Containing Building Material</b>	<b>Location</b>	<b>Previous Condition</b>	<b>Present Condition</b>	<b>Change in Condition (Yes/No)</b>	<b>Estimated Damaged Quantity</b>	<b>Comments</b>
1" Multi-Tan Ceramic Floor Tile and Associated Gray Grout and Adhesive	Staff Bathrooms by Break Room and Main Office, Boy's and Girl's Bathrooms by Gym, Girl's Bathroom by Room 27, Nurse's Bathroom, Women's Bathroom by Cafeteria, Bathrooms in Classrooms 1-17 and 19	G				
1" Multi-Blue Ceramic Floor Tile and Associated Gray Grout and Adhesive	Boy's Bathroom by Room 28 and Men's Bathroom by Cafeteria	G				
Blue 12" x 12" Floor Tile and Associated Adhesive	I.P.P. Room by Room 27	G				
Yellow Glue Associated with 12" x 12" Floor Tile	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	IA				
Black Mastic Associated with 12" x 12" Floor Tile	Throughout Building – Corridors, Classrooms, Offices, Storage Rooms, Toilet Rooms, Library, Main Office, Principal's Office, Teacher's Room, Storage Rooms, Kitchen, and Cafeteria	IA				
Orange 4" x 4" Quarry Tile and Associated Grout and Adhesive	Kitchen	G				
Stage Light Electrical Wiring	Cafeteria	G				

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
Black Sink Undercoating	Throughout Classrooms, Teacher's Room, and Nurse's Room	G				Not Required by AHERA; for informational purposes only Material must be Managed and Disposed of as ACM Prior Disturbance
Gray Sink Undercoating	Main Office Copy/Staff Room	G				Not Required by AHERA; for informational purposes only Material must be Managed and Disposed of as ACM Prior Disturbance
White Sink Undercoating	Nurse's Room	G				Not Required by AHERA; for informational purposes only Material must be Managed and Disposed of as ACM Prior Disturbance
Vapor Barrier/Tar Under Wood Flooring	Gymnasium, Stage in Cafeteria	IA	IA			

Conditions: D = Damaged; G = Good; IA = Inaccessible; NA = Not Applicable; SF = Square Feet; LF = Linear Feet

Surveillance conducted by: \_\_\_\_\_  
 (print name) (signature)

I, the LEA's Designated Person, have read and understood the findings noted above: \_\_\_\_\_

Date: \_\_\_\_\_

## **Appendix F**

---

### Preventive Measures

## Preventive Measures for Various Asbestos-Containing Building Materials

### A. Surfacing Materials

“Surfacing Materials” means materials in a school building that are applied by spray, trowel, or otherwise applied to surfaces. These include sprayed-applied fireproofing materials on structural members, ceiling and wall plasters, or other materials applied to surfaces for acoustical, fireproofing, or other purposes.

Surfacing Materials are generally considered friable and can release asbestos fibers if damaged by impact, air erosion, vibration, and/or water intrusion. When properly implemented, the following procedures will reduce the potential for fiber release:

#### 1. Sprayed-Applied Fireproofing

- a) Identify the materials and post warning signs on the laid-in or glued-in ceiling tile. If the decking is not covered, place the sign on the wall.
- b) Maintain the materials in intact state and undamaged condition. During winter, pigeons, squirrels and other rodents tend to roost in boiler/machine rooms and dislodge sprayed-applied fireproofing on the decking. Prevent such possibilities.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, enclosure is a temporary solution. Encapsulation of damaged sprayed-on fireproofing material is not recommended.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials. Please note that the repair/removal can only be performed by a licensed abatement contractor.

#### 2. Ceiling and Wall Plasters

- a) Identify the materials and post asbestos warning signs.
- b) Maintain the materials in intact state and undamaged condition. Avoid storing/stacking on/near the materials to reduce contact damage.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, repair or enclosure is a temporary solution.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials.

### B. Thermal System Insulation (TSI)

“Thermal System Insulation (TSI)” means insulating materials applied to pipes, pipe fittings, boilers, breechings, tanks, ducts, or other components to prevent process heat loss or gain, water condensation, or for other purposes (e.g., fire door insulation core).



TSI are generally considered friable ACBM. This means they can be easily damaged, increasing the potential for fiber release. When properly implemented, the following procedures will reduce the potential for fiber release:

1. Boiler and Breeching Insulation

- a) Identify the locations and label the boiler. Warning signs should be posted outside the boiler room.
- b) Reduce the likelihood of fiber release by ensuring that the insulation is not damaged. Avoid storing/stacking on/near the boiler to reduce contact damage.
- c) Maintain the insulation in intact state and undamaged condition. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Pipe, Pipe Fitting, Tank, Duct & Breeching Insulations

- a) Identify the locations and label the materials. Warning signs should be posted outside of rooms that have TSI materials.
- b) Reduce the likelihood of fiber release by ensuring that the materials are not damaged. Avoid storing/stacking near the materials to reduce contact damage.
- c) Maintain all TSI materials in intact state and undamaged condition. Inspect the protective jackets for damage. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

## **C. Miscellaneous Materials**

“Miscellaneous Materials” are the other ACBM in a school building that are not categorized as Surfacing Materials or TSI. These include floor tiles, floor tile and carpet mastics, gypsum wallboard and joint compound, ceiling tiles, glue daubs, asbestos cement panels, cove base and associated glue, window/door caulking and glazing compounds, etc. The following maintenance procedures are recommended for these materials:

1. Vinyl Asbestos Floor Tiles (VAT)

Vinyl Asbestos Floor Tiles (VAT) are considered non-friable, however routine maintenance procedures such as spray-buffing, burnishing, wet scrubbing, and stripping can generate asbestos fibers. Following procedures, when properly implemented, will reduce the potential of fiber release:

- a) Do not sand, grind, or abrade the tiles. Stripping of VAT should be done as infrequently as possible. When stripping becomes necessary, follow the appropriate work practices. Never perform dry stripping.
- b) During spray-buffing or burnishing the floor, operate the machine at the lowest workable speed and use the least abrasive pad. Use a wet mop for routine cleaning whenever possible.
- c) Routinely check whether chair and desk glides are in good condition and replace when necessary. Worn glides can gouge the floor and cause fiber release.
- d) Place carpets/floor mats in all entrances to reduce abrasion of floor tiles by sand and pebbles. During winter, have parking lots and walkways swept to the extent possible to avoid the tracking of salt and ice-melting compounds into the school by the students.
- e) Train the custodial people who are responsible for care and maintenance of VAT. Please note that the repair/removal can only be performed by a licensed abatement contractor.

## 2. Wallboard and Joint Compound Assembly

- a) Since a number of different homogeneous assemblies may exist in a building, sheetrock/joint compound must be assumed to be ACBM unless sample results prove otherwise. If any specific areas are going to be disturbed, samples of the material in that area should be collected and analyzed.
- b) Reduce the likelihood of fiber release by avoiding cutting or drilling holes through the sheetrock panels.

## 3. Ceiling Tile and Glue Daubs

- a) Reduce the likelihood of fiber release by limiting access to the space above the ceiling tiles. Maintain the ceiling tiles in undamaged condition. Replace any damaged or water-stained tile.
- b) If the ceiling tiles are non-asbestos, collect samples and analyze the glue daubs to identify asbestos-content before disturbing the tiles.

## 4. Asbestos Cement Panels, Window/Door Caulking and Glazing Compounds

- a) Maintain asbestos cement panels and window/door caulking and glazing compounds in undamaged condition.

## 5. Carpet Glue, Blackboard/Tack Board Glue, Floor Tile Mastic, Cove Base, and Mastic

- a) Reduce the likelihood of fiber release by leaving materials in place.
- b) Maintain materials in good condition. Collect samples and analyze to identify asbestos-content before disturbing.

## **Appendix G**

---

### Asbestos Inspector and Management Planner State Licenses and EPA Accreditations

Dear BENJAMIN L SILVERMAN,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:



Department of Public Health  
P.O. Box 340308  
M.S.#12MQA  
Hartford, CT 06134-0308

(860) 509-7603  
opl.c.dph@ct.gov  
www.ct.gov/dph/license

Sincerely,



RENÉE D. COLEMAN-MITCHELL, MPH, COMMISSIONER  
DEPARTMENT OF PUBLIC HEALTH

**EMPLOYER'S COPY**  
STATE OF CONNECTICUT  
DEPARTMENT OF PUBLIC HEALTH  
NAME  
BENJAMIN L SILVERMAN  
VALIDATION NO. 03-768866      CERTIFICATE NO. 000349      CURRENT THROUGH 08/31/20  
PROFESSION  
ASBESTOS CONSULTANT-INSP/MGMT PLANNER  
SIGNATURE:         
COMMISSIONER

**STATE OF CONNECTICUT  
DEPARTMENT OF PUBLIC HEALTH**

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED  
BY THIS DEPARTMENT AS A


ASBESTOS CONSULTANT-INSP/MGMT PLANNER

BENJAMIN L SILVERMAN

CERTIFICATE NO.  
000349

CURRENT THROUGH  
08/31/20



VALIDATION NO.  
03-768866

  
SIGNATURE

  
COMMISSIONER

**INSTRUCTIONS:**

1. Detach and sign each of the cards on this form
2. Display the large card in a prominent place in your office or place of business.
3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet card, place it in a secure place.
4. The employer's copy is for persons who must demonstrate current licensure/certification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.

**WALLET CARD**  
STATE OF CONNECTICUT  
DEPARTMENT OF PUBLIC HEALTH  
NAME  
BENJAMIN L SILVERMAN  
VALIDATION NO. 03-768866      CERTIFICATE NO. 000349      CURRENT THROUGH 08/31/20  
PROFESSION  
ASBESTOS CONSULTANT-INSP/MGMT PLANNER  
SIGNATURE:         
COMMISSIONER

# Certificate of Training

Awarded to

**BEN SILVERMAN**

*For successful completion of an 8 Hour, 1 Day*

**Asbestos Inspector & Management Planner  
Annual Refresher Training**

**JANUARY 22, 2020**

This training was approved and given in accordance with

Regulations for Connecticut State Agencies

RCSA 20-440 - 1-9 and RCSA 20-441 and meets the

requirements of the EPA Revised MAP under TSCA Title II of 4/4/94

*Presented by*

**Mystic Air Quality Consultants, Inc.**

**1204 North Road, Groton, CT 06340 (800) 247-7746**

Certificate Number: IMPR27986

Exam Grade: 97

Expiration Date: 01/22/2021



**Christopher J. Eident, CIH, CSP, RS**



**George Williamson, Training Director**

Richard Haffey, Training Director