

**Asbestos Periodic Surveillance Inspection
Winter 2009
New Milford Schools/Buildings**

**New Milford Public Schools
386 Danbury Road
New Milford, Connecticut**

January 2009



**Fuss & O'Neill EnviroScience, LLC
56 Quarry Road
Trumbull, Connecticut 06611**



January 21, 2009

Mr. John Calhoun
Manager, Environmental Services
New Milford Public Schools
386 Danbury Road
New Milford, CT 06776

Re: Periodic Surveillance Services – Winter 2008
Five New Milford Schools and Two Administration Buildings
EnviroScience Project No. 20071230.A2E

Dear Mr. Calhoun:

Enclosed, in duplicate, is the report generated for the asbestos surveillance performed in winter 2009. These forms should be added to the permanent file on hand at each building to document updates and revisions to the Management Plans. The surveillance at the former alternative High School located at 47 Bridge Street was not performed as decided by the New Milford Public Schools Environmental Services Manager at this time (the building was not being utilized as a public school at the time of these periodic surveillances).

The following buildings were inspected:

1. John Pettibone Elementary School
2. Lillis Administration Building
3. Northville Elementary School
4. Schaghticoke Middle School
5. Hill and Plain Elementary School
6. Sarah Noble Intermediate School
7. Facilities Administration Building

56 Quarry Road
Trumbull, CT
06611

t (203) 374-3748
f (203) 374-4391

www.FandO.com

Connecticut

Massachusetts

New York

Rhode Island

North Carolina

South Carolina

If materials found by the inspector are repaired or removed before the next re-inspection, work order forms should be completed by New Milford Public Schools. These work order forms are located in the Asbestos Management Plan for each building. There should be a permanent file on hand at each building documenting all updates and revisions for the State to review if necessary.



FUSS & O'NEILL

Mr. John Calhoun
January 21, 2009
Page 2

If you have any questions regarding these inspections, please contact me at (203) 374-3748, extension 3515. Thank you for the opportunity to have served your environmental needs.

Sincerely,

Matthew Myers
Senior Project Manager

Neal B. Freuden
Neal B. Freuden
President

Enclosure

**Asbestos Periodic Surveillance Inspection
Winter 2009
John Pettibone Elementary School**

**New Milford Public Schools
386 Danbury Road
New Milford, Connecticut**

January 2009



**Fuss & O'Neill EnviroScience, LLC
56 Quarry Road
Trumbull, Connecticut 06611**

**JOHN PETTIBONE ELEMENTARY SCHOOL
PERIODIC SURVEILLANCE REPORT
NEW MILFORD, CONNECTICUT**

On January 14, 2009, Fuss & O'Neill EnviroScience, LLC (EnviroScience's) representative, Kristopher Girton, performed routine surveillance for the John Pettibone Elementary School under the Periodic Surveillance program as described in the AHERA regulations. The surveillance assessments were conducted in order to update the condition of known and assumed asbestos-containing building materials (ACBM) and to identify areas where corrective measures may be required. The most recent Asbestos Management Plan Three-Year Update and Periodic Surveillance Report for John Pettibone Elementary School were referenced. These are the most recent Asbestos Management Plans for the School.

Periodic surveillance involves the visual reassessment of any ACBM or assumed ACBM listed in the Asbestos Management Plan (AMP) for each school. The date of the periodic surveillance, as well as the location of each area, was noted along with the change in the condition of the ACBM, if any. Completed inspection forms are included in this report. The Asbestos Inspector's license is also included in this report.

All ACBM found in the school is listed on the attached periodic surveillance report. Changes in ACBM assessment are listed below. "Changes" can include conditions, and/or locations of ACBM that were not assessed in the last six-month inspection. ACBM that was previously identified as intact and is in slightly damaged condition is listed below.

LOCATION	ASSESSMENT
Rooms 33 and 35	Cement Boards are Punctured.
Nurses Room	Plaster Walls are Water Damaged.

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: John Pettibone Elementary School
2 Pickett District Road, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Pipe and/or pipe fitting insulation	Throughout building - within walls and pipe chases, main office corridor outside principal's office, main office copier room, corridor outside classroom 31, 33, bathrooms by classroom 10, 1955 tunnel - 50' from access door located in boiler room (blue access door), 1964 wing, and storage room near room 20	G	G	No		
Plaster ceilings and walls	Throughout building	G	G	No		
Plaster ceilings and walls	Nurse's Office	D	D	No		Material is water damaged
Sheetrock™ and associated joint/taping compound	Throughout building	G	G	No		
Vapor barriers/tars located below wood floor	Gymnasium	G	G	No		
Ceramic tile adhesives	Throughout toilet rooms	G	G	No		
Glue daubs associated with 1'x1' ceiling tiles	Vice principal's and guidance offices, foyer at building entrance and hallway between cafeteria and gym, 1962 building entrance foyer ceiling, classrooms 21-30, closet near main office, closet across corridor from classroom 26	G	G	No		

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: John Pettibone Elementary School
2 Pickett District Road, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Asphaltic paper vapor barrier	1955 tunnels, applied to concrete ceiling	G	G	No		
Black window sills and associated grout/adhesives	Classrooms 10-16 (A and B), 18, and 20A	G	G	No		
Vibration isolation cloth	1964 Wing, storage room near room 20	G	G	No		
Transite™ paneling under the exterior windows	Throughout building	G	G	No		
Transite™ paneling under the exterior windows	Classrooms 33 and 35	D	D	No		Panels punctured
Sink undercoating – various colors	Throughout classrooms, nurse's room, and teacher's lounge	G	G	No		
Blackboard and tackboard adhesives	Throughout building	G	G	No		
9" x 9" floor tile and associated mastic	Main office, vault room and storage closets by principal's office, custodian's closet by classroom 3, book storage room across from main office, storage room by classroom 29 and custodial closets by classrooms 26 and 27	G	G	No		

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: John Pettibone Elementary School
2 Pickett District Road, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
9"x9" floor tile and associated mastic (materials located under carpet and/or 12" x12" floor tile)	Throughout building	G	G	No		

Conditions: G = Good D = Damaged SD = Significant damage

Surveillance conducted by: Kristopher Girton (000674/CT)

 (Signature)

I, the LEA's Designated Person, have read and understood the findings noted above:

Name: _____
 Date: _____

**Asbestos Periodic Surveillance Inspection
Winter 2009
Lillis Administration Building**

**New Milford Public Schools
386 Danbury Road
New Milford, Connecticut**

January 2009



**Fuss & O'Neill EnviroScience, LLC
56 Quarry Road
Trumbull, Connecticut 06611**


**LILLIS ADMINISTRATION BUILDING
PERIODIC SURVEILLANCE REPORT
NEW MILFORD, CONNECTICUT**

On January 14, 2009, Fuss & O'Neill EnviroScience, LLC (EnviroScience's) representative, Kristopher Girton, performed routine surveillance for the Lillis Administration Building under the Periodic Surveillance program as described in the AHERA regulations. The surveillance assessments were conducted in order to update the condition of known and assumed asbestos containing building materials (ACBM) and to identify areas where corrective measures may be required. The most recent Asbestos Management Plans Three-Year Updates and most recent six-month Periodic Surveillance Report for the Lillis Administration Building were referenced. These are the most recent Asbestos Management Plans for the School.

Periodic surveillance involves the visual reassessment of any ACBM or assumed ACBM listed in the Asbestos Management Plan (AMP) for each school. The date of the periodic surveillance, as well as the location of each area, was noted along with the change in the condition of the ACBM, if any. Completed inspection forms are included in this report. The Asbestos Inspector's license is also included in this report.

All ACBM found in the school is listed on the attached periodic surveillance report. Changes in ACBM assessment are listed below. "Changes" can include conditions, and/or locations of ACBM that were not assessed in the last six-month inspection. ACBM that was previously identified as damaged and remains in a damaged condition is listed below.

LOCATION	ASSESSMENT
Second Floor Copier Room	Damaged Floor Tiles under Carpet
Office Between Room 6 and 7	Damaged Floor Tiles under Carpet
Gymnasium Storage Room	Damaged Ceiling Tiles
Gym Kitchen	Damaged Cement Board




FUSS & O'NEILL
Environmental Science, LLC

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Lillis Administration Building
50 East Street, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Pipe and/or pipe fitting insulation	Vertical wall pipe chases and bathrooms, traffic coordinator's closet	G	G	No		
White foundation wall paint	Basement	G	G	No		
Fire door insulation	Throughout the building, potentially in fire doors	G	G	No		
Glue daubs associated with 1'x1' ceiling tile	Gymnasium toilet rooms, storage rooms 3 and 5	G	G	No		
Glue daubs associated with 1'x1' ceiling tile	Basement storage room by gymnasium	D	D	No		Damaged ceiling tile and associated glue daubs
Transite™ paneling	Gym kitchen by water fountain	D	D	No		Cracked panel
Vibration isolation cloth	Attic	G	G	No		
Ceramic tile adhesive	Throughout toilet rooms and kitchen	G	G	No		
Vapor barrier/tar under wood floor	Gymnasium, throughout first and second floors	G	G	No		
Wood paneling glue	1 st floor town offices	G	G	No		
Duct wrap insulation	Throughout toilet rooms and second floor offices/rooms	G	G	No		
Blackboard/tackboard and associated adhesive	Throughout building	G	G	No		




PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Lillis Administration Building
50 East Street, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Sheetrock and associated joint/taping compound	First and second floor partition walls	G	G	No		
9"x9" floor tile and associated mastic - located under carpet and/or 12"x12" floor tiles	Throughout building	G	G	No		
9"x9" floor tile and associated mastic - located under carpet	Second floor copy room and office between room 6 and 7	D	D	No		
12"x12" floor tile and mastic	Throughout building	G	G	No		

Conditions: G = Good D = Damaged SD = Significant damage

Surveillance conducted by: Kristopher Girtory (000674/CT)

 (Signature)

I, the LEA's Designated Person, have read and understood the findings noted above:

Name: _____
 Date: _____

**Asbestos Periodic Surveillance Inspection
Winter 2009
Northville Elementary School**

**New Milford Public Schools
386 Danbury Road
New Milford, Connecticut**

January 2009



**Fuss & O'Neill EnviroScience, LLC
56 Quarry Road
Trumbull, Connecticut 06611**

**NORTHVILLE ELEMENTARY SCHOOL
PERIODIC SURVEILLANCE REPORT
NEW MILFORD, CONNECTICUT**

On January 14, 2009, Fuss & O'Neill EnviroScience, LLC (EnviroScience's) representative, Kristopher Girton performed routine surveillance for Northville Elementary School under the Periodic Surveillance program as described in the AHERA regulations. The surveillance assessments were conducted in order to update the condition of known and assumed asbestos containing building materials (ACBM) and to identify areas where corrective measures may be required. The most recent Asbestos Management Plan Three-Year Update and Periodic Surveillance Report for Northville Elementary School were referenced. These are the most recent Asbestos Management Plans for the School.

Periodic surveillance involves the visual reassessment of any ACBM or assumed ACBM listed in the Asbestos Management Plan (AMP) for each school. The date of the periodic surveillance, as well as the location of each area, was noted along with the change in the condition of the ACBM, if any. Completed inspection forms are included in this report. The Asbestos Inspector's license is also included in this report.

All ACBM found in the school is listed on the attached periodic surveillance report. Changes in ACBM assessment are listed below. "Changes" can include conditions, and/or locations of ACBM that were not assessed in the last six-month inspection. ACBM that was previously identified as present and has been removed is listed below.

LOCATION	ASSESSMENT
Chapter One Room, Classrooms 20, 25/26, 27, 34	Carpeting and Carpet Mastic reported to have been removed April Vacation and Summer 2008. 12"x12" Floor Tile now present in these areas.

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Northville Elementary School
22 Hipp Rd, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Pipe and/or pipe fitting insulation	Within walls and pipe chases	G	G	No		
Textured ceiling paint	Front entrance corridor	G	G	No		
Transite panels	Throughout window systems (below windows) – especially at interior courtyard	G	G	No		
Cove base and/or associated adhesives	Throughout building – corridors, classrooms, offices, storage rooms, toilet rooms, library, main office, principal's office, teacher's room, storage rooms, kitchen, and cafeteria	G	G	No		
Fire door insulation	Throughout building, potentially in fire door cores	G	G	No		
Sheetrock™ and associated joint/taping compound	Throughout building – corridors, classrooms, offices, storage rooms, toilet rooms, library, main office, principal's office, teacher's room, storage rooms, kitchen, boiler room, and cafeteria	G	G	No		

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Northville Elementary School
22 Hipp Rd, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Glue daubs associated with blackboards, tackboards, and mirrors	Throughout building – corridors, classrooms, offices, toilet rooms, library, main office, principal's office, teacher's room, kitchen, and cafeteria	G	G	No		
Floor tile mastic – black and yellow colored	Throughout building – corridors, classrooms, offices, storage rooms, toilet rooms, library, main office, principal's office, teacher's room, storage rooms, kitchen, and cafeteria	G	G	No		
Sink undercoating – various colors	Throughout classrooms, teacher's room, and nurse's room	G	G	No		
Vapor barrier/tar under wood flooring	Gymnasium	G	G	No		


PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Northville Elementary School
22 Hipp Rd, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Carpet Glue/Old Black Mastic	Throughout carpeted areas of building – library, classrooms, offices, and conference rooms	G	G	No		Chapter One Room, Classrooms 20, 25/26, 27, 34 Carpeting and Carpet Mastic reported to have been removed April Vacation and Summer 2008. 12'x12" Floor Tile now present in these areas. Room 9 and Music Room abated in 2007

Conditions: G = Good D = Damaged SD = Significant damage

Surveillance conducted by: Kristopher Girtor (000674/CT)

 (Signature)

I, the LEA's Designated Person, have read and understood the findings noted above: _____
 Date: _____

**Asbestos Periodic Surveillance Inspection
Winter 2009
Schaghticoke Elementary School**

**New Milford Public Schools
386 Danbury Road
New Milford, Connecticut**

January 2009



FUSS & O'NEILL
Disciplines to Deliver

**Fuss & O'Neill EnviroScience, LLC
56 Quarry Road
Trumbull, Connecticut 06611**


**SCHAGHTICOKE MIDDLE SCHOOL
PERIODIC SURVEILLANCE REPORT
NEW MILFORD, CONNECTICUT**

On January 14, 2009, Fuss & O'Neill EnviroScience, LLC (EnviroScience's) representative, Kristopher Girton performed routine surveillance for Schaghticoke Middle School under the Periodic Surveillance program as described in the AHERA regulations. The surveillance assessments were conducted in order to update the condition of known and assumed asbestos containing building materials (ACBM) and to identify areas where corrective measures may be required. The most recent Asbestos Management Plan Three-Year Updates and most recent six-month Periodic Surveillance Report for Schaghticoke Middle School were referenced. These are the most recent Asbestos Management Plans for the School.

Periodic surveillance involves the visual reassessment of any ACBM or assumed ACBM listed in the Asbestos Management Plan (AMP) for each school. The date of the periodic surveillance, as well as the location of each area, was noted along with the change in the condition of the ACBM, if any. Completed inspection forms are included in this report. The Asbestos Inspector's license is also included in this report.

All ACBM found in the school is listed on the attached periodic surveillance report. Changes in ACBM assessment are listed below. "Changes" may include conditions, and/or locations of ACBM that were not assessed in the last six-month inspection. ACBM that was previously identified as present and has been removed is listed below.

LOCATION	ASSESSMENT
Library	Floor Tile reported to have been removed Summer 2008.



FUSS & O'NEILL
EnviroScience, LLC

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Schaghticoke Middle School
23 Hipp Road, New Milford, Connecticut
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Pipe fitting insulation	Air handler rooms 11 & 12 (across from room 207), 13 & 14 (behind room 201), 15 & 16/chiller pump room (near room 222), and corridor by media center	G	G	No		
Pump insulation	Air handler room 15 & 16 (behind room 201)	G	G	No		
Black window sills	Throughout building	G	G	No		
Tackboard and blackboard adhesives	Throughout building	G	G	No		
Vapor barriers/tar paper located below wood flooring	Gymnasium and multi-purpose room	G	G	No		
Sheetrock and associated joint/taping compound	Throughout building	G	G	No		
Cove base – various colors and associated adhesives – various colors	Throughout building	G	G	No		


PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Schaghticoke Middle School
23 Hipp Road, New Milford, Connecticut
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
12"x12" older tan floor tile and associated mastic	Exercise room, two (2) gymnasium storage rooms, cafeteria storage room, custodial room, classroom 90, 92, 95, 107, 109, 112, 114, 123 (former room 121), 125 (former room 121), 188, tutor 1, two (2) entry ways (under carpet), two (2) closets across from classroom 109, bathroom across from 113A, corridor next to classroom 95 and associated four (4) practices rooms (new tile over black mastic in one room), and closets in classroom 108 and 110, and custodian closet across from classroom 224	G	G	No		Library was abated during Summer 2008. New Carpet is present. Black Mastic may remain under the Carpet.

Conditions: G = Good D = Damaged SD = Significant damage

Surveillance conducted by: Kristopher Girtton (000674)

 (Signature)

I, the LEA's Designated Person, have read and understood the findings noted above:
 Name: _____
 Date: _____

**Asbestos Periodic Surveillance Inspection
Winter 2009
Hill and Plain Elementary School**

**New Milford Public Schools
386 Danbury Road
New Milford, Connecticut**

January 2009



**Fuss & O'Neill EnviroScience, LLC
56 Quarry Road
Trumbull, Connecticut 06611**

**HILL AND PLAIN SCHOOL
PERIODIC SURVEILLANCE REPORT
NEW MILFORD, CONNECTICUT**


On January 14, 2009, Fuss & O'Neill EnviroScience, LLC (EnviroScience's) representative, Kristopher Girton, performed routine surveillance for Hill and Plain School under the Periodic Surveillance program as described in the AHERA regulations. The surveillance assessments were conducted in order to update the condition of known and assumed asbestos containing building materials (ACBM) and to identify areas where corrective measures may be required. The most recent Asbestos Management Plan Three-Year Updates and most recent six-month Periodic Surveillance Report for Hill and Plain School were referenced. These are the most recent Asbestos Management Plans for the School.

Periodic surveillance involves the visual reassessment of any ACBM or assumed ACBM listed in the Asbestos Management Plan (AMP) for each school. The date of the periodic surveillance, as well as the location of each area, was noted along with the change in the condition of the ACBM, if any. Completed inspection forms are included in this report. The Asbestos Inspector's license is also included in this report.

During a previous re-inspection, the Inspector observed damaged breaching on both boilers in the Boiler Room. EnviroScience collected three (3) samples of this suspect ACBM as required by AHERA regulations. This breaching material was found to be non-ACBM. **However, please note that this does not mean the boilers are "asbestos-free". Additional ACBM in the form of fire-bricks, gasket(s), roping, additional breaching(s), etc. may be present on or within the boilers.**

All ACBM found in the school is listed on the attached periodic surveillance report. Changes in ACBM assessment are listed below. "Changes" may include conditions, and/or locations of ACBM that were not assessed in the last six-month inspection. ACBM that was previously identified as damaged and remains in a damaged condition, is also listed below.

LOCATION	ASSESSMENT
Kindergarten Room 1	Damaged Pipe Insulation
Storage Room near Paraprofessional Office	New 12"x12" Floor Tiles are now present.



FUSS & O'NEILL
EnviroScience, LLC

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Hill and Plain Elementary School
60 Old Town Park Road, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Pipe and/or pipe fitting insulation	Kindergarten 1	D	D	No		
Pipe and/or pipe fitting insulation	Throughout building – tunnels, above ceilings in corridor, classrooms, cafeteria, storage areas, main office, and within pipe chases	G	G	No		
Interior boiler roping, gaskets, firebrick materials, etc.	Boiler room – within boilers one (1) and two (2)	G	G	No		
Plaster ceiling	Boiler room	G	G	No		
Vibration isolation cloth	Gymnasium (four locations)	G	G	No		
Sink undercoating – grey and black colored	Throughout building – office near OT/PT, kindergarten rooms 1, 2, and 3, classrooms 1-22, teacher's room, and main office storage room	G	G	No		
Glue daubs associated with blackboards/tackboards	Throughout building – corridors, classrooms, offices, library, main office, principal's office, teacher's room, storage rooms, and cafeteria	G	G	No		
Sheetrock™ and associated joint/taping compound	Throughout building – corridors, classrooms, offices, storage rooms, toilet rooms, library, main office, principal's office, teacher's room, storage rooms, kitchen, boiler room, and cafeteria	G	G	No		

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Hill and Plain Elementary School
60 Old Town Park Road, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Ductwork joint sealant and/or paper	Throughout building – corridors, classrooms, offices, storage rooms, toilet rooms, library, main office, principal's office, teacher's room, storage rooms, kitchen, boiler room, and cafeteria	G	G	No		
Black window sills	Throughout building – classrooms, offices, storage rooms, toilet rooms, library, principal's office, teacher's room, kitchen, and cafeteria	G	G	No		
Cove base and/or associated adhesives	Throughout building – corridors, classrooms, offices, storage rooms, toilet rooms, library, main office, principal's office, teacher's room, storage rooms, kitchen, boiler room, and cafeteria	G	G	No		
Transite™ paneling	Exterior overhangs – classrooms 21-26, classrooms 16-20, teacher's room – 10, classrooms 9-10, kindergarten 1 – kindergarten 3, classrooms 4 - custodian room	G	G	No		

PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Hill and Plain Elementary School
60 Old Town Park Road, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
12"x12" floor tile and/or associated mastic	Throughout building - with the exception of classrooms 23 and 24	G	G	No		
9"x9" floor tile and/or associated mastic	Throughout building - closets in kindergarten 1, 2, 3, classrooms 4, 5, (under 12x12 floor tile) 6, 7, 8, electrical closet near classroom 7, main office storage, main office (under carpet), assistant principal's office (under carpet), principal's office (under carpet), guidance room (under carpet), paraprofessional office (under carpet), psychology office (under carpet), storage room near paraprofessional office (under carpet) classrooms 15, 16, 17, 18, 19, storage room near classroom 19, classroom 21	G	G	No		Material is located under carpet and/or newer 12x12 floor tile in some locations. Storage Room near Paraprofessional Office, Carpeting removed and new 12"x12" Floor Tiles are now present. Room 4 reported to have been removed.

Conditions: G = Good
 D = Damaged
 SD = Significant damage

Surveillance conducted by: Kristopher Girton (000674/CT)

 (Signature)

I, the LEA's Designated Person, have read and understood the findings noted above:
 Date: _____

**Asbestos Periodic Surveillance Inspection
Winter 2009
Sarah Noble Intermediate School**

**New Milford Public Schools
386 Danbury Road
New Milford, Connecticut**

January 2009




**Fuss & O'Neill EnviroScience, LLC
56 Quarry Road
Trumbull, Connecticut 06611**

**SARAH NOBLE INTERMEDIATE SCHOOL
PERIODIC SURVEILLANCE REPORT
NEW MILFORD, CONNECTICUT**

On January 14, 2009, Fuss & O'Neill EnviroScience, LLC (EnviroScience's) representative, Kristopher Girton, performed routine surveillance for Sarah Noble Intermediate School under the Periodic Surveillance program as described in the AHERA regulations. The surveillance assessments were conducted in order to update the condition of known and assumed asbestos containing building materials (ACBM) and to identify areas where corrective measures may be required. The most recent Asbestos Management Plan Three-Year Update and most recent six-month Periodic Surveillance Report for Sarah Noble Intermediate School were referenced. These are the most recent Asbestos Management Plans for the School.

Periodic surveillance involves the visual reassessment of any ACBM or assumed ACBM listed in the Asbestos Management Plan (AMP) for each school. The date of the periodic surveillance, as well as the location of each area, was noted along with the change in the condition of the ACBM, if any. Completed inspection forms are included in this report. The Asbestos Inspector's license is also included in this report.

All ACBM found in the school is listed on the attached periodic surveillance report



PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
Facility Address: Sarah Noble Intermediate School
25 Sunny Valley Road, New Milford, CT
Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Table with 6 columns: Asbestos Containing Material, Location, Previous Condition, Present Condition, Change in Condition (Yes/No), Quantity Damaged, Comments. Row 1: Brown mastic for older tackboards and blackboards; Hallway wall in rooms 156, 155, 154, 153, 157, 214, 212, 208, 206, 207, 202, 110, 108, 106A, 106, 104, 102A, 101, 103, 105, 107, 109, 111, 113; south wall of rooms 158, 202, 103; north wall of room 110, northwest corner of room 103, hallway in back of room 158; G, G, No, Material is enclosed in sheetrock walls

Conditions: G = Good D = Damaged SD = Significant damage

Surveillance conducted by: Kristopher Girton (000674/CT) (Signature)

I, the LEA's Designated Person, have read and understood the findings noted above:

Name:
Date:

**Asbestos Periodic Surveillance Inspection
Winter 2009
Facilities Administration Building**

**New Milford Public Schools
386 Danbury Road
New Milford, Connecticut**

January 2009



**Fuss & O'Neill EnviroScience, LLC
56 Quarry Road
Trumbull, Connecticut 06611**




**FACILITIES ADMINISTRATION BUILDING
PERIODIC SURVEILLANCE REPORT
NEW MILFORD, CONNECTICUT**

On January 14, 2009, Fuss & O'Neill EnviroScience, LLC (EnviroScience's) representative, Kristopher Girton, performed routine surveillance for the Facilities Administration Building, 386 Danbury Road, under the Periodic Surveillance program as described in the AHERA regulations. The surveillance assessments were conducted in order to update the condition of known and assumed asbestos containing building materials (ACBM) and to identify areas where corrective measures may be required. These are the most recent Asbestos Management Plans for the School.

Periodic surveillance involves the visual reassessment of any ACBM or assumed ACBM listed in the Asbestos Management Plan (AMP) for each school. The date of the periodic surveillance, as well as the location of each area, was noted along with the change in the condition of the ACBM, if any. Completed inspection forms are included in this report. The Asbestos Inspector's license is also included in this report.

All ACBM found in the school is listed on the attached periodic surveillance report. Changes in ACBM assessment are listed below. "Changes" may include conditions, and/or locations of ACBM that were not assessed in the last six-month inspection. ACBM that was previously identified as damaged and has been repaired or removed is listed below.

LOCATION	ASSESSMENT
Basement	End Caps of Pipe Insulation are exposed.
Second Floor – Office	1'x1' Ceiling tiles are water damaged and falling from ceiling glue daubs.




PERIODIC SURVEILLANCE FORM

Local Education Agency (LEA): New Milford Public Schools, 386 Danbury Road
 Facility Address: Facilities Administration Building
386 Danbury Road, New Milford, CT
 Date of Surveillance: January 14, 2009

ACBM DAMAGE REPORT

Asbestos Containing Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Quantity Damaged	Comments
Pipe and/or Pipe Fitting Insulation	Basement	G	G	No		End Caps of Pipe Insulation is Exposed.
1'x1' Ceiling Tile and Associated Glue Daubs	Second Floor Secretary Office	D	D	No	6 SF	Water Damaged Tiles are falling from Ceiling Glue Daubs.

Conditions: G = Good D = Damaged SD = Significant damage

Surveillance conducted by: Kristopher Girton (000674/CT)

 (Signature)

I, the LEA's Designated Person, have read and understood the findings noted above:

Name: _____
 Date: _____

No. SI-0466



39 Spruce Street
East Longmeadow, MA

MATTHEW MYERS

Has attended an 24 hour Asbestos Training Course for Asbestos Site Inspectors on March 11-13, 1991 and has passed a written examination.

Course topics covered include Asbestos Types, Uses and Applications, Government Regulations, Health Effects, the Site Inspection, Bulk Sampling and Documentation, Respirators and Worker Protection.

COURSE INSTRUCTORS

Thomas E. Veratti

Thomas E. Veratti, Vice President
Certified Chemical Engineer
Industrial Hygienist

Brenda Bolduc

Brenda Bolduc,
Training Dept. Manager
Expires March 13, 1992

Fuss & O'Neill EnviroScience, LLC

795 North Mountain Road, Newington, CT 06111 – (860) 953-2700

This is to certify that

Matthew Myers

SS#: xxx-xx-3305

has successfully completed the
4 Hr. Asbestos Inspector Refresher
Asbestos Accreditation under TSCA Title II
40 CFR Part 763


Ashis Roychowdhury, Principal Instructor

September 9, 2008

Date of Course

September 9, 2008 A-

Examination Date & Grade



Neal Freuden, Training Manager

AI-R-09/08-4

Certificate Number

September 9, 2009

Expiration Date

0003604 FP **PRSR T1 0 0864 06111

MATTHEW A. MYERS
FUSS & O'NEILL ENVIROSCIENCE LLC
795 NORTH MOUNTAIN RD
NEWINGTON CT 06111

Dear Licensed/Certified Professional,
Attached you will find your validated license/certification for the coming year. Should you have any questions about your license/certificate renewal, please do not hesitate to write or call:

Department of Public Health (860) 509-7603
P.O. Box 340308
M.S.#12MQA <http://www.dph.state.ct.us>
Hartford, CT 06134-0308

Sincerely,

J. ROBERT GALVIN, MD, MPH, COMMISSIONER
DEPARTMENT OF PUBLIC HEALTH

INSTRUCTIONS:

1. Detach and sign each of the cards on this form.
2. Display the large card in a prominent place in your office or place of business.
3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet card, place it in a secure place.

4. The employer's copy is for persons who must demonstrate current licensure/certification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT
THE INDIVIDUAL NAMED BELOW IS LICENSED
BY THIS DEPARTMENT AS A
ASBESTOS CONSULTANT - INSP/MGMT PLANNER

MATTHEW A. MYERS

LICENSE NO. 000041
CURRENT THROUGH 04/30/09
VALIDATION NO. 03-639354

SIGNATURE
 COMMISSIONER

EMPLOYER'S COPY

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
NAME
MATTHEW A. MYERS

VALIDATION NO. 03-639354
LICENSE NO. 000041
CURRENT THROUGH 04/30/09
PROFESSION
ASBESTOS CONSULTANT-INSP/MGMT PLANNER

SIGNATURE
 COMMISSIONER

WALLET CARD

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
NAME
MATTHEW A. MYERS

VALIDATION NO. 03-639354
LICENSE NO. 000041
CURRENT THROUGH 04/30/09
PROFESSION
ASBESTOS CONSULTANT-INSP/MGMT PLANNER

SIGNATURE
 COMMISSIONER

EnviroScience Consultants, Inc.

795 North Mountain Road, Newington, CT 06111 – (860) 953-2700

This is to certify that

Kristopher Girton

20 Lance Lane, Milford, CT 06460


SS# [REDACTED]

has successfully completed the

24 Hr. Asbestos Inspector Initial Course

Asbestos Accreditation under TSCA Title II

40 CFR Part 763



Ashis Roychowdhury, Principal Instructor

January 3-5, 2007

Date of Course

January 5, 2007: A+

Examination Date & Grade


Neal Freuden, Training Manager

AI-I-01/07-4

Certificate Number

January 7, 2008

Expiration Date

EnviroScience Consultants, Inc.

795 North Mountain Road, Newington, CT 06111 – (860) 953-2700

This is to certify that

Kristopher Girton

20 Lance Lane, Milford, CT 06460

has successfully completed the
4 Hr. Asbestos Inspector Refresher
Asbestos Accreditation under TSCA Title II
40 CFR Part 763



James L. Scott, Principal Instructor

January 3, 2008

Date of Course

January 3, 2008 B+

Examination Date & Grade





Neal Friedman, Training Manager



AI-R-01/07-1


Certificate Number

January 3, 2009

Expiration Date

WALLET CARD
STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
NAME
KRISTOPHER GIRTON
VALIDATION NO. 03-759926
LICENSE NO. 000593
CURRENT THROUGH 12/31/09
PROFESSION
ASBESTOS CONSULTANT-PROJECT MONITOR
SIGNATURE  COMMISSIONER 

WALLET CARD
STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
NAME
KRISTOPHER GIRTON
VALIDATION NO. 03-759923
LICENSE NO. 000674
CURRENT THROUGH 12/31/09
PROFESSION
ASBESTOS CONSULTANT-INSPECTOR
SIGNATURE  COMMISSIONER 

WALLET CARD
STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
NAME
KRISTOPHER GIRTON
VALIDATION NO. 03-759935
CERTIFICATION NO. 002147
CURRENT THROUGH 12/31/09
PROFESSION
LEAD INSPECTOR
SIGNATURE  COMMISSIONER 