

# **Asbestos Hazard Emergency Response Act Three-Year Asbestos Re-Inspection and Management Plan Update**

for  
Sarah Noble Intermediate School

For Compliance with  
State of Connecticut Department of Public Health  
Asbestos-Containing Material in Schools Regulation  
(Sections 19a - 333-1 through 19a - 333-13)  
and  
EPA Asbestos Hazard Emergency Response Act  
(Title 40 CFR, Part 763, Subpart E)

**New Milford Public Schools**  
New Milford, Connecticut

March 2020



56 Quarry Road  
Trumbull, CT 06611



FUSS & O'NEILL

April 23, 2020

Mr. Kevin Munrett  
Facilities Manager  
New Milford Public Schools  
386 Danbury Road  
New Milford, CT 06776

**RE: Three-Year AHERA Asbestos Re-Inspection and Management Plan Update**  
**Re-Inspection Date: March 26, 2020**  
**Sarah Noble Intermediate School**  
**25 Sunny Valley Road, New Milford, CT**  
Fuss & O'Neill Project No. 20071230.C40

Dear Mr. Munrett:

Enclosed is the three-year AHERA Asbestos Re-Inspection and Management Plan Update report prepared by Fuss & O'Neill, Inc. for Sarah Noble Intermediate School located at 25 Sunny Valley Road in New Milford, Connecticut (the "Site"). The inspection was performed for New Milford Public Schools (the "Client"). This report is an important document that must be kept on file at the school as well as at a central location where the Management Plans are maintained.

If you should have any questions regarding this report, please do not hesitate to contact me. Thank you for this opportunity to have served your environmental needs.

Sincerely,

Eduardo Miguel Marques  
Senior Environmental Analyst

56 Quarry Road  
Trumbull, CT  
06611

t 203.374.3748  
800.286.2469  
f 203.374.4391

[www.fando.com](http://www.fando.com)

EMM/nw

Enclosure

California  
Connecticut  
Maine  
Massachusetts  
New Hampshire  
Rhode Island  
Vermont

# Table of Contents

## Asbestos Hazard Emergency Response Act Three-Year Re-Inspection and Management Plan Update Sarah Noble Intermediate School New Milford Public Schools

---

<b>1</b>	<b>Introduction .....</b>	<b>1</b>
	1.1 Background .....	1
	1.2 Local Education Agency (LEA) Responsibilities .....	1
	1.3 Accreditation .....	2
<b>2</b>	<b>Building and Mechanical System Description .....</b>	<b>3</b>
<b>3</b>	<b>Three Year Re-Inspection.....</b>	<b>4</b>
	3.1 Re-Inspection Procedures .....	4
<b>4</b>	<b>Re-Inspection Report.....</b>	<b>4</b>
	4.1 Review of Existing Records .....	4
	4.2 Re-Inspection Summary.....	4
	4.3 Newly Identified or Re-sampled ACBM Materials .....	8
	4.4 Physical Assessment of ACBM .....	9
<b>5</b>	<b>Management Plan Update .....</b>	<b>10</b>
	5.1 Recommended Response Actions.....	10
	5.2 Periodic Surveillance .....	11
	5.3 Preventive Measures.....	11
	5.4 Abatement (Removal) Cost Estimates .....	11
<b>6</b>	<b>EPA Accreditation Requirements .....</b>	<b>12</b>

### Appendices

End of Report

APPENDIX A	EXISTING RECORDS CHECKLIST
APPENDIX B	RE-INSPECTION FORM 1A
APPENDIX C	RE-INSPECTION FORM 1B
APPENDIX D	RE-INSPECTION FORM 2
APPENDIX E	SAMPLE 6-MONTH PERIODIC SURVEILLANCE FORM
APPENDIX F	PREVENTIVE MEASURES
APPENDIX G	ASBESTOS INSPECTOR AND MANAGEMENT PLANNER STATE LICENSES AND EPA ACCREDITATIONS

# 1 Introduction

---

## 1.1 Background

The Clean Air Act required the United States Environmental Protection Agency (EPA) to develop standards to address the potential health risks associated with adverse effects of asbestos exposure as an indoor contaminant. In October 1986, the EPA promulgated the Asbestos Hazard Emergency Response Act (AHERA) located at Title 40 CFR, Part 763, Subpart E.

The AHERA regulations required that local education agencies (LEAs) conduct inspections of each school building that they lease, own, or otherwise use as a school building to identify friable (easily crumbled or crushed to powder by hand pressure) and non-friable asbestos-containing building materials (ACBM) locations. The original inspections were required to have been completed prior to October 12, 1988.

AHERA also requires that any building leased or acquired on or after October 12, 1988 that is to be used as a school building shall be inspected for friable and non-friable ACBM prior to use as a school building. In the event of an emergency use of a building that has not been inspected for ACBM, the building shall be inspected within 30 days after commencement of such use.

The regulatory requirements remain in effect for private or public school systems, a church-affiliated school of any denomination, a school dedicated to the education of children with special needs, or a charter school. In the State of Connecticut, the Department of Public Health (CTDPH) is responsible for AHERA regulation enforcement.

---

## 1.2 Local Education Agency (LEA) Responsibilities

- A. The LEA is responsible for compliance with the AHERA regulation. The following responsibilities must be followed:
1. The LEA must designate a person to ensure that all of the AHERA requirements are properly implemented. The Designated Person must receive adequate training to perform their duties.
  2. The LEA must ensure that management plans are maintained in a central location, as well as at each facility, and such plans and records are available for inspection or review at all times.
  3. The LEA must inform all workers, building occupants or their legal representative in writing at least once per school year about asbestos-related activities, and the availability of the AHERA management plans for the school buildings.

4. The LEA must ensure proper accreditation for all persons who perform asbestos inspections, asbestos re-inspections, develop/update management plans, develop response actions, and perform required response actions including operations and maintenance (O&M) activities that may disturb asbestos.
5. The LEA must provide training for all custodial and maintenance staff who regularly perform building maintenance where ACBM are present. The training must be provided upon initial hire, as well as annual updates.
6. The LEA must provide information (disclosure) to any workers who may perform work and may come into contact with asbestos in school buildings where ACBM or presumed ACBM are present.
7. The LEA must ensure that known ACBM or presumed ACBM are provided with warning labels in routine maintenance areas.
8. The LEA must ensure that periodic surveillance is performed at least once every six months, after management plan implementation, in all school buildings that it leases, owns, or otherwise uses that contains ACBM or presumed ACBM.
9. The LEA must ensure that once every three years, after a management plan is implemented, a Re-Inspection is performed at each school building that it leases owns or otherwise uses that contains ACBM or presumed ACBM.

Refer to above-mentioned regulation for full requirements and responsibilities.

---

### 1.3 Accreditation

A. Local Education Agency (LEA):

LEA: New Milford Public Schools  
Address: 50 East Street  
New Milford, Connecticut  
Phone: (860) 355-8406  
Fax: (860) 210-4132

B. Designated Person:

Designated Person: Mr. Kevin Munrett  
Address: 386 Danbury Road  
New Milford, Connecticut  
Phone: (860) 354-6265  
Fax: (860) 210-2233

C. Asbestos Consultant:

Firm: Fuss & O'Neill, Inc.  
Address: 56 Quarry Road  
Trumbull, Connecticut  
Phone: (203) 374-3748  
Fax: (203) 374-4391

D. Asbestos Inspector:

Inspector: Benjamin Silverman  
CTDPH License #: 000349  
Expiration Date: 08/31/2020

E. Asbestos Management Planner:

Planner: Eduardo Miguel Marques  
CTDPH License #: 000201  
Expiration: 02/28/2021

## 2 Building and Mechanical System Description

The Sarah Noble Intermediate School was previously New Milford High School and was renamed in approximately 2001 when the new High School was constructed. The original building was reportedly built in 1962, with additions reportedly constructed in 1969, 1986, and in 1999. The original building is slab on grade construction with brick outer walls and a corrugated steel frame. The inner walls are constructed of concrete block. A suspended ceiling exists in most of the building creating a plenum space with water pipes and HVAC. Ventilation is provided by an air handling system which draws air into return ducts and supplies air by means of air handling units located in the roof, forcing air into each room by means of supply ducts. The administration offices are serviced by a central air conditioning system, independent of the main air handling system.

All areas of the school are serviced by a central boiler room. Heat is provided by two oil burning boilers, which convey heat through steam pipes that traverse the building through the pipe tunnels. The upper gymnasium and the administration offices are heated by a separate system of hot water heat. The pipe tunnels begin at the boiler room and are located below grade, throughout the perimeter of the building, branching up to the baseboard radiators located in each of the rooms. The pipe insulation and associated piping have been removed in the majority of the pipe tunnels.

The conversion of the New Milford High School into Sarah Noble Intermediate School involved extensive asbestos abatement. Abatement involved the removal of floor tile and associated mastic, pipe fitting insulation, asbestos cement science table tops, sinks, test tube racks, and hoods, asbestos cement panels, interior radiator insulating paper, and exterior window glazing compounds from throughout the building.

## 3 Three Year Re-Inspection

---

### 3.1 Re-Inspection Procedures

This three-year asbestos re-inspection was conducted in accordance with EPA requirements of the AHERA regulation, Title 40 CFR, Part 763, Section 763.85 (b).

On March 26, 2020, Fuss & O'Neill, Inc. (Fuss & O'Neill) representative Mr. Ben Silverman performed the re-inspection.

- A. During the re-inspection, Fuss & O'Neill conducted the following required tasks:
1. A visual re-inspection and reassessment of all known friable or assumed ACBM.
  2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has become friable.
  3. Identification and assessment of any newly-identified homogeneous area that contains friable ACBM since the last inspection or re-inspection.

## 4 Re-Inspection Report

---

### 4.1 Review of Existing Records

An important part of this AHERA re-inspection involved researching prior documentation that is required to be present at the school, as well as at the central recordkeeping location where management plans are stored.

Please see *Appendix A* for the checklist for existing records.

### 4.2 Re-Inspection Summary

The on-site portion of the re-inspection was documented on forms modeled after examples provided by the EPA and reviewed with the CTDPH. The first form, **Re-Inspection Form 1A**, identifies previous inspection data gathered during the initial AHERA inspection and subsequent re-inspection (see *Appendix B*). This form is useful to reference response actions (if any), which have been performed since the last inspection, as well as identifies the last known conditions of ACBM in the building. It additionally provides the inspector a “quick glance” reference when performing the re-inspection.

The second EPA form, **Re-Inspection Form 1B**, is used to list all known or assumed asbestos-containing materials that were previously unidentified (See *Appendix C*). It also lists the ACBM in areas newly-acquired by the school for student use either permanently or temporarily.

The third EPA form, **Re-Inspection Form 2**, was used to provide information and justification regarding re-assessment of the ACBM (see *Appendix D*). This form also provides response action recommendations, including a tentative schedule for completing response actions that recommend removal or repair.

No bulk samples were collected during this re-inspection.

Using EPA protocol and criteria, the following materials existing in Sarah Noble Intermediate School at the time of this three-year re-inspection have been determined and/or assumed to be **ACBM**. Please refer to the above-mentioned Re-Inspection Forms for specific locations of the materials.

**Table 1**  
**Asbestos-Containing Building Materials**

<b>Material</b>	<b>Location</b>	<b>Reference</b>	<b>Asbestos Content</b>
Brown Mastic Associated with Blackboards and Tack Boards – (material enclosed within sheetrock walls)	Classrooms and Corridors	EnviroScience 2017 AHERA Inspection	Assumed
Adhesive Associated with Blackboards & Tack Boards	Classrooms	EnviroScience 2017 AHERA Inspection	Assumed
White Fire Door Insulation	Throughout Building	EnviroScience 2017 AHERA Inspection	5% Vermiculite
White Pipe Insulation	Tunnels and Wall Cavities	EnviroScience 2017 AHERA Inspection	Assumed
White Mudded Pipe Fitting Cement	Boiler Room (2 fittings per boiler)	Fuss & O'Neill AHERA Surveillance	Assumed
White Roping Associated with Old Water Tank Exhaust	Boiler Room	EnviroScience 2017 AHERA Inspection	Assumed
Cloth Wrap on Ducts	Boiler Room, Throughout Building Within Walls and Plenum Space	EnviroScience 2017 AHERA Inspection	Assumed
Duct Insulation Glue	Boiler Room, Throughout Building Within Walls and Plenum Space	EnviroScience 2017 AHERA Inspection	Assumed
Gray Duct Sealant	Throughout Building Within Walls and Plenum Space	EnviroScience 2017 AHERA Inspection	Assumed
White 12" x 12" Floor Tiles (Multicolor Pattern) and Associated Adhesive	Classrooms and Corridors	EnviroScience 2017 AHERA Inspection	Assumed



<b>Material</b>	<b>Location</b>	<b>Reference</b>	<b>Asbestos Content</b>
Blue 12" x 12" Floor Tiles (Multicolor Pattern) and Associated Adhesive	Classrooms and Corridors	EnviroScience 2017 AHERA Inspection	Assumed
Multicolor Pattern 12" x 12" Floor Tiles (Blue-Yellow- Red-Green-Black) and Associated Adhesive	Classrooms and Corridors	EnviroScience 2017 AHERA Inspection	Assumed
White with Blue Specks 12" x 12" Floor Tiles and Associated Adhesive	Cafeteria	EnviroScience 2017 AHERA Inspection	Assumed
Tan with Tan and Black/Dark Brown Streaks 12" x 12" Floor Tiles & Associated Adhesive	Ramp near Loading Dock at Cafeteria	EnviroScience 2017 AHERA Inspection	Assumed
Light Blue 12" x 12" Floor Tile and Associated Adhesive	Rooms 160 A, B, C, and D	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Off-White Pebbled Sheet Flooring and Associated Adhesive	Growing Room 186	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Yellow Carpet Glue	Rooms 136,159, 161,163, 163A, 173, 205, 205A, 205C, 205D, 206, 206A, Media Center, and Main Offices	EnviroScience 2017 AHERA Inspection	Assumed
Black 4" Cove Base and Associated Adhesive	Rooms 160 A, B, C, and D	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Black Paper/Mastic	Gymnasium underneath Hardwood Floor	EnviroScience 2017 AHERA Inspection	Assumed
Blue Epoxy Floor Coating	Kitchen, Custodial Closet 101A	EnviroScience 2017 AHERA Inspection	Assumed
Gray Epoxy Floor Coating	Boy's Bathrooms 115, 170, and 238; Girl's Bathrooms 114, 166, and 236	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Gray Ceramic Floor Tiles and Associated Grout and Adhesive	Bathrooms and Custodial Closets	EnviroScience 2017 AHERA Inspection	Assumed
Adhesive Associated with Gray Rubber Stair Treads	Stairwells, Interior Corridor Stair at Elevator	EnviroScience 2017 AHERA Inspection	Assumed

<b>Material</b>	<b>Location</b>	<b>Reference</b>	<b>Asbestos Content</b>
Gray Ceramic Cove Base and Associated Grout and Adhesive	Bathrooms and Custodial Rooms	EnviroScience 2017 AHERA Inspection	Assumed
Tan Canvas Wall Covering and Associated Adhesive	Rooms 136, 136A, 206, 206A, and Media Center	EnviroScience 2017 AHERA Inspection	Assumed
White Gypsum Board & Joint/Taping Compound	Throughout Building	EnviroScience 2017 AHERA Inspection	Assumed
Gray Plaster Wall	Boiler Room & Records	EnviroScience 2017 AHERA Inspection	Assumed
Textured 2' x 2' Suspended Ceiling Tiles	Cafeteria, Front and Back Lobbies, Gymnasium, Nurse's Office, Nurse's Hallway, Main Office Suite, Music Classrooms 107 and 108	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Pinholes 2' x 2' Suspended Ceiling Tiles	Staff 127, 131A, 136, 136A, 160, 160A, 160C, 160D, 163, 163A, Hallways, Bathrooms, Media Center	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Pinholes 2' x 4' Suspended Ceiling Tiles	Classrooms, Hallways, Bathrooms	Fuss & O'Neill 2020 AHERA Inspection	Assumed
Gypsum 2' x 2' and 2' x 4' Suspended Ceiling Tiles	Kitchen, Serving 101, Office 101C, Bathroom 101D, Storage 101 H, Growing Room	Fuss & O'Neill 2020 AHERA Inspection	Assumed
White Sink Undercoating	Throughout Classrooms	EnviroScience 2017 AHERA Inspection	Assumed
Grey Sink Undercoating	Art Rooms 194, 195 & 196 (double sinks); Rooms 140, 173 & 208 (single sinks)	Fuss & O'Neill AHERA Surveillance	Assumed
Red Fire Stop Caulk	Throughout Building	EnviroScience 2017 AHERA Inspection	Assumed
Tan Backsplash Glue Daubs	Grade 3 Classrooms (Formerly Science Rooms)	EnviroScience 2017 AHERA Inspection	Assumed
Gray Interior Column Caulking	Throughout Building	EnviroScience 2017 AHERA Inspection	Assumed
Gray Floor Leveling Material	Throughout Building	EnviroScience 2017 AHERA Inspection	Assumed
White with Yellow, Brown, Black Ceramic Wall Tile and Associated Gray Grout and Adhesive	Kitchen	EnviroScience 2017 AHERA Inspection	Assumed

Material	Location	Reference	Asbestos Content
Stage Curtain	Stage	EnviroScience 2017 AHERA Inspection	Assumed
Interior Boiler Components	Boiler Room	EnviroScience 2017 AHERA Re-inspection	Assumed

Using the EPA protocol, samples of the following suspect materials were collected and analyzed. The analytical results indicated that these materials are **non-ACBM**:

**Table 2**  
**Non-Asbestos-Containing Building Materials**

Material	Location	Reference
Pipe Fitting Insulation	1970's Building	EnviroScience 2007 AHERA Inspection
Tan Mottled 12" x 12" Floor Tiles and Associated Tan Mastic	Rooms 189, 193, 231, Corridor outside Room 234	Fuss & O'Neill Bulk Sampling March 2018
Blue 4" Cove Base and Associated Adhesive	Classrooms and Corridors	Fuss & O'Neill Bulk Sampling

Mr. Eduardo Miguel Marques reviewed the information obtained during this Re-Inspection. Mr. Marques is an EPA-accredited and CTDPH-licensed Asbestos Management Planner.

### 4.3 Newly Identified or Re-sampled ACBM Materials

The following newly identified suspect ACBM have been identified in the building:

- Light Blue 12" x 12" Floor Tile and Associated Adhesive;
- Off-White Pebbled Sheet Flooring and Associated Adhesive;
- Black 4" Cove Base and Associated Adhesive;
- Gray Epoxy Floor Coating;
- Textured 2' x 2' Suspended Ceiling Tiles;
- Pinholes 2' x 2' Suspended Ceiling Tiles;
- Pinholes 2' x 4' Suspended Ceiling Tiles; and
- Gypsum 2' x 2' and 2' x 4' Suspended Ceiling Tiles.

These materials must be assumed to contain asbestos until laboratory analysis determine otherwise. These materials have been added to *Table 1* as assumed ACBM.

AHERA regulations pertain to interior identified or assumed ACBM and limited exterior ACBM. AHERA regulations do include ACBM located on exterior porticos, covered walkways, and mechanical equipment used to condition interior building air.

Any suspect material encountered during renovation/demolition/maintenance activities that is not specifically identified in the Asbestos Management Plan (AMP) as a non-ACM should be assumed to contain asbestos unless sample results indicate otherwise.

**Additional Information:**

- ACBM floor tile and associated mastics may exist below non-moveable objects such as cabinets, platforms, sheetrock walls, lockers, etc.;
- Samples of exterior building materials not covered under AHERA, such as caulking and glazing compounds, roofing materials and materials behind exterior walls and panels should be collected and analyzed to determine asbestos content prior to performing activities that would disturb them;
- Asbestos-containing vapor barriers and waterproofing materials may exist beneath wood floors, behind walls, exterior below ground surface foundations, etc.; and
- Subsurface cementitious pipe (i.e., asbestos cement pipe).

---

## 4.4 Physical Assessment of ACBM

During inspection, suspect ACBM were separated into three EPA categories. These categories are thermal system insulation (TSI), surfacing ACBM, and miscellaneous ACBM. TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe and fitting insulations, boiler insulation, and duct insulation. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACBM not listed in TSI or surfacing, such as sheet flooring, vinyl asbestos flooring, ceiling tiles, and construction mastics/adhesives.

Finally, ACBM were quantified in linear and/or square feet, depending on the nature of the material.

The ACBM identified during the inspection and still remaining in the school were re-assessed using the CTDPH and AHERA guidelines for assessment of ACBM. The following assessment categories are listed:

1. Damaged or significantly damaged TSI ACBM
2. Damaged friable surfacing ACBM
3. Significantly damaged friable surfacing ACBM
4. Damaged or significantly damaged friable miscellaneous ACBM
5. ACBM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining friable ACBM or friable suspected ACBM

Material locations, assessments, and recommended response actions are listed in the Re-Inspection forms.

## 5 Management Plan Update

### 5.1 Recommended Response Actions

Based on the inspection report, physical walk-through inspection, and existing ACBM conditions, the following response actions are recommended:

1. Removal – 20 SF of Gray Plaster Wall in Boiler Room & Records Room.
2. Repair – 1 SF of White Mudded Pipe Fitting Cement in the Boiler Room.
3. Enclosure – Not Applicable
4. Encapsulation – Not Applicable
5. Operations and Maintenance (O & M) – All remaining ACBM.

It should be noted that only ACBM with assessments of 1 or 2 are recommended for removal or repair. The remaining ACBM should be included in the O & M Program. The condition of these ACBM will be monitored until all of the ACBM have been completely removed from the building. A successful O & M Program includes the following elements:

- A. Cleaning: All areas of the school where friable ACBM or assumed friable ACBM are present should be cleaned at least once after completion of the initial inspection. Additional cleaning may be necessary if the Management Planner makes a written recommendation indicating the methods and frequency of such cleaning.
- B. O & M Activities: The LEA shall ensure that the procedures described below are followed to protect building occupants from O & M activities that may disturb known or assumed ACBM:
  1. Restrict entry into the area either by physically isolating or by scheduling.
  2. Post asbestos warning signs to prevent entry by unauthorized persons.
  3. Deactivate or temporarily shut off or divert the air-handling system to the area.
  4. Use proper work practices and engineering controls, such as wet methods, protective clothing, High Efficiency Particulate Air (HEPA) vacuums, mini-enclosures/glove bags, etc. to inhibit fiber migration.
  5. Place asbestos debris and other contaminated materials into a sealed, leak-tight container for disposal.
- C. Minor Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., disturbance of less than or equal to 3 linear/square feet of friable ACBM):
  1. Saturate the debris using wet method.
  2. Place the debris in a sealed, leak-tight container and clean the area.
  3. Repair the area of damaged ACBM with materials such as asbestos-free spackling, plaster or insulation or seal with an encapsulant.

- D. Major Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., disturbance of greater than 3 linear/square feet of friable ACBM):
1. Restrict entry into the area and post asbestos warning signs.
  2. Deactivate or temporarily shut off or divert the air handling system from the area to prevent fiber migration.
  3. The response action for any major fiber release episode must be prepared by EPA-accredited Asbestos Project Designers and conducted by EPA-accredited personnel.
  4. The LEA shall notify the CTDPH of any major fiber release episode within twenty-four hours of its occurrence and, if necessary, provide written notification as required by applicable federal and/or state regulations.

---

## 5.2 Periodic Surveillance

At least once every six months after an AMP is implemented, the LEA will conduct periodic surveillance in the school that contains ACBM or assumed ACBM. The person conducting periodic surveillance will visually inspect all areas in the school that where ACBM have been identified in the AMP, record the date of surveillance, their name, any changes in the ACBM condition and submit the record to the LEA Designated Person for inclusion in the AMP.

Please see *Appendix E* for the sample Periodic Surveillance Form that may be used for conducting periodic surveillance.

---

## 5.3 Preventive Measures

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that ACBM will become damaged, deteriorated, or delaminated.

Please see *Appendix F* for preventive measures designed for various types of ACBM that may exist in the school.

---

## 5.4 Abatement (Removal) Cost Estimates

Costs for abatement (removal) of damaged ACBM identified as recommended response actions are as follows:

**Table 3**  
**Abatement Cost Estimates**


<b>Material</b>	<b>Location</b>	<b>Quantity</b>	<b>Estimated Contractor Cost</b>
Gray Plaster Wall	Boiler Room & Records	20 SF	~\$2,400
White Mudded Pipe Fitting Insulation	Boiler Room	1 SF	~\$500


## 6 EPA Accreditation Requirements

The EPA accreditations and the CTDPH Asbestos Inspector licenses for Mr. Ben Silverman and Mr. Eduardo Miguel Marques are provided in *Appendix G*.

Report prepared by Senior Environmental Technician Ben Silverman.

Reviewed by:

  
Eduardo Miguel Marques  
Senior Environmental Analyst

  
Jared D. Smith, CSP  
Senior Project Manager

## **Appendix A**

---

### Existing Records Checklist



## Existing Records Checklist

Local Education Agency (LEA): New Milford Public Schools  
50 East Street  
New Milford, CT 06776

School Building: Sarah Noble Intermediate School

The following documentation is required to be present in both the LEA's office, as well as in a centralized location in the school administrative office. The information included in this checklist will be verified to be present and complete as part of three-year Re-Inspection.

DOCUMENTATION		LOCATION	
		School	LEA Office
1	Original AHERA Operations and Maintenance Plan/Inspection Report	*	Yes
2	Three Year Re-Inspection (First and All Subsequent Inspections)	*	Yes
3	Parents and Teachers Notifications (Annually Since Last Re-Inspection)	*	Yes
4	Designated Person Identification and Proper Training (Person Must Be Named and Have Appropriate Training)	*	Yes
5	Designated Person Periodic Surveillance (Once Every Six Months)	*	Yes
6	Maintenance Staff Awareness Training Records	*	Yes
7	Outside Vendor Awareness Notification	*	Yes
8	Asbestos Warning Signs and Labels (Required Posting in Boiler Rooms and Mechanical Spaces Only)	No	N/A
9	Response Action Records (Includes Any Abatement Conducted Since Last 3-Year Re-Inspection)	*	Yes

Comments: \* The Asbestos Management Plan (AMP) and support documentation is available electronically on the New Milford Public Schools website facilities page. Please refer to the Facilities page on the New Milford Public School website ([newmilfordps.org](http://newmilfordps.org)) for further information.

Inspector (LEA Office): Ben Silverman

Date: 3/26/2020

Inspector (School): Ben Silverman

Date: 3/26/2020

## **Appendix B**

---

### Re-Inspection Form 1A

School: New Milford Public Schools  
 Address: 25 Sunny Valley Road, New Milford, CT

 Building: Sarah Noble Intermediate School Date(s) of Original Inspection: 2007  
 Date(s) of Subsequent Re-Inspections: 2007, 2009, 2010, 2017, 2020

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
Assumed	Assumed ACM	Brown Mastic Associated with Blackboards and Tack Boards – (material enclosed within sheetrock walls)	Misc.	NF	5	Classrooms and Corridors	
Assumed	Assumed ACM	Adhesive Associated with Blackboards & Tack Boards	Misc.	NF	5	Classrooms	
0124BH-01A-C	5% Vermiculite	White Fire Door Insulation	Misc.	F	N/A	Throughout Building	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.
Assumed	Assumed ACM	White Pipe Insulation	TSI	F	7	Tunnels and Wall Cavities	
Assumed	Assumed ACM	White Mudded Pipe Fitting Cement	TSI	F	1/7	Boiler Room (2 fittings per boiler)	
Assumed	Assumed ACM	White Roping Associated with Old Water Tank Exhaust	Misc.	F	7	Boiler Room	
Assumed	Assumed ACM	Cloth Wrap on Ducts	Misc.	NF	5	Boiler Room, Throughout Building Within Walls and Plenum Space	
Assumed	Assumed ACM	Duct Insulation Glue	Misc.	NF	5	Boiler Room, Throughout Building Within Walls and Plenum Space	

School: New Milford Public Schools  
 Address: 25 Sunny Valley Road, New Milford, CT

 Building: Sarah Noble Intermediate School Date(s) of Original Inspection: 2007  
 Date(s) of Subsequent Re-Inspections: 2007, 2009, 2010, 2017, 2020

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
Assumed	Assumed ACM	Gray Duct Sealant	Misc.	NF	5	Throughout Building Within Walls and Plenum Space	
Assumed	Assumed ACM	White 12" x 12" Floor Tiles (Multicolor Pattern) and Associated Adhesive	Misc.	NF	5	Classrooms and Corridors	
Assumed	Assumed ACM	Blue 12" x 12" Floor Tiles (Multicolor Pattern) and Associated Adhesive	Misc.	NF	5	Classrooms and Corridors	
Assumed	Assumed ACM	Multicolor Pattern 12" x 12" Floor Tiles (Blue-Yellow- Red-Green- Black) and Associated Adhesive	Misc.	NF	5	Classrooms and Corridors	
Assumed	Assumed ACM	White with Blue Specks 12" x 12" Floor Tiles and Associated Adhesive	Misc.	NF	5	Cafeteria	
Assumed	Assumed ACM	Tan with Tan and Black/Dark Brown Streaks 12" x 12" Floor Tiles & Associated Adhesive	Misc.	NF	5	Ramp near Loading Dock at Cafeteria	

School: New Milford Public Schools  
 Address: 25 Sunny Valley Road, New Milford, CT

 Building: Sarah Noble Intermediate School Date(s) of Original Inspection: 2007  
 Date(s) of Subsequent Re-Inspections: 2007, 2009, 2010, 2017, 2020

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
Assumed	Assumed ACM	Yellow Carpet Glue	Misc.	NF	5	Rooms 136,159, 161,163, 163A, 173, 205, 205A, 205C, 205D, 206, 206A, Media Center, and Main Offices	
Assumed	Assumed ACM	Black Paper/Mastic	Misc.	NF	5	Gymnasium underneath Hardwood Floor	
Assumed	Assumed ACM	Blue Epoxy Floor Coating	Misc.	NF	5	Kitchen, Custodial Closet 101A	
Assumed	Assumed ACM	Gray Ceramic Floor Tiles and Associated Grout and Adhesive	Misc.	NF	5	Bathrooms and Custodial Closets	
Assumed	Assumed ACM	Adhesive Associated with Gray Rubber Stair Treads	Misc.	NF	5	Stairwells, Interior Corridor Stair at Elevator	
Assumed	Assumed ACM	Gray Ceramic Cove Base and Associated Grout and Adhesive	Misc.	NF	5	Bathrooms and Custodial Rooms	
Assumed	Assumed ACM	Tan Canvas Wall Covering and Associated Adhesive	Misc.	NF	5	Rooms 136, 136A, 206, 206A, and Media Center	
Assumed	Assumed ACM	White Gypsum Board & Joint/Taping Compound	Misc.	NF	5	Throughout Building	
Assumed	Assumed ACM	Gray Plaster Wall	Surf.	F	2	Boiler Room & Records	

School: New Milford Public Schools  
 Address: 25 Sunny Valley Road, New Milford, CT

 Building: Sarah Noble Intermediate School Date(s) of Original Inspection: 2007  
 Date(s) of Subsequent Re-Inspections: 2007, 2009, 2010, 2017, 2020

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
Assumed	Assumed ACM	White Sink Undercoating	Misc.	NF	N/A	Throughout Classrooms	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.
Assumed	Assumed ACM	Grey Sink Undercoating	Misc.	NF	N/A	Art Rooms 194, 195 & 196 (double sinks); Rooms 140, 173 & 208 (single sinks)	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.
Assumed	Assumed ACM	Red Fire Stop Caulk	Misc.	NF	5	Throughout Building	
Assumed	Assumed ACM	Tan Backsplash Glue Daubs	Misc.	NF	5	Grade 3 Classrooms (Formerly Science Rooms)	
Assumed	Assumed ACM	Gray Interior Column Caulking	Misc.	NF	5	Throughout Building	
Assumed	Assumed ACM	Gray Floor Leveling Material	Misc.	NF	5	Throughout Building	
Assumed	Assumed ACM	White with Yellow, Brown, Black Ceramic Wall Tile and Associated Gray Grout and Adhesive	Misc.	NF	5	Kitchen	

School: New Milford Public Schools  
 Address: 25 Sunny Valley Road, New Milford, CT

 Building: Sarah Noble Intermediate School Date(s) of Original Inspection: 2007  
 Date(s) of Subsequent Re-Inspections: 2007, 2009, 2010, 2017, 2020

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
Assumed	Assumed ACM	Stage Curtain	Misc.	NF	N/A	Stage	Not Regulated by AHERA; for Informational Purposes Only. Material must be Managed/Disposed of as ACM.
Assumed	Assumed ACM	Interior Boiler Components	TSI	F	5	Boiler Room	
Assumed	Assumed ACM	White Insulation associated with Old Water Tank	TSI	F	5	Boiler Room	Material not observed and removed from the inventory.
Assumed	Assumed ACM	Blue Cove Base and associated adhesive	Misc.	NF	5	Classrooms and Corridors	Materials tested and determined to be non-ACM. Materials removed from inventory.

 Information abstracted by: Ben Silverman Date: 3/26/2020

Material Category: TSI = Thermal System Insulation, Surf. = Surfacing, Misc. = Miscellaneous

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories:

1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM

## **Appendix C**

---

### Re-Inspection Form 1B



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date(s) of Original Inspection: 2007

 Address: 25 Sunny Valley Road, New Milford, CT

 Date(s) of Subsequent Re-Inspections: 2007, 2009, 2010, 2017, 2020

Homogeneous Material		Asbestos Content (%)	Material Category	Estimated Quantity (SF/LF)	Friability	Assessment Category (1-7)	Recorded Locations of Material for Each Assessment Category
Sample Number	Material Description						
Assumed	Light Blue 12" x 12" Floor Tile and Associated Adhesive	Assumed ACM	Misc.	840 SF	NF	5	Rooms 160 A, B, C, and D
Assumed	Off-White Pebbled Sheet Flooring and Associated Adhesive	Assumed ACM	Misc.	240 SF	NF	5	Growing Room 186
Assumed	Black 4" Cove Base and Associated Adhesive	Assumed ACM	Misc.	101 LF	NF	5	Rooms 160 A, B, C, and D
Assumed	Gray Epoxy Floor Coating	Assumed ACM	Misc.	1,680 SF	NF	5	Boy's Bathrooms 115, 170, and 238; Girl's Bathrooms 114, 166, and 236
Assumed	Textured 2' x 2' Suspended Ceiling Tiles	Assumed ACM	Misc.	23,150 SF	F	7	Cafeteria, Front and Back Lobbies, Gymnasium, Nurse's Office, Nurse's Hallway, Main Office Suite, Music Classrooms 107 and 108
Assumed	Pinholes 2' x 2' Suspended Ceiling Tiles	Assumed ACM	Misc.	11,000 SF	F	7	Staff 127, 131A, 136, 136A, 160, 160A, 160C, 160D, 163, 163A, Hallways, Bathrooms, Media Center
Assumed	Pinholes 2' x 4' Suspended Ceiling Tiles	Assumed ACM	Misc.	112,000 SF	F	7	Classrooms, Hallways, Bathrooms

## Re-Inspection Form 1 (B) – List of Previously-Unidentified Suspect ACBM

 School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date(s) of Original Inspection: 2007

 Address: 25 Sunny Valley Road, New Milford, CT

 Date(s) of Subsequent Re-Inspections: 2007, 2009, 2010, 2017, 2020

Homogeneous Material		Asbestos Content (%)	Material Category	Estimated Quantity (SF/LF)	Friability	Assessment Category (1-7)	Recorded Locations of Material for Each Assessment Category
Sample Number	Material Description						
Assumed	Gypsum 2' x 2' and 2' x 4' Suspended Ceiling Tiles	Assumed ACM	Misc.	3,990 SF	NF	5	Kitchen, Serving 101, Office 101C, Bathroom 101D, Storage 101 H, Growing Room

 Inspected by: Ben Silverman

 Date: 3/26/2020

Material Category: TSI = Thermal System Insulation, S = Surfacing, M = Miscellaneous

LF = Linear Feet; SF = Square Feet

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories:

1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM

## **Appendix D**

---

### Re-Inspection Form 2





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Brown Mastic Associated with Blackboards and Tack Boards

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Corridors and Classrooms (material enclosed within sheetrock walls)	NF	9,600 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Adhesive Associated with Blackboards & Tack Boards

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Classrooms	F	100 boilers	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: White Fire Door Insulation

Sample ID Number: 0124BH-01A-C

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building	F	220 doors	N/A	Not Regulated by AHERA; for Informational Purposes Only	Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____						
Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: White Pipe Insulation

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Tunnels and Wall Cavities	F	1,500 LF	7	Any remaining friable ACBM or friable suspected ACBM	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: White Mudded Pipe Fitting Cement

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boiler Room	F	1 SF	1	Damaged or significantly damaged TSI ACBM	Recommend Sampling Material to Confirm Asbestos Content Repair damaged material	Summer 2020
		3 SF	7	Any remaining friable ACBM or friable suspected ACBM	Recommend Sampling Material to Confirm Asbestos Content Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: White Roping Associated with Old Water Tank Exhaust

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boiler Room	F	4 LF	7	Any remaining friable ACBM or friable suspected ACBM	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Cloth Wrap on Ducts

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boiler Room, Throughout Building Within Walls and Plenum Space	NF	500 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Duct Insulation Glue

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boiler Room, Throughout Building Within Walls and Plenum Space	NF	500 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Gray Duct Sealant

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building Within Walls and Plenum Space	NF	200 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: White 12" x 12" Floor Tiles (Multicolor Pattern) and Associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Classrooms and Corridors	NF	36,800 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Blue 12" x 12" Floor Tiles (Multicolor Pattern) and Associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Classrooms and Corridors	NF	36,800 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____						
Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Multicolor Pattern 12" x 12" Floor Tiles (Blue-Yellow- Red-Green- Black) and Associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Classrooms and Corridors	NF	18,400 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: White with Blue Specks 12" x 12" Floor Tiles and Associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Cafeteria	NF	10,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						





School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Tan with Tan and Black/Dark Brown Streaks 12" x 12" Floor Tiles & Associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Ramp near Loading Dock at Cafeteria	NF	600 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Light Blue 12" x 12" Floor Tile and Associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 160 A, B, C, and D	NF	840 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Off-White Pebbled Sheet Flooring and Associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Growing Room 186	NF	240 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Yellow Carpet Glue

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 136,159, 161,163, 163A, 173, 205, 205A, 205C, 205D, 206, 206A, Media Center, and Main Offices	NF	27,500 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Black 4" Cove Base and Associated Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 160 A, B, C, and D	NF	101 LF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Black Paper/Mastic

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Gymnasium underneath Hardwood Floor	NF	10,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Blue Epoxy Floor Coating

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Kitchen, Custodial Closet 101A	NF	2,048 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Gray Epoxy Floor Coating

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boy's Bathrooms 115, 170, and 238; Girl's Bathrooms 114, 166, and 236	NF	1,680 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____						
Date: _____						







School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Gray Ceramic Floor Tiles and Associated Grout and Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Bathrooms and Custodial Closets	NF	7,320 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____						
Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Adhesive Associated with Gray Rubber Stair Treads

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Stairwells, Interior Corridor Stair at Elevator	NF	1,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Gray Ceramic Cove Base and Associated Grout and Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Bathrooms and Custodial Rooms	NF	750 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Tan Canvas Wall Covering and Associated Adhesive

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms 136, 136A, 206, 206A, and Media Center	NF	3,200 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: White Gypsum Board & Joint/Taping Compound

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building	NF	100,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Gray Plaster Wall

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boiler Room & Records	F	20 SF	2	Damaged friable surfacing ACBM	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	Summer 2020
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____						
Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Textured 2' x 2' Suspended Ceiling Tiles

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Cafeteria, Front and Back Lobbies, Gymnasium, Nurse's Office, Nurse's Hallway, Main Office Suite, Music Classrooms 107 and 108	F	23,150 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Pinholes 2' x 2' Suspended Ceiling Tiles

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Staff 127, 131A, 136, 136A, 160, 160A, 160C, 160D, 163, 163A, Hallways, Bathrooms, Media Center	F	11,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						







School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Pinholes 2' x 4' Suspended Ceiling Tiles

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Classrooms, Hallways, Bathrooms	F	112,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Gypsum 2' x 2' and 2' x 4' Suspended Ceiling Tiles

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Kitchen, Serving 101, Office 101C, Bathroom 101D, Storage 101 H, Growing Room	NF	3,990 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: White Sink Undercoating

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Classrooms	NF	500 SF	N/A	Not Regulated by AHERA; for Informational Purposes Only.	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Gray Sink Undercoating

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Art Rooms 194, 195 & 196 (double sinks); Rooms 140, 173 & 208 (single sinks)	NF	45 SF	N/A	Not Regulated by AHERA; for Informational Purposes Only.	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Red Fire Stop Caulk

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building	NF	1,500 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Tan Backsplash Glue Daubs

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Grade 3 Classrooms (Formerly Science Rooms)	NF	540 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <u>No</u>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Gray Interior Column Caulking

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building	NF	4,000 LF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: Gray Floor Leveling Material

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Throughout Building	NF	149,000 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

 Building: Sarah Noble Intermediate School

 Date of Re-Inspection: 3/26/2020

 Homogeneous Material: White with Yellow, Brown, and Black Ceramic Wall Tile and Associated Gray Grout and Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Kitchen	NF	2,400 SF	5	ACBM with potential for damage	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____  Date: _____						





School: New Milford Public Schools

Building: Sarah Noble Intermediate School

Date of Re-Inspection: 3/26/2020

Homogeneous Material: Stage Curtain

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Stage	NF	1,800 SF	N/A	Not Regulated by AHERA; for Informational Purposes Only.	Recommend Sampling Material to Confirm Asbestos Content  Maintain under O&M Plan	On-going
Were additional samples of this ACBM collected? <b>No</b>					Date of Management Planner Review: <u>4/13/2020</u>	
Inspector's Name: <u>Benjamin Silverman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000349 / CT</u> Expiration Date: <u>8/31/2020</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201 / CT</u> Expiration Date: <u>2/28/2021</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

## **Appendix E**

---

### Sample 6-Month Periodic Surveillance Form

### 6- Month Periodic Surveillance Form

Local Education Agency (LEA): New Milford Public Schools

Facility Address: Sarah Noble Intermediate School, 25 Sunny Valley Road, New Milford, CT

Date of Surveillance: \_\_\_\_\_

#### ACBM Damage Report

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
Brown Mastic Associated with Blackboards and Tack Boards – (material enclosed within sheetrock walls)	Classrooms and Corridors	IA	IA			
Adhesive Associated with Blackboards & Tack Boards	Classrooms	IA	IA			
White Fire Door Insulation	Throughout Building	IA	IA			Not Required by AHERA; for informational purposes only Material must be Managed and Disposed of as ACM Prior Disturbance
White Pipe Insulation	Tunnels and Wall Cavities	G/IA	G/IA			
White Mudded Pipe Fitting Cement	Boiler Room (2 fittings per boiler)	D			1 SF	Repair damaged elbow at boiler
White Roping Associated with Old Water Tank Exhaust	Boiler Room	G				
Cloth Wrap on Ducts	Boiler Room, Throughout Building Within Walls and Plenum Space	G				

<b>Asbestos-Containing Building Material</b>	<b>Location</b>	<b>Previous Condition</b>	<b>Present Condition</b>	<b>Change in Condition (Yes/No)</b>	<b>Estimated Damaged Quantity</b>	<b>Comments</b>
Duct Insulation Glue	Boiler Room, Throughout Building Within Walls and Plenum Space	G				
Gray Duct Sealant	Throughout Building Within Walls and Plenum Space	G				
White 12" x 12" Floor Tiles (Multicolor Pattern) and Associated Adhesive	Classrooms and Corridors	G				
Blue 12" x 12" Floor Tiles (Multicolor Pattern) and Associated Adhesive	Classrooms and Corridors	G				
Multicolor Pattern 12" x 12" Floor Tiles (Blue-Yellow-Red-Green- Black) and Associated Adhesive	Classrooms and Corridors	G				
White with Blue Specks 12" x 12" Floor Tiles and Associated Adhesive	Cafeteria	G				
Tan with Tan and Black/Dark Brown Streaks 12" x 12" Floor Tiles & Associated Adhesive	Ramp near Loading Dock at Cafeteria	G				
Light Blue 12" x 12" Floor Tile and Associated Adhesive	Rooms 160 A, B, C, and D	G				
Off-White Pebbled Sheet Flooring and Associated Adhesive	Growing Room 186	G				
Yellow Carpet Glue	Rooms 136,159, 161,163, 163A, 173, 205, 205A, 205C, 205D, 206, 206A, Media Center, and Main Offices	IA	IA			

<b>Asbestos-Containing Building Material</b>	<b>Location</b>	<b>Previous Condition</b>	<b>Present Condition</b>	<b>Change in Condition (Yes/No)</b>	<b>Estimated Damaged Quantity</b>	<b>Comments</b>
Black 4" Cove Base and Associated Adhesive	Rooms 160 A, B, C, and D	G				
Black Paper/Mastic	Gymnasium underneath Hardwood Floor	IA	IA			
Blue Epoxy Floor Coating	Kitchen, Custodial Closet 101A	G				
Gray Epoxy Floor Coating	Boy's Bathrooms 115, 170, and 238; Girl's Bathrooms 114, 166, and 236	G				
Gray Ceramic Floor Tiles and Associated Grout and Adhesive	Bathrooms and Custodial Closets	G				
Adhesive Associated with Gray Rubber Stair treads	Stairwells, Interior Corridor Stair at Elevator	IA	IA			
Gray Ceramic Cove Base and Associated Grout and Adhesive	Bathrooms and Custodial Rooms	G				
Tan Canvas Wall Covering and Associated Adhesive	Rooms 136, 136A, 206, 206A, and Media Center	G				
White Gypsum Board & Joint/Taping Compound	Throughout Building	G				
Gray Plaster Wall	Boiler Room & Records	D			20 SF	Material damaged
Textured 2' x 2' Suspended Ceiling Tiles	Cafeteria, Front and Back Lobbies, Gymnasium, Nurse's Office, Nurse's Hallway, Main Office Suite, Music Classrooms 107 and 108	G				

<b>Asbestos-Containing Building Material</b>	<b>Location</b>	<b>Previous Condition</b>	<b>Present Condition</b>	<b>Change in Condition (Yes/No)</b>	<b>Estimated Damaged Quantity</b>	<b>Comments</b>
Pinholes 2' x 2' Suspended Ceiling Tiles	Staff 127, 131A, 136, 136A, 160, 160A, 160C, 160D, 163, 163A, Hallways, Bathrooms, Media Center	G				
Pinholes 2' x 4' Suspended Ceiling Tiles	Classrooms, Hallways, Bathrooms	G				
Gypsum 2' x 2' and 2' x 4' Suspended Ceiling Tiles	Kitchen, Serving 101, Office 101C, Bathroom 101D, Storage 101 H, Growing Room	G				
White Sink Undercoating	Throughout Classrooms	G				Not Required by AHERA; for informational purposes only Material must be Managed and Disposed of as ACM Prior Disturbance
Grey Sink Undercoating	Art Rooms 194, 195 & 196 (double sinks); Rooms 140, 173 & 208 (single sinks)	G				Not Required by AHERA; for informational purposes only Material must be Managed and Disposed of as ACM Prior Disturbance
Red Fire Stop Caulk	Throughout Building	G				
Tan Backsplash Glue Daubs	Grade 3 Classrooms (Formerly Science Rooms)	IA	IA			
Gray Interior Column Caulking	Throughout Building	G				
Gray Floor Leveling Material	Throughout Building	IA	IA			

<b>Asbestos-Containing Building Material</b>	<b>Location</b>	<b>Previous Condition</b>	<b>Present Condition</b>	<b>Change in Condition (Yes/No)</b>	<b>Estimated Damaged Quantity</b>	<b>Comments</b>
White with Yellow, Brown, and Black Ceramic Wall Tile and Associated Gray Grout and Adhesive	Kitchen	G				
Stage Curtain	Stage	G				Not Required by AHERA; for informational purposes only Material must be Managed and Disposed of as ACM Prior Disturbance

Conditions: D = Damaged; G = Good; IA = Inaccessible; NA = Not Applicable; SF = Square Feet; LF = Linear Feet

Surveillance conducted by: \_\_\_\_\_  
 (print name) (signature)

I, the LEA's Designated Person, have read and understood the findings noted above: \_\_\_\_\_

Date: \_\_\_\_\_



## **Appendix F**

---

### Preventive Measures

## Preventive Measures for Various Asbestos-Containing Building Materials

### A. Surfacing Materials

“Surfacing Materials” means materials in a school building that are applied by spray, trowel, or otherwise applied to surfaces. These include sprayed-applied fireproofing materials on structural members, ceiling and wall plasters, or other materials applied to surfaces for acoustical, fireproofing, or other purposes.

Surfacing Materials are generally considered friable and can release asbestos fibers if damaged by impact, air erosion, vibration, and/or water intrusion. When properly implemented, the following procedures will reduce the potential for fiber release:

#### 1. Sprayed-Applied Fireproofing

- a) Identify the materials and post warning signs on the laid-in or glued-in ceiling tile. If the decking is not covered, place the sign on the wall.
- b) Maintain the materials in intact state and undamaged condition. During winter, pigeons, squirrels and other rodents tend to roost in boiler/machine rooms and dislodge sprayed-applied fireproofing on the decking. Prevent such possibilities.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, enclosure is a temporary solution. Encapsulation of damaged sprayed-on fireproofing material is not recommended.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials. Please note that the repair/removal can only be performed by a licensed abatement contractor.

#### 2. Ceiling and Wall Plasters

- a) Identify the materials and post asbestos warning signs.
- b) Maintain the materials in intact state and undamaged condition. Avoid storing/stacking on/near the materials to reduce contact damage.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, repair or enclosure is a temporary solution.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials.

### B. Thermal System Insulation (TSI)

“Thermal System Insulation (TSI)” means insulating materials applied to pipes, pipe fittings, boilers, breechings, tanks, ducts, or other components to prevent process heat loss or gain, water condensation, or for other purposes (e.g., fire door insulation core).

TSI are generally considered friable ACBM. This means they can be easily damaged, increasing the potential for fiber release. When properly implemented, the following procedures will reduce the potential for fiber release:

1. Boiler and Breeching Insulation

- a) Identify the locations and label the boiler. Warning signs should be posted outside the boiler room.
- b) Reduce the likelihood of fiber release by ensuring that the insulation is not damaged. Avoid storing/stacking on/near the boiler to reduce contact damage.
- c) Maintain the insulation in intact state and undamaged condition. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Pipe, Pipe Fitting, Tank, Duct & Breeching Insulations

- a) Identify the locations and label the materials. Warning signs should be posted outside of rooms that have TSI materials.
- b) Reduce the likelihood of fiber release by ensuring that the materials are not damaged. Avoid storing/stacking near the materials to reduce contact damage.
- c) Maintain all TSI materials in intact state and undamaged condition. Inspect the protective jackets for damage. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

## **C. Miscellaneous Materials**

“Miscellaneous Materials” are the other ACBM in a school building that are not categorized as Surfacing Materials or TSI. These include floor tiles, floor tile and carpet mastics, gypsum wallboard and joint compound, ceiling tiles, glue daubs, asbestos cement panels, cove base and associated glue, window/door caulking and glazing compounds, etc. The following maintenance procedures are recommended for these materials:

1. Vinyl Asbestos Floor Tiles (VAT)

Vinyl Asbestos Floor Tiles (VAT) are considered non-friable, however routine maintenance procedures such as spray-buffing, burnishing, wet scrubbing, and stripping can generate asbestos fibers. Following procedures, when properly implemented, will reduce the potential of fiber release:

- a) Do not sand, grind, or abrade the tiles. Stripping of VAT should be done as infrequently as possible. When stripping becomes necessary, follow the appropriate work practices. Never perform dry stripping.
- b) During spray-buffing or burnishing the floor, operate the machine at the lowest workable speed and use the least abrasive pad. Use a wet mop for routine cleaning whenever possible.
- c) Routinely check whether chair and desk glides are in good condition and replace when necessary. Worn glides can gouge the floor and cause fiber release.
- d) Place carpets/floor mats in all entrances to reduce abrasion of floor tiles by sand and pebbles. During winter, have parking lots and walkways swept to the extent possible to avoid the tracking of salt and ice-melting compounds into the school by the students.
- e) Train the custodial people who are responsible for care and maintenance of VAT. Please note that the repair/removal can only be performed by a licensed abatement contractor.

## 2. Wallboard and Joint Compound Assembly

- a) Since a number of different homogeneous assemblies may exist in a building, sheetrock/joint compound must be assumed to be ACM unless sample results prove otherwise. If any specific areas are going to be disturbed, samples of the material in that area should be collected and analyzed.
- b) Reduce the likelihood of fiber release by avoiding cutting or drilling holes through the sheetrock panels.

## 3. Ceiling Tile and Glue Daubs

- a) Reduce the likelihood of fiber release by limiting access to the space above the ceiling tiles. Maintain the ceiling tiles in undamaged condition. Replace any damaged or water-stained tile.
- b) If the ceiling tiles are non-asbestos, collect samples and analyze the glue daubs to identify asbestos-content before disturbing the tiles.

## 4. Asbestos Cement Panels, Window/Door Caulking and Glazing Compounds

- a) Maintain asbestos cement panels and window/door caulking and glazing compounds in undamaged condition.

## 5. Carpet Glue, Blackboard/Tack Board Glue, Floor Tile Mastic, Cove Base, and Mastic

- a) Reduce the likelihood of fiber release by leaving materials in place.
- b) Maintain materials in good condition. Collect samples and analyze to identify asbestos-content before disturbing.

## **Appendix G**

---

### Asbestos Inspector and Management Planner State Licenses and EPA Accreditations

Dear BENJAMIN L SILVERMAN,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health  
P.O. Box 340308  
M.S.#12MQA  
Hartford, CT 06134-0308

(860) 509-7603  
opl.c.dph@ct.gov  
www.ct.gov/dph/license

Sincerely,

RENÉE D. COLEMAN-MITCHELL, MPH, COMMISSIONER  
DEPARTMENT OF PUBLIC HEALTH

**EMPLOYER'S COPY**

STATE OF CONNECTICUT  
DEPARTMENT OF PUBLIC HEALTH

NAME  
BENJAMIN L SILVERMAN

VALIDATION NO. 03-768866      CERTIFICATE NO. 000349      CURRENT THROUGH 08/31/20

PROFESSION  
ASBESTOS CONSULTANT-INSP/MGMT PLANNER

SIGNATURE      COMMISSIONER

**STATE OF CONNECTICUT  
DEPARTMENT OF PUBLIC HEALTH**

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED  
BY THIS DEPARTMENT AS A

**ASBESTOS CONSULTANT-INSP/MGMT PLANNER**

BENJAMIN L SILVERMAN

CERTIFICATE NO.  
**000349**

CURRENT THROUGH  
**08/31/20**

VALIDATION NO.  
**03-768866**

SIGNATURE

COMMISSIONER

**INSTRUCTIONS:**

1. Detach and sign each of the cards on this form
2. Display the large card in a prominent place in your office or place of business.
3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet card, place it in a secure place.
4. The employer's copy is for persons who must demonstrate current licensure/certification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.

**WALLET CARD**

STATE OF CONNECTICUT  
DEPARTMENT OF PUBLIC HEALTH

NAME  
BENJAMIN L SILVERMAN

VALIDATION NO. 03-768866      CERTIFICATE NO. 000349      CURRENT THROUGH 08/31/20

PROFESSION  
ASBESTOS CONSULTANT-INSP/MGMT PLANNER

SIGNATURE      COMMISSIONER

1000997-0001002-0000001 of 0000001-C01-at1d00101-1264-00999

# Certificate of Training

Awarded to

**BEN SILVERMAN**

*For successful completion of an 8 Hour, 1 Day*

**Asbestos Inspector & Management Planner  
Annual Refresher Training**

**JANUARY 22, 2020**

This training was approved and given in accordance with

Regulations for Connecticut State Agencies

RCSA 20-440 - 1-9 and RCSA 20-441 and meets the

requirements of the EPA Revised MAP under TSCA Title II of 4/4/94

*Presented by*

**Mystic Air Quality Consultants, Inc.**

**1204 North Road, Groton, CT 06340 (800) 247-7746**

Certificate Number: IMPR27986

Exam Grade: 97

Expiration Date: 01/22/2021



**Christopher J. Eident, CIH, CSP, RS**



**George Williamson, Training Director**

Richard Haffey, Training Director