

## **SIX-MONTH PERIODIC SURVEILLANCE**

**BEECHER ELEMENTARY SCHOOL**

**9/25/17**

### **HOMOGENEOUS AREAS CONTAINING ASBESTOS**

- 1 Thermal systems insulation in 1930  
Inaccessible, no visual inspection
- 10 Thermal systems insulation on pipe joints 1967 addition  
Inaccessible, no visual inspection
- 5 Thermal systems insulation aircell 1960 addition  
Inaccessible, no visual inspection
- 6 Thermal systems insulation in 1960 addition  
Inaccessible, no visual inspection
- 30-FD Fire doors 1930 building & Solid Core Wood Classroom Doors  
No maintenance required
- A Vinyl asbestos floor tile - 1930 building stairwell-9 x 9 light green  
No maintenance required  
  
Floor tile mastic - 1930 building stairwell-9 x 9 light green  
No maintenance required
- B Vinyl asbestos floor tile - 1930 building stairwell-12 x 12 light green  
No maintenance required  
  
Floor tile mastic - 1930 building stairwell-12 x 12 light green  
No maintenance required
- C Vinyl asbestos floor tile - 1930 building gym-9 x 9 brown  
Abated Summer 2014  
  
Floor tile mastic - 1930 building gym-9 x 9 brown  
Abated Summer 2014
- D Vinyl asbestos floor tile - 1960 addition classrooms 9 x 9 brown/tan  
No maintenance required
- E Vinyl asbestos floor tile - 1960 addition classrooms & corridor 9 x 9 green  
No maintenance required
- F Vinyl asbestos floor tile - 1960 addition classrooms 9 x 9 black/gray  
No maintenance required

- G Vinyl asbestos floor tile - 1967 addition gym, kitchen, storage areas 9 x 9 tan  
No maintenance required
- H Vinyl asbestos floor tile - 1960 addition maintenance office 9 x 9 brown  
No maintenance required
- I Vinyl asbestos floor tile - 1960 addition principal's office 9 x 9 light brown  
No maintenance required, carpet over
- J Vinyl asbestos floor tile - 1967 addition art, kindergarten, library 9 x 9 black/white  
No maintenance required
- K Vinyl asbestos floor tile - 1967 addition 1 classroom 9 x 9 brown  
No maintenance required
- L Vinyl asbestos floor tile - 1967 addition multi-purpose & kitchen 9 x 9 light tan  
No maintenance required
- M Vinyl asbestos floor tile - 1967 addition corridor 9 x 9 green/white  
No maintenance required
- MMA Flooring mastic - 1960 addition  
No maintenance required
- NF-Q Transite board- 1967 addition multi-purpose room ceiling perimeter  
No maintenance required
- NF-T Vibration elimination cloth- 1967 addition multi-purpose room  
No maintenance required
- Ceiling tile mastic- 1967 addition multi-purpose room  
No maintenance required
- Vinyl asbestos floor tile - 1930 building gym entry 9 x 9 green  
No maintenance required
- Floor tile mastic -1930 building gym entry 9 x 9 green  
No maintenance required
- Laboratory countertops in 1967 addition art room  
No maintenance required
- Cove base - 1967 addition library, kitchen & kindergarten  
No maintenance required
- Cove base mastic - 1967 addition library, kitchen & kindergarten  
No maintenance required
- Vinyl stair treads - 1930 building  
No maintenance required

Vinyl stair treads mastic - 1930 building

No maintenance required

W Vinyl asbestos floor tile - 1967 addition classrooms 16 & 17 9 x 9 green

No maintenance required

X Floor tile & carpet mastics - 1930 building & additions

No maintenance required

Y Metal window glazing- 1930 building & additions

East windows abated Summer 2014

1960 Wing & West Windows abated Summer 2017

Terrazzo flooring- 1960 addition foyer

No maintenance required

Slate window sills - 1960 & 1972 additions

No maintenance required

## SIX-MONTH PERIODIC SURVEILLANCE

### BEECHER HIGH SCHOOL

9/25/17

#### HOMOGENEOUS AREAS CONTAINING ASBESTOS

- 2 Thermal systems insulation 1952 original building & 1970 addition  
Inaccessible, no visual inspection
- 3 Thermal systems insulation - elbows 1952 original building & 1970 addition  
Inaccessible areas, no visual inspection  
Accessible areas - No maintenance required
- 6 Thermal systems insulation - elbows 1970 addition  
Inaccessible, no visual inspection
- 1 Thermal systems insulation 1952 original building pipe chases & above ceilings  
No maintenance required
- 1 Thermal systems insulation 1952 original building boiler room abated except hot water storage tank  
**Jacket loose on hot water storage tank**
- THJ Thermal systems insulation 1952 original building maintenance shop  
No maintenance required
- THP Thermal systems insulation 1952 original building maintenance shop  
No maintenance required
- MMP Textured plaster ceilings - 1952 original building classrooms, corridors & offices  
No maintenance required
- 5 2 x 4 layin ceiling tile - 1970 addition  
No maintenance required
- MMT Transite ceiling panels - 1952 original building boiler room & maintenance shop  
**2 Loose Panels Boiler Room Ceiling**
- A Vinyl asbestos floor tile - 1952 original building & 1970 addition 9 x 9 tan  
No maintenance required
- P Floor tile mastic - 1952 original building & 1970 addition 9 x 9 tan  
No maintenance required
- B Vinyl asbestos floor tile - 1952 original building & 1970 addition 9 x 9 brown  
No maintenance required
- P Floor tile mastic - 1952 original building & 1970 addition 9 x 9 brown

**SIX-MONTH PERIODIC SURVEILLANCE**

**BUS GARAGE**

**9/25/17**

Homogeneous Area (HA) Name

Drywall

No maintenance required

Drywall Joint Compound

No maintenance required

Unit heater flues

No maintenance required