

## Harney County School District #3 Radon Testing December 2021

- The EPA's recommended action level for radon is 4 pCi/L and would have required mitigation by the district, followed by retesting.
- All tests resulted in lower levels than the 4 pCi/L maximum

Site Name	Building Name	Room Description (per floor plan)	Kit serial #	Date Sampled	Type of test	Results (pCi/L)
District Office	Old Lincoln Junior High	Sped Files Classroom	7314371	2020-12-02	Detector kit	1.9
District Office	Old Lincoln Junior High	Sped Files Classroom	7314372	2020-12-02	Detector kit	1.5
District Office	Old Lincoln Junior High	Middle Classroom	7314373	2020-12-02	Detector kit	1.4
District Office	Old Lincoln Junior High	Old Home Ec Classroom	7314374	2020-12-02	Detector kit	1.1
District Office	Old Lincoln Junior High	Gymnasium	7314375	2020-12-02	Detector kit	0.7
District Office	Old Lincoln Junior High	Gymnasium	7314376	2020-12-02	Detector kit	< 0.3
BUS	Bus Garage	Office	7314378	2020-12-02	Detector kit	1.1
BUS	Bus Garage	Bus Garage	7314379	2020-12-02	Detector kit	1.3
BUS	Bus Garage	Bus Garage	7314380	2020-12-02	Detector kit	1.4
BUS	Bus Garage	Bus Garage	7314381	2020-12-02	Duplicate	1.3
SLTR	Slater Elementary School	Kitchen	7314383	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Cafeteria	7314384	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Cafeteria	7314385	2020-12-02	Duplicate	< 0.3
SLTR	Slater Elementary School	Music Room	7314386	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Speech Rooms	7314388	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Small office across from main	7314389	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Library	7314390	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 4	7314391	2020-12-02	Detector kit	0.6
SLTR	Slater Elementary School	Room 5	7314392	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 29	7314393	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 28	7314394	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 27	7314395	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 26	7314396	2020-12-02	Detector kit	0.9
SLTR	Slater Elementary School	Room 24	7314397	2020-12-02	Detector kit	1.1
SLTR	Slater Elementary School	Room 25	7314398	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Gymnasium	7314399	2020-12-02	Detector kit	0.7
SLTR	Slater Elementary School	Gymnasium	7314400	2020-12-02	Detector kit	0.6
SLTR	Slater Elementary School	Maintenance Shop	7314401	2020-12-02	Detector kit	0.6
SLTR	Slater Elementary School	Staff Work room	7314403	2020-12-02	Detector kit	0.7
SLTR	Slater Elementary School	Room 15	7314404	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 23	7314405	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 16	7314406	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 17	7314407	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 18	7314408	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 19	7314409	2020-12-02	Detector kit	0.8
SLTR	Slater Elementary School	Room 20	7314410	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 21	7314411	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 22	7314412	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 6	7314413	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 7	7314414	2020-12-02	Detector kit	0.8
SLTR	Slater Elementary School	Office #7	7314415	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 10	7314416	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 8	7314417	2020-12-02	Detector kit	< 0.3
SLTR	Slater Elementary School	Room 14	7314418	2020-12-02	Detector kit	< 0.3
BHS	Burns High School	Room 32	7314419	2020-12-02	Detector kit	0.9
BHS	Burns High School	Room 34	7314420	2020-12-02	Detector kit	< 0.3
BHS	Burns High School	Room 31	7316141	2020-12-02	Detector kit	1
BHS	Burns High School	Room 33	7316142	2020-12-02	Detector kit	1.2
BHS	Burns High School	Room 35	7316143	2020-12-02	Detector kit	0.8
BHS	Burns High School	Room 36	7316144	2020-12-02	Detector kit	1.2
BHS	Burns High School	Custodial office	7316145	2020-12-02	Detector kit	2.4
BHS	Burns High School	Room 37	7316146	2020-12-02	Detector kit	1.1
BHS	Burns High School	Room 38	7316147	2020-12-02	Detector kit	1.2
BHS	Burns High School	Ceramics Room	7316148	2020-12-02	Detector kit	0.8
BHS	Burns High School	Band Room	7316149	2020-12-02	Detector kit	1.4
BHS	Burns High School	Cafeteria	7316150	2020-12-02	Detector kit	1.2
BHS	Burns High School	Cafeteria	7316151	2020-12-02	Detector kit	1.4
BHS	Burns High School	Blank	7316152	2020-12-02	Duplicate	1.1

## Harney County School District #3 Radon Testing December 2021

- The EPA's recommended action level for radon is 4 pCi/L and would have required mitigation by the district, followed by retesting.
- All tests resulted in lower levels than the 4 pCi/L maximum

Site Name	Building Name	Room Description (per floor plan)	Kit serial #	Date Sampled	Type of test	Results (pCi/L)
BHS	Burns High School	Room 45 Woodshop	7316153	2020-12-02	Detector kit	0.7
BHS	Burns High School	Room 46 Weightroom	7316154	2020-12-02	Detector kit	0.8
BHS	Burns High School	Room 41	7316155	2020-12-02	Detector kit	0.8
BHS	Burns High School	Gymnasium	7316156	2020-12-02	Detector kit	0.8
BHS	Burns High School	Gymnasium	7316157	2020-12-02	Detector kit	0.6
BHS	Burns High School	Gymnasium	7316158	2020-12-02	Detector kit	0.8
BHS	Burns High School	Gymnasium	7316159	2020-12-02	Detector kit	0.9
BHS	Burns High School	Main office	7316160	2020-12-02	Detector kit	1.6
BHS	Burns High School	Library	7316161	2020-12-02	Detector kit	0.9
BHS	Burns High School	Room 30	7316162	2020-12-02	Detector kit	0.9
BHS	Burns High School	Room 13	7316163	2020-12-02	Detector kit	1.1
BHS	Burns High School	Room 12	7316164	2020-12-02	Detector kit	0.9
BHS	Burns High School	Room 11	7316165	2020-12-02	Detector kit	1.4
BHS	Burns High School	TVCC Building	7316166	2020-12-02	Detector kit	< 0.3
BHS	Burns High School	Room 23	7316167	2020-12-02	Detector kit	1.1
BHS	Burns High School	Room 22	7316168	2020-12-02	Detector kit	1.3
BHS	Burns High School	Room 25	7316169	2020-12-02	Detector kit	0.8
BHS	Burns High School	Room 24	7316170	2020-12-02	Detector kit	0.9
BHS	Burns High School	Room 26	7316171	2020-12-02	Detector kit	1.1
BHS	Burns High School	Room 18	7316172	2020-12-02	Detector kit	0.9
BHS	Burns High School	Room 17	7316173	2020-12-02	Detector kit	0.7
BHS	Burns High School	Room 14	7316174	2020-12-02	Detector kit	1.6
BHS	Burns High School	Room 19	7316175	2020-12-02	Detector kit	1.2
BHS	Burns High School	Room 27	7316176	2020-12-02	Detector kit	0.9
BHS	Burns High School	Room 29	7316177	2020-12-02	Detector kit	0.8
BHS	Burns High School	Room 28	7316178	2020-12-02	Detector kit	1.2
BHS	Burns High School	Room 16	7316179	2020-12-02	Detector kit	1.2
BHS	Burns High School	Room 15	7316180	2020-12-02	Detector kit	1.2
BHS	Burns High School	Welding Shop	7316181	2020-12-02	Detector kit	0.6
BHS	Burns High School	Welding Shop	7316182	2020-12-02	Detector kit	< 0.3
BHS	Burns High School	Auto Mechanics	7316183	2020-12-02	Detector kit	0.9
BHS	Burns High School	Auto Mechanics	7316184	2020-12-02	Detector kit	1.1
HMS	Hines Middle School	Room 29	7316186	2020-12-02	Detector kit	< 0.3
HMS	Hines Middle School	Room 28	7316187	2020-12-02	Detector kit	0.5
HMS	Hines Middle School	Room 27	7316188	2020-12-02	Detector kit	0.7
HMS	Hines Middle School	Room 26	7316189	2020-12-02	Detector kit	0.7
HMS	Hines Middle School	Room 25	7316190	2020-12-02	Detector kit	1.1
HMS	Hines Middle School	Room 23	7316191	2020-12-02	Detector kit	1
HMS	Hines Middle School	Speech Room	7316192	2020-12-02	Detector kit	0.9
HMS	Hines Middle School	Room 21	7316193	2020-12-02	Detector kit	0.6
HMS	Hines Middle School	Room 21	7316194	2020-12-02	Duplicate	0.8
HMS	Hines Middle School	Cafeteria	7316195	2020-12-02	Detector kit	0.7
HMS	Hines Middle School	Gymnasium	7316196	2020-12-02	Detector kit	< 0.3
HMS	Hines Middle School	Gymnasium	7316197	2020-12-02	Detector kit	0.6
HMS	Hines Middle School	Gymnasium	7316198	2020-12-02	Detector kit	< 0.3
HMS	Hines Middle School	Cafeteria	7316200	2020-12-02	Detector kit	1.5