# **WENDELL SCHOOL DISTRICT #232**

TEN YEAR FACILITIES PLAN [2019-2029]



August 21, 2018

# WENDELL SCHOOL DISTRICT #232

### TEN YEAR FACILITIES PLAN [2019-2029]

## **Table of Contents**

1	DESCRIPTION & HISTORY OF SCHOOL DISTRICT (Size and Schools)
2	PURPOSE OF THE SCHOOL DISTRICT FACILITIES
3	BUILDING & LAND STATISTICS (with Replacement Costs)
4	SCHOOL DISTRICT ENROLLMENT & PROJECTIONS
5	SCHOOL & DISTRICT ENROLLMENT & CAPACITIES
6	BUILDING CONDITION EVALUATION TABLES (Summary Ranges)
7	BUILDING CONDITION EVALUATION INSTRUMENTS (Condition Assessments
8	BUILDING CONDITION EVALUATION FORMS (Cost of Improvements)
9	BUILDING CONDITION EVALUATION FORM (Districtwide Totals)
10	CONCLUSION & ANALYSIS (Signatures' Sheet)

### **Description/History of the Wendell School District**

Wendell School District's first general school was built in 1908. A new elementary school was built in 1911. A new high school was built in 1920 where the Veteran's Memorial now stands. The District then added a gym next to the high school in 1937.

The elementary school was demolished in 1963 and a new one was then built on the same site. That same year a new middle school was built located where the Wendell City Hall is located.

The District built a new gymnasium in 1976 on land that was purchased where the high school and middle schools are now located. The gymnasium is still known as the "new gym" to many of the Wendell residents.

The high school students moved into a new building in 1994. The old high school building was then given to the middle school students for additional classrooms.

However, in 2001 the old high school building (housing middle school students) was condemned. For almost a year middle school students schedules were changed to attending school every other day, including Saturdays. These students were bussed to Gooding where they attended class on the site of the ISDB. The District passed a bond in 2003 to build a new school and students were then able to return to attend classes in their new middle school.

The District passed another bond to build a new elementary school during the 2012-13 school year which was built on the site of the existing elementary school.

Patrons have been very supportive of supplemental levies and have passed them throughout the past 12 to 14 years to help the district with teacher salaries. The supplemental levy was increased in 2014 to help the district fund much needed maintenance -- such as a new roof on the gym, recoating the high school roof, improving/replacing many aging HVAC systems, etc.

# # #

### Purpose of the Wendell School District's Facilities

Effective school maintenance protects the District's capitol investment, ensures the health and safety of the students -- supporting the overall educational performance of the entire Wendell Sch. District.

As Idaho's school buildings age – they face the growing challenge of maintaining school facilities at an appropriate level, which enables staff to meet the educational needs of their 21st century leaders.

The Wendell School Board and Administration currently developed this ten-year facilities plan. It includes applicable renovation and upgrades of both existing schools -- which supports contemporary instructional practices. At the same time, they are striving to develop and fine tune, more advanced technological facilities, which are demanding considerable expertise and financial commitments.

# WENDELL SCHOOL DISTRICT #232 [Facilities, Costs and Acreage]

			Acreage, Square Footage & Costs					
Land/Bldg. Statistics	Year of Const	Age of Facility	Total Land- Acreages	Total Building Square Footages	Re	Total Building placement Costs* (as of 2018)		
Elementary School (K-4)	2012	6	9	60,000	\$	11,700,000		
Middle School {5-8}	2003	15	10.5	57,608	\$	11,233,560		
High School {9-12}	1994	24	13.5	52,000	\$	10,140,000		
Gymnasium	1976	42	inc. above	24,300	\$	4,738,500		
Vo-Ag Shop	2003	15	inc. above	4,392	\$	658,800		
Welding & Maint. Shop	1948	70	0.5	7,000	\$	1,050,000		
District Office	1940	78	0.25	950	\$	185,250		
School District covers <b>115</b> square miles in total area	TOTALS	250	33.8	206,250	\$	39,520,860		
		Total Age of Bldgs	Total Land Acreages	Total Building Square Footages	Re	Total Building eplacement Costs (as of 2018)		

<sup>\*</sup> Sch. Building Costs @ \$195/sf Shops Costs @ \$150/sf

### ACTUAL ENROLLMENT - - WENDELL SCHOOL DISTRICT #232

	08-09	09-10	10-11	11-12	12-13	13-14	14-15	15-16	16-17	17-18	
K	94	82	98	122	74	96	97	91	84	79	K
1	92	92	81	92	124	76	104	102	91	87	1
2	97	90	87	84	92	120	72	104	108	85	2
3	88	85	88	81	90	85	120	72	99	108	3
4	83	90	89	99	86	87	93	112	76	100	4
K-4	454	439	443	478	466	464	486	481	458	459	K-4
5	81	82	94	98	94	89	85	89	102	68	5
6	85	76	84	93	88	89	80	83	97	106	6
7	64	78	85	88	93	83	85	85	81	101	7
8	86	71	93	85	84	86	78	81	88	79	8
5-8	316	307	356	364	359	347	328	338	368	354	5-8
9	78	90	78	91	88	89	90	85	76	82	9
10	. 76	84	85	75	88	83	84	84	88	68	10
11	74	72	76	78	62	79	72	74	79	74	11
12	81	70	79	70	71	64	72	70	72	64	12
9-12	309	316	318	314	309	315	318	313	315	288	9-12
Totals	1,079	1,062	1,117	1,156	1,134	1,126	1,132	1,132	1,141	1,101	Totals
Growth %		-2%	5%	3%	-2%	-1%	1%	0%	1%	4%	Growth %
Growth #		-17	55	39	-22	-8	6	0	9	-40	Growth #

#### PROJECTED ENROLLMENT -- WSD #232

	18-19	19-20	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	
K	79	79	79	79	79	79	79	79	79	79	K
1	79	79	79	79	79	79	79	79	79	79	1
2	87	79	79	79	79	79	79	79	79	7.9	2
3	85	87	79	79	79	79	79	79	79	79	3
4	108	85	87	79	79	79	79	79	79	79	4
K-4	438	409	403	395	395	395	395	395	395	395	K-4
5	100	108	85	87	79	79	79	79	79	79	5
6	68	100	108	85	87	79	79	79	79	79	6
7	106	68	100	108	85	87	79	79	79	79	7
8	101	106	68	100	108	85	87	79	79	79	8
5-8	375	382	361	380	359	330	324	316	316	316	5-8
9	79	101	106	68	100	108	85	87	79	79	9
10	82	79	101	106	68	100	108	85	87	79	10
11	68	82	79	101	106	68	100	108	85	87	11
12	74	68	82	79	101	106	68	100	108	85	12
9-12	303	330	368	354	375	382	361	380	359	330	9-12
Totals	1,116	1,121	1,132	1,129	1,129	1,107	1,080	1,091	1,070	1,041	Totals
Growth %	1%	0%	1%	0%	0%	-2%	-2%	1%	-2%	-3%	Growth %
Growth #	15	5	11	-3	0	-22	-27	11	-21	-29	Growth #

#### **ACTUAL ENROLLMENT - - WENDELL SCHOOL DISTRICT #232**

	08-09	09-10	10-11	11-12	12-13	13-14	14-15	15-16	16-17	17-18	
K	94	82	98	122	74	96	97	91	84	79	K
1	92	92	81	92	124	76	104	102	91	87	1
2	97	90	87	84	92	120	72	104	108	85	2
3	88	85	88	81	90	85	120	72	99	108	3
4	83	90	89	99	86	87	93	112	76	100	4
K-4	454	439	443	478	466	464	486	481	458	459	K-4
5	.81	82	94	98	94	89	85	89	102	68	5
6	85	76	. 84	93	88	89	80	83	97	106	6
7	64	78	85	88	93	83	85	85	81	101	7
8	86	71	93	85	84	86	′ 78	81	88	79	8
5-8	316	307	356	364	359	347	328	338	368	354	5-8
9	78	90	78	91	88	89	90	85	76	82	9
10	76	84	85	75	88	83	84	84	88	68	10
11	74	72	76	78	62	79	72	74	79	74	11
12	81	70	79	70	71	64	72	70	72	64	12
9-12	309	316	318	314	309	315	318	313	315	288	9-12
Totals	1,079	1,062	1,117	1,156	1,134	1,126	1,132	1,132	1,141	1,101	Totals
Growth %		-2%	5%	3%	-2%	-1%	1%	0%	1%	-4%	Growth %
Growth #		-17	55	39	-22	-8	6	0	9	-40	Growth #

#### PROJECTED ENROLLMENT -- WSD #232

	18-19	19-20	20-21	21-22	22-23	23-24	24-25	25-26	26-27	27-28	
K	80	81	81	82	83	84	85	86	86	87	K
1	80	81	81	82	83	84	85	86	86	87	1
2	88	81	81	82	83	84	85	86	86	87	2
3	86	89	81	82	83	84	85	86	86	87	3
4	109	87	90	82	83	84	85	86	86	87	4
K-4	442	417	415	411	415	419	423	428	432	436	K-4
5	101	110	88	91	83	84	85	86	86	87	5
6	69	102	111	88	91	84	85	86	86	87	6
7	107	69	103	112	89	92	85	86	86	87	7
8	102	108	70	104	114	90	93	86	86	87	8
5-8	379	390	372	395	377	350	347	342	346	349	5-8
9	80	103	109	71	105	115	91	94	86	87	9
10	83	81	104	110	71	106	116	92	95	87	10
11	69	84	81	105	111	72	107	117	93	96	11
12	75	69	84	82	106	113	73	108	118	94	12
9-12	306	337	379	368	394	406	387	411	393	365	9-12
Totals	1,127	1,144	1,166	1,175	1,187	1,175	1,158	1,181	1,170	1,150	Totals
Growth %	2%	1%	2%	1%	1%	-1%	-1%	2%	-1%	-2%	Growth %
Growth #	26	16	23	9	12	-11	-17	23	-11	-20	Growth #

### Wendell School District #232

# **Building Enrollment vs Capacity**

Grades	Elementay	Middle	High	Totals	Grades
K	79			79	K
1	87			87	1
2	85	8		85	2
3	108	5		108	3
4	100			100	4
5		68		68	5
6		106		106	6
7	±:	101	*	101	7
8		79		79	8
9			82	82	9
10			68	68	10
11			74	74	11
12			64	64	12
TOTAL ENROLL.	459	354	288	1,101	TOTAL ENROLL.
Estimated Bldg. Cap.	480	368	320	1,168	Estimated Bldg. Cap.
% Cap (2018-19)	96%	96%	90%	94%	% Cap (2018-19)

Elementary (K-4) 20 clrms x 24 = 480 (No portables) Middle (5-8) 16 clrms x 23 = 368 (No portables) High (9-12) 16 clrms x 20 = 320 (No portables)

	BUILDING CONDITION	EVALU	ATION	FORM				
School District	School Na	ame			Building Nu	ımber	s 2	
			RATI	NGS			<b>用历史的第三人</b>	
		GOOD	FAIR	POOR	UNSAT.			
COMPONENTS	SYSTEMS	(1)	(2)	(3)	(4)		COMM	IENTS
1.0 Exterior Building Condition	1.1 Foundation/Structure	+12	+8	+6	+4			
	1.2 Walls	+8	+5	+3	+1.			
	1.3 Roof	+7	+5	+2	0			
Component Score	1.4 Windows/Doors	+2	+1	0	0			
	1.5 Trim	+2	+1	0	0			
2.0 Interior Building Condition	2.1 Floors	+8	+5	+2	0			
	2.2 Walls	+8	+5	+1	0			
	2.3 Ceilings	+5	+3	+1	0			
Component Score	2.4 Fixed Equipment	+2	+1	0	0			
3.0 Mechanical Systems Condition	3.1 Electrical	+6	+4	+2	0			
*	3.2 Plumbing	+4	+2	+1	0			
	3.3 Heating	+6	+4	+2	+1			
Component Score .	3.4 Cooling	+6	+4	+2	+1			
	3.5 Lighting	+4	+3	+2	0			
4.0 Safety/Building Code	4.1 Means of Exit	+6	+4	+2	0			
	4.2 Fire Control Capability	+4	+3	+2	+1			
	4.3 Fire Alarm System	+4	+3	+2	+1			
Component Score	4.4 Emergency Lighting	+2	+1	0	0			
	4.5 Fire Resistance	+4	+3	+2	+1			
							Unadjusted	Adjusted
701	TAL COMPLETION COORES						Score	Score
10	TAL CONDITION SCORES							
			The second secon				8	
50 B 6 U A					T			
5.0 Provisions for Handicap Accessi		TEALS	NO	1111012				
6.0 Functional Adaptability	GOOD	FAIR	POOR	UNSAT.				E.
7.0 Suitability of Space	EXCEL GOOD	FAIR	POOR	UNSAT.				
Evolue	ator Name	Thete		Veer Duite			]	
Evalua	ator inallie	Date	L	Year Built			_Total Sq. Ft	

# **BCEF Scoring Table and Summary Ranges**

	COMPONENTS		GOOD	FAIR	POOR	UNSATISFACTORY
BCEF 1.0	Exterior Condition		2831	1827	1117	10 or less
BCEF 2.0	Interior Condition		2123	1320	412	3 or less
BCEF 3.0	Mechanical Systems		2326	1522	814	7 or less
BCEF 4.0	Safety/Building Codes		1820	1317	712	6 or less
		16				
	Total Scores		90100	6089	3059	29 or less

### **Summary of Building Condition Evaluation Scoring Range Recommendations**

Total Adjusted Scores	Recommendations for Consideration
90100	No renovation nor remodeling is needed.
7589	Problems developing; minor renovation/remodeling needed or should be scheduled soon.
5074	Serious problems are developing; renovation/remodeling costs should be considered if \$ is less than 50% of the replacement.
3149	Serious problems exist and need immediate attention; no type of renovation when the \$ is greater than 50% of replacement.
030	Major problems exist; building is dangerous to be occupied; very high maint. & operational; no renovation should occur & building(s) should be vacated (by students) as soon as possible.

Wendell School District #232

Elementary School (K-4)

	hat tylke tille skale i den den skale		RAT	INGS		
		GOOD	FAIR	POOR	UNSAT.	
COMPONENTS	SYSTEMS	(1)	(2)	(3)	(4)	COMMENTS
1.0 Exterior Building Condition	1.1 Foundation/Structure	+12	+8	+6	+4	
	1.2 Walls	+8	+5	+3	+1	
Good	1.3 Roof	+7	+5	+2	0	6 year old asphalt shingle roof
Component Score = 31	1.4 Windows/Doors	+2	+1	0	0	
	1.5 Trim	+2	+1	0	0	3
2.0 Interior Building Condition	2.1 Floors	+8	+5	+2	0	
λ	2.2 Walls	+8	+5	+1	0	
Good	2.3 Ceilings	+5	+3	+1	0	Some tiles need replaced
Component Score = 21	2.4 Fixed Equipment	+2	+1	0	0	
3.0 Mechanical Systems Condition	3.1 Electrical	+6	+4	+2	0	
	3.2 Plumbing	+4	+2	+1	0	
Good	3.3 Heating	+6	+4	+2	+1	
Component Score = 26	3.4 Cooling	+6	+4	+2	+1	A/C (indiv pulse units)
4	3.5 Lighting	+4	+3	+2	0	
4.0 Safety/Building Code	4.1 Means of Exit	+6	+4	+2	0	
*	4.2 Fire Control Capability	+4	+3	+2	+1	Yes is sprinkled
Good	4.3 Fire Alarm System	+4	+3	+2	+1	Simplex system is a problem
Component Score = 19	4.4 Emergency Lighting	+2	+1	0	0	
	4.5 Fire Resistance	+4	+3	+2	+1	
					·	
						Unadjusted Adjusted
Condo	N CONDITION COCCES	04				Score Score
Good Condition TOTA	AL CONDITION SCORES	91	6	0	0	97 97

5.0 Provisions for Handicap Accessibility

6.0 Functional Adaptability

7.0 Suitability of Space

	YES		NO			
	GOOD	FAIR	POOR	UNSAT.		
EXCEL	GOOD	FAIR	POOR	UNSAT.		

Rich Bauscher Evaluator Name

July 24, 2018 Date

2012 Year Built 60,000

Total Sq. Ft.

6 years Age of Facility

### **Elementary School** [K-4]

Square footage of building:

60,000

Conversion on BCEF

100 - 97 = 3%

Cost per/sf for upgrades\*

\$195

Mathematical calculation

 $60,000 \times 3\% = 1,800 \text{ sf}$ 

Upgrade calculation cost

1,800 sf x 195\* sf = \$351,000

Total upgrade cost

\$350,000

Suitability of Space Problems include the following items:

- 1) Narrow hallways
- 2) Insufficient science labs
- 3) Insufficient band room
- 4) Choir/music room in building
- 5) Auditorium in building
- 6) Art room in building
- 7) Library size adequate
- 8) Kitchen in building
- 9) Central air in building
- 10) Core areas to small for an expansion

Yes	or No
	No
1	N/A
1	N/A
1	N/A
	No
	No
	Yes
	Yes
,	Yes
	No

	Comments			
1				
-				

<sup>\* \$</sup> Provided by Beniton CM's

Wendell School District #232

Middle School (5-8)

			RAT	INGS	Visit Property		
		GOOD	FAIR	POOR	UNSAT.		
COMPONENTS	SYSTEMS	(1)	(2)	(3)	(4)	COMM	IENTS
1.0 Exterior Building Condition	1.1 Foundation/Structure	+12	+8	+6	+4		
	1.2 Walls	+8	+5	+3	+1		
Good	1.3 Roof	+7	+5	+2	0	15 year old meta	al roof
Component Score = 29	1.4 Windows/Doors	+2	+1	0	0	Dbl pane and ve	stibules
	1.5 Trim	+2	+1	0	0		
2.0 Interior Building Condition	2.1 Floors	+8	+5	+2	0		
	2.2 Walls	+8	+5	+1	0		
Good	2.3 Ceilings	+5	+3	+1	0	Some tiles need	replaced
Component Score = 21	2.4 Fixed Equipment	+2	+1	0	0		
3.0 Mechanical Systems Condition	3.1 Electrical	+6	+4	+2	0	1/3	
	3.2 Plumbing	+4	+2	+1	0		
Good	3.3 Heating	+6	+4	+2	+1		
Component Score = 23	3.4 Cooling	+6	+4	+2	+1	A/C Yes (need	new controler)
	3.5 Lighting	+4	+3	+2	0	T8s needed thro	
4.0 Safety/Building Code	4.1 Means of Exit	+6	+4	+2	0	70	
	4.2 Fire Control Capability	+4	+3	+2	+1	Yes is sprinkled	
Good	4.3 Fire Alarm System	+4	+3	+2	+1	Simplex system	is a problem
Component Score = 19	4.4 Emergency Lighting	+2	+1	0	0		***************************************
	4.5 Fire Resistance	+4	+3	+2	+1		
		1				Unadjusted	Adjusted
						Score	Score
Good Condition TOTA	AL CONDITION SCORES	74	18	0	0	92	92

5.0 Provisions for Handicap Accessibility

6.0 Functional Adaptability

7.0 Suitability of Space

	YES		NO		
	GOOD	FAIR	POOR	UNSAT.	
EXCEL	GOOD	FAIR	POOR	UNSAT.	

Rich Bauscher Evaluator Name

July 24, 2018 Date

2003 Year Built

57,608 Total Sq. Ft.

15 years Age of Facility

### Middle School [5-8]

Square footage of building:

57,608

Conversion on BCEF

100 - 92 = 8%

Cost per/sf for upgrades\*

\$195

Mathematical calculation

 $57,608 \times 8\% = 4,609 \text{ sf}$ 

Upgrade calculation cost

4,609 sf x \$195\* sf = **\$898,685** 

Total upgrade cost

\$890,000

Suitability of Space Problems include the following items:

- 1) Narrow hallways
- 2) Insufficient science labs
- 3) Insufficient band room
- 4) Choir/music room in building
- 5) Auditorium in building
- 6) Art room in building
- 7) Library size adequate
- 8) Kitchen in building
- 9) Central air in building
- 10) Core areas to small for an expansion

Y	es or No
	No
	No
	Yes
	No
	No
	No
	Yes
	Yes
100	Yes
	No

		_
1 lab		
1 Iau		
Use the HS	music room	
Use the HS	music room	
Use the HS	music room	

Comments

<sup>\* \$</sup> Provided by Beniton CM's

Wendell School District #232

High School (9-12)

POOR (3) +6 +3	UNSAT.		
+6		Villa	
	14	COM	MENTS
+3	+4	Some footing cra	cks .
	+1		
+2	0	24 yrs old (some	leaks)
0	0	Dbl pane	
0	0		
+2	0	Needs some new	carpet or tile
+1	0	1 cracked section	ĺ
+1	0		
0	0	Older units	
+2	0	At capacity	
+1	. 0	Need some new	sinks & toilets
+2	+1	1 Old boiler need	s replaced
+2	+1	Yes (Cooling tow	er needs replaced)
+2	0	T8s needed & fev	
+2	0		
+2	+1		
+2	+1	Simplex system i	s a problem
0	0	Few ballasts need	d replaced
+2	+1		
1		Unadjusted	Adjusted
설		Score	Score
0	0	76	76
5	5 0	5 0 0	Score

6.0 Functional Adaptability

7.0 Suitability of Space

	YES		NO	
	GOOD	FAIR	POOR	UNSAT.
EXCEL	GOOD	FAIR	POOR	UNSAT.

Rich Bauscher Evaluator Name July 24, 2018 Date 1994 Year Built 52,000 Total Sq. Ft.

#### High School [9-12]

Square footage of building:

52,000

Conversion on BCEF

100 - 76 = 24%

Cost per/sf for upgrades\*

.\$195

Mathematical calculation

 $52,000 \times 24\% = 12,400 \text{ sf}$ 

Upgrade calculation cost

 $12,400 \text{ sf x } 195* \text{ sf} = $2,433,600}$ 

Total upgrade cost

\$2.4 million

Suitability of Space Problems include the following items:

- 1) Narrow hallways
- 2) Insufficient science labs
- 3) Insufficient band room
- 4) Choir/music room in building
- 5) Auditorium in building
- 6) Art room in building
- 7) Library size adequate
- 8) Kitchen in building
- 9) Central air in building
- 10) Core areas to small for an expansion

Yes or	No
No	
No	
No	
Yes	

No

Shared wi	th 2 clrms	
Combo with	n Band	
Combo with	n Choir	
	<u></u>	

Comments

<sup>\* \$</sup> Provided by Beniton CM's

Wendell School District #232

High School (Gym)

<b>会发展的一种更多发展。这种是不是</b>	RATINGS						
		GOOD	FAIR	POOR	UNSAT.		
COMPONENTS	SYSTEMS	(1)	(2)	(3)	(4)	COM	MENTS
1.0 Exterior Building Condition	1.1 Foundation/Structure	+12	+8	+6	+4	Cracks and moist	ure from berms
	1.2 Walls	+8	+5	+3	+1	Brick uneven & no	eds painted
Fair	1.3 Roof	+7	+5	+2	0	2 year old metal r	oof
Component Score = 21	1.4 Windows/Doors	+2	+1	0	0	Sing pane Need	ls new entry drs
	1.5 Trim	+2	+1	0	0		
2.0 Interior Building Condition	2.1 Floors	+8	+5	+2	0	Cracks in cement 8	VB stan crooked
	2.2 Walls	+8	+5	+1	0	Cracks in blocks	
Fair	2.3 Ceilings	+5	+3	+1	0	Some ceiling tiles	need replaced
Component Score = 7	2.4 Fixed Equipment	+2	+1	0	0	Some older fixtur	9S
3.0 Mechanical Systems Condition	3.1 Electrical	+6	+4	+2	0	Older elec boxes	& @ capacity
4	3.2 Plumbing	+4	+2	+1	0 .	Faucets need replo	& rusting pipes
Poor	3.3 Heating	+6	+4	+2	+1	1 cracked heat ex	changer
Component Score = 9	3.4 Cooling	+6	+4	+2	+1	No A/C	
	3.5 Lighting	+4	+3	+2	0	T8s are needed th	roughout
4.0 Safety/Building Code	4.1 Means of Exit	+6	+4	+2	0	2 stories without r	amps
9 95	4.2 Fire Control Capability	+4	+3	+2	+1	Not sprinkled	
Poor	4.3 Fire Alarm System	+4	+3	+2	+1	Simplex system is	s a problem
Component Score = 11	4.4 Emergency Lighting	+2	+1	0	0	Some additional of	nes needed
	4.5 Fire Resistance	+4	+3	+2	+1	Wooden structure	<del>Mirota - 100 (100 (100 (100 (100 (100 (100 (10</del>
		T				Inadiusted	Adjusted
						Unadjusted Score	Adjusted Score
Poor Candidan TOT	AL CONDITION SCORES		25	44		in the second second	
Poor Condition TOT	AL CONDITION SCORES	9	25	11	3	48	48

5.0 Provisions for Handicap Accessibility

6.0 Functional Adaptability

7.0 Suitability of Space

YES			NO		
novi virtuali soni ili — i tradici di ili	GOOD	FAIR	POOR	UNSAT.	
EXCEL	GOOD	FAIR	POOR	UNSAT.	

Rich Bauscher Evaluator Name July 24, 2018 Date 1976

1976 Year Built 24,300 Total Sq. Ft.

42 Age of Facility

#### **High School Gymnasium**

Square footage of building:

24,300

Conversion on BCEF

100 - 48 = 52 %

Cost per/sf for upgrades\*

\$195

Mathematical calculation

 $24,300 \times 52 \% = 12,636 \text{ sf}$ 

Upgrade calculation cost

12,636 sf x 195\* sf = \$2,464,020

Total upgrade cost

\$2.5 million

Suitability of Space Problems include the following items:

- 1) Narrow hallways
- 2) Insufficient science labs
- 3) Insufficient band room
- 4) Choir/music room in building
- 5) Auditorium in building
- 6) Art room in building
- 7) Library size adequate
- 8) Kitchen in building
- 9) Central air in building
- 10) Core areas to small for an expansion

N/A	
N/A	
N/A	
N/A	
No	٦
No	
N/A	
No	
None	
Yes	٦

zed w/ 2	bad drs
	zed w/ 2

Comments

<sup>\* \$</sup> Provided by Beniton CM's

Wendell School District #232

High School (Vo-Ag Shop & FFA)

			RAT	INGS			
		GOOD	FAIR	POOR	UNSAT.		
COMPONENTS	SYSTEMS	(1)	(2)	(3)	(4)	COMM	ENTS
1.0 Exterior Building Condition	1.1 Foundation/Structure	+12	+8	+6	+4		
	1.2 Walls	+8	+5	+3	+1	Metal skin building	g
Good	1.3 Roof	+7	+5	+2	0	15 year old metal	roof
Component Score = 28	1.4 Windows/Doors	+2	+1	0	0	Db pane No ve	stibules
to the same second and the	1.5 Trim	+2	+1	0	0		
2.0 Interior Building Condition	2.1 Floors	+8	+5	+2	0	Some cracks in co	ement
The state of the s	2.2 Walls	+8	+5	+1	0		
Fair	2.3 Ceilings	+5	+3	+1	0	Need a drop ceilir	ng added
Component Score = 18	2.4 Fixed Equipment	+2	+1	0	0		
3.0 Mechanical Systems Condition	3.1 Electrical	+6	+4	+2	0		
	3.2 Plumbing	+4	+2	+1	0	Ť.	
Good	3.3 Heating	+6	+4	+2	+1		
Component Score = 26	3.4 Cooling	+6	+4	+2	+1	A/C	
	3.5 Lighting	+4	+3	+2	0	T8s are in place	
4.0 Safety/Building Code	4.1 Means of Exit	+6	+4	+2	0		
	4.2 Fire Control Capability	+4	+3	+2	+1	Not sprinkled	
Fair	4.3 Fire Alarm System	+4	+3	+2	+1	Simplex system is	s a problem
Component Score = 15	4.4 Emergency Lighting	+2	+1	0	0		
	4.5 Fire Resistance		+3	+2	+1	Wooden structure	)
						Unadjusted	Adjusted
						Score	Score
Fair Condition TOTA	AL CONDITION SCORES	66	20	0	1	87	87

5.0 Provisions for Handicap Accessibility

6.0 Functional Adaptability

7.0 Suitability of Space

	YES		NO		
	GOOD	FAIR	POOR	UNSAT.	
EXCEL	GOOD	FAIR	POOR	UNSAT.	

Rich Bauscher Evaluator Name July 24, 2018 Date 2003 Year Built 15 years Age of Facility

Total Sq. Ft.

4,392

#### High Sch Vo-Ag Shop & FFA

Square footage of building:

4,392

Conversion on BCEF

100 - 87 = **13%** 

Cost per/sf for upgrades\*

\$150

Mathematical calculation

 $4,392 \times 13 \% = 571 \text{ sf}$ 

Upgrade calculation cost

571 sf x \$150\* sf = **\$85,650** 

Total upgrade cost

\$86,000

Suitability of Space Problems include the following items:

- 1) Narrow hallways
- 2) Insufficient science labs
- 3) Insufficient band room
- 4) Choir/music room in building
- 5) Auditorium in building
- 6) Art room in building
- 7) Library size adequate
- 8) Kitchen in building
- 9) Central air in building
- 10) Core areas to small for an

expansion

N/A	
N/A	
No	
Yes	

Yes

Could be expanded

<sup>\* \$</sup> Provided by Beniton CM's

Wendell School District #232

High School Welding/Maint. Shop

			RAT	INGS			
		GOOD	FAIR	POOR	UNSAT.		
COMPONENTS	SYSTEMS	(1)	(2)	(3)	(4)	COM	MENTS
1.0 Exterior Building Condition	1.1 Foundation/Structure	+12	+8	+6	+4	Many cracks arou	nd building
	1.2 Walls	+8	+5	+3	+1	Cracks throughou	
Poor	1.3 Roof	+7	+5	+2	0	Tar built up - old	Ų.
Component Score = 12	1.4 Windows/Doors	+2	+1	0	0	Single pane	*
	1.5 Trim	+2	+1	0	0	Needs painted an	d tacked up
2.0 Interior Building Condition	2.1 Floors	+8	+5	+2	0	Cracks throughou	t floors
	2.2 Walls	+8	+5	. +1	0		
Poor	2.3 Ceilings	+5	+3	+1	0	Older	
Component Score = 9	2.4 Fixed Equipment	+2	+1	0	0	Older	
3.0 Mechanical Systems Condition	3.1 Electrical	+6	+4	+2	0	Panels are old	
	3.2 Plumbing	+4	+2	+1	0	Need new fixures	
Poor	3.3 Heating	+6	+4	+2	+1	Units are old	
Component Score = 12	3.4 Cooling	+6	+4	+2	+1	No A/C	
	3.5 Lighting	+4	+3	+2	0	Needs T8s	
4.0 Safety/Building Code	4.1 Means of Exit	+6	+4	+2	0	Some doors hard	to get out
	4.2 Fire Control Capability	+4	+3	+2	+1	No sprinkling syst	em
Poor	4.3 Fire Alarm System	+4	+3	+2	+1	None	
Component Score = 8	4.4 Emergency Lighting	+2	+1	0	0	None	
	4.5 Fire Resistance	+4	+3	+2	+1	Wooden structure	
				Γ		Unadjusted	Adjusted
						Score	Score
Poor Condition TOTAL CONDITION SCORES		0	19	19	3	41	41

6.0 Functional Adaptability

7.0 Suitability of Space

	YES		NO		
	GOOD	FAIR	POOR	UNSAT.	
EXCEL	GOOD	FAIR	POOR	UNSAT.	

Rich Bauscher Evaluator Name July 24, 2018 Date 1948 Year Built 7,000 Total Sq. Ft.

#### High Sch Welding/Maint. Shop

Square footage of building:

7,000

Conversion on BCEF

100 - 41 = 59%

Cost per/sf for upgrades\*

\$150

Mathematical calculation

 $7,000 \times 59 \% = 4,130 \text{ sf}$ 

Upgrade calculation cost

4,130 sf x 150 \* sf = \$619,500

Total upgrade cost

\$620,000

Suitability of Space Problems include the following items:

- 1) Narrow hallways
- 2) Insufficient science labs
- 3) Insufficient band room
- 4) Choir/music room in building
- 5) Auditorium in building
- 6) Art room in building
- 7) Library size adequate
- 8) Kitchen in building
- 9) Central air in building
- 10) Core areas to small for an expansion

Yes or No	
N/A	7
N/A	7
N/A	1
N/A	7
N/A	7
N/A	1
N/A	1
No	1

None

Yes

	Commic	11110	
	29		
Animity of 1	ے سالہ الیسیا	! X / . !	1
Majority of I	building	is a iviaint s	пор

Comments

<sup>\* \$</sup> Provided by Beniton CM's

# Wendell Schools' Districtwide BCEF Calculations

Below are the total calculations that combine these six school buildings & shop -- BCEF's. The total is then divided over two, five and ten years to help balance out the desired revenue with expenditures.

Sq Footage	Ratings	BCEF Scores	<b>Tota</b>	l Upgrade Costs
60,000	Good	97	\$	351,000
57,608	Good	92	\$	898,685
52,000	Fair	76	\$	2,433,600
24,300	Poor	48	\$	2,464,020
4,392	Fair	87	\$	85,650
7,000	Poor	41	\$	620,000
205,300	Fair	74	\$	6,852,955
,		\$6,852,955/10=	\$	685,296
		\$6,852,955/5 =	\$	1,370,591
		\$6,852,955/2 =	\$	3,426,478
	60,000 57,608 52,000 24,300 4,392 7,000	60,000 Good 57,608 Good 52,000 Fair 24,300 Poor 4,392 Fair 7,000 Poor	60,000       Good       97         57,608       Good       92         52,000       Fair       76         24,300       Poor       48         4,392       Fair       87         7,000       Poor       41         205,300       Fair       74         \$6,852,955/10 =       \$6,852,955/5 =	60,000       Good       97       \$         57,608       Good       92       \$         52,000       Fair       76       \$         24,300       Poor       48       \$         4,392       Fair       87       \$         7,000       Poor       41       \$         205,300       Fair       74       \$         \$6,852,955/10 =       \$         \$6,852,955/5 =       \$

# Conclusion and Analysis of Ten-Year Plan

Tim Perrigot, Superintendent

- In conclusion, the Wendell School District #232 details their strategies for proactively maintaining and upgrading their facilities as entailed in this ten-year facilities plan. Effective plans reflect the facilities vision and mission of the organization, including assessment of all of the facilities, incorporating the perspectives of the stakeholders and a focus on measures that ensure that the capitol investment is responsibly managed.
- The District's overall analysis is that this plan will contribute to both the instructional and financial well being of the Wendell School District along with their respective community.

###

The following signatures signify concurrence and approval of this Ten-Year Facilities Plan:

8/21/2018

Doyle Hope, School Board Chairperson

Date

8/21/2018

Troy Fletcher, Maintenance Director

Date

8/21/2018

Date